INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

STAR Case

Case Number: [redacted]

Release Date: 01/16/2016

Symptom/Vehicle Issue: CEL Warning Lamp On Intermittently, DTC P0013 - Bank 1 Camshaft 2 Position Actuator Circuit Open, P0010 - Bank 1 Camshaft 1 Position Actuator Circuit Open

Discussion: Check engine lamp on intermittently, stored codes P0013, P0010. Inspect the ground locations at the left strut tower Fig 1. Loosen, clean and secure to complete.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Center Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via ECCI or eCONTACT ticket if no solution is found