INFORMATION REDACTED PURSUANT TOTHE FREEDOM
OF INFORMATION ACT (FOIA), 5 U.S.C.552(B)(6)

Case Number	[redacted]
Vehicle Issue	Customers may experience difficulty locking or unlocking the doors when using the power door lock system or remote keyless entry transmitter.;When operating the power door locks with the door switches and/or RKE the actuator knob does not move or moves slow.
System or Component	Appearance / Condition Issues,Alignment / Poor Pattern / Gap / Fit Issues;Customer Concern (No DTCs);Power Door Locks;Interior;Enter / Exit Vehicle;Yes - Continuously
Recommendation	Please refer to Technical Service Bulletin 23-004-09. This TSB describes the procedure to enlarge the trim panel hole to correct this condition.
Modification Date	05/22/09 9:54 AM