
INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

RQ24-003 000158 RC


Search Criteria	
UserID	[redacted]
Report Date Time	2023-07-18 12:13:53
Total Result Count	57
Manufacturer	FORD MOTOR COMPANY
Model	E-350;E-350 BUS;E-450
Model Year	2021;2022
Load/Received Date From	2022-07-16
Load/Received Date To	2023-07-18

Responsive (to failure after passing inspection)	yes

Row Labels	Count of ODI/Source ID #
2022	7
Apr	1
May	1
Jun	1
Sep	2
Nov	1
Dec	1
2023	2
May	1
Jul	1
Grand Total	9



Count of ODI/Source ID # Row Labels	Column Labels ambiguous	[redacted]
2021		
Jul		
Nov		
Dec		
2022		
Mar		
Apr		
May		
Jun		
Jul		
Sep		
Nov		
Dec		
2023		
May		
Jul		
Grand Total		



S.No	Source	ODI/Source ID #	CMPL ID	Incident Date	Load/Received Date	Date Added to Source/ODI Letter Date	VIN	Manufacturer	Make	Model	Model Year	Significant Event	Fatality #	Injury #	Country	State/Province	City	Odometer	Occurences	Component	Responsive (to failure after passing inspection)
1	NHTSA	11530672	[redacted]	[redacted]	7/10/2023	7/6/2023	[redacted]	FORD MOTOR COMPANY	FORD	E-350	2021		0	0	UNITED STATES	FL	Daytona Beach	40000	0	SERVICE BRAKES, HYDRAULIC	yes
4	NHTSA	11521237	[redacted]	[redacted]	5/15/2023	5/9/2023	[redacted]	FORD MOTOR COMPANY	FORD	E-350	2022		0	0	UNITED STATES	UT	Saint George	12361	0	SERVICE BRAKES, HYDRAULIC	yes
15	NHTSA	11493799	[redacted]	[redacted]	11/21/2022	11/16/2022	[redacted]	FORD MOTOR COMPAN	FORD	E-350	2022		0	0	UNITED STATES	MD	EDGEWATER	0	0	STEERING:HYDRAULIC POWER ASSIST:POWER STEERING FLUID	ambiguous
17	TRANSPORT CANADA	20222325	[redacted]	[redacted]	11/14/2022	11/9/2022	[redacted]	FORD MOTOR COMPANY	FORD	E-450	2022		0	0	CANADA	Ontario	Timmins	16205	0	POWER ASSIST	yes
22	NHTSA	11485151	[redacted]	[redacted]	9/26/2022	9/19/2022	[redacted]	FORD MOTOR COMPAN	FORD	E-450	2021		0	0	UNITED STATES	WY	LARAMIE	0	0	STEERING:HYDRAULIC POWER ASSIST SYSTEM	ambiguous
23	NHTSA	11483429	[redacted]	[redacted]	9/12/2022	9/8/2022	[redacted]	FORD MOTOR COMPANY	FORD	E-350	2022		0	0	UNITED STATES	VA	Max Meadows	6300	0	SERVICE BRAKES, HYDRAULIC	yes
27	NHTSA	11487034	[redacted]	[redacted]	10/3/2022	9/29/2022	[redacted]	FORD MOTOR COMPANY	FORD	E-450	2021		0	0	UNITED STATES	FL	Molino	4826	0	STEERING	yes

42	NHTSA	11496999	[redacted]	12/19/2022	12/12/2022	[redacted]	FORD MOTOR COMPANY	FORD	E-450	2022		0	0	UNITED STATES	MI	Spring Lake	3200	0	STEERING	yes
45	NHTSA	11467764		3/27/2023	6/6/2022		FORD MOTOR COMPANY	FORD	E-450	2022		0	0	UNITED STATES	LA	Roseland	6300	0	SERVICE BRAKES	dupe, resent
48	NHTSA	11471820		7/10/2023	6/30/2022		FORD MOTOR COMPANY	FORD	E-350	2021		0	0	UNITED STATES	OH	Monroe	10800	0	SERVICE BRAKES, HYDRAULIC:POWER ASSIST	dupe, resent
50	NHTSA	11464223		7/10/2023	5/11/2022		FORD MOTOR COMPANY	FORD	E-450	2021		0	0	UNITED STATES	CA	Hemet	0	0	SERVICE BRAKES, HYDRAULIC:POWER ASSIST	dupe, resent
34	NHTSA	11445045		2/11/2022	12/27/2021		FORD MOTOR COMPAN	FORD	E-350	2022		0	0	UNITED STATES	NY	Buffalo	0	0	STEERING:HYDRAULIC POWER ASSIST:PUMP	before FSA
42	NHTSA	11424629		2/11/2022	7/13/2021		FORD MOTOR COMPANY	FORD	E-350	2021		0	0	UNITED STATES	AK	Wasilla	5000	0	STEERING:HYDRAULIC POWER ASSIST:POWER STEERING FLUID	before FSA
49	NHTSA	11456659		3/21/2022	3/14/2022		FORD MOTOR COMPANY	FORD	E-450	2021		0	0	UNITED STATES	IL	Antioch	3000	0	STEERING	before FSA
29	NHTSA	11457855		3/27/2022	3/22/2022		FORD MOTOR COMPAN	FORD	E-450	2022		0	0	UNITED STATES	CA	Manteca	0	0	STEERING	appointment availability

27	NHTSA	11459276	[redacted]	[redacted]	4/10/2022	4/1/2022	[redacted]	FORD MOTOR COMPANY	FORD	E-350	2021		0	0	UNITED STATES	NV	Las Vegas	22000	0	SERVICE BRAKES, HYDRAULIC	yes
24	NHTSA	11460930			4/18/2022	4/15/2022		FORD MOTOR COMPANY	FORD	E-450	2022		0	0	UNITED STATES	PA	Lewisberg	0	0	STEERING	part availability
31	NHTSA	11460679			4/18/2022	4/13/2022		FORD MOTOR COMPANY	FORD	E-450	2021		0	0	UNITED STATES	TX	Beaumont	8000	0	SERVICE BRAKES, HYDRAULIC	part availability, 22S08 still open
22	NHTSA	11464223			5/15/2022	5/11/2022		FORD MOTOR COMPANY	FORD	E-450	2021		0	0	UNITED STATES	CA	Hemet	0	0	SERVICE BRAKES	yes
12	NHTSA	11466381			6/5/2022	5/27/2022		FORD MOTOR COMPANY	FORD	E-450	2021		0	0	UNITED STATES	CO	Aurora	0	0	ENGINE	part availability
9	TRANSPORT CANADA	20221359			6/6/2022	6/6/2022		FORD MOTOR COMPANY	FORD	E-350	2021		0	0	CANADA			80369	0	BOOSTER	ambiguous
10	NHTSA	11467764			6/13/2022	6/6/2022		FORD MOTOR COMPANY	FORD	E-450	2022		0	0	UNITED STATES	LA	Roseland	6300	0	SERVICE BRAKES	inspection not performed prior to failure

7	NHTSA	11469453	[redacted]	6/20/2022	6/15/2022	[redacted]	FORD MOTOR COMPANY	FORD	E-350	2022		0	0	UNITED STATES	ID	Blanchard	11000	0	STEERING	ambiguous
15	NHTSA	11471820		7/4/2022	6/30/2022		FORD MOTOR COMPANY	FORD	E-350	2021		0	0	UNITED STATES	OH	Monroe	10800	0	SERVICE BRAKES, HYDRAULIC	yes
1	NHTSA	11472024		7/11/2022	7/1/2022		FORD MOTOR COMPANY	FORD	E-350	2021		0	0	UNITED STATES	FL	Tampa	13667	0	FUEL SYSTEM, DIESEL	ambiguous
37	TRANSPORT CANADA	20211503		11/24/2021	11/24/2021		FORD MOTOR COMPANY	FORD	E-350	2022		0	0	CANADA	Quebec	St-Mathieu de beloeil	5000	0	LINES AND FITTINGS	RV dealer complaint of 5 failures
60	TRANSPORT CANADA	20211267		11/24/2021	11/24/2021		FORD MOTOR COMPAN	FORD	E-350	2022		0	0	CANADA	Ontario	Cornwall	4500	0	GENERAL	before FSA

Consumer Comments	[redacted]
The contact owns a 2021 Ford E-350. The stated while driving into the driveway, the vehicle made an abnormal popping sound. The vehicle lost power steering functionality, and the brake pedal became spongy. Additionally, the contact stated that there was a trail of fluid in the driveway. The contact stated that upon opening the hood, he noticed that the brake line had fractured, and brake fluid was leaking inside the engine compartment. There was no further information provided. The manufacturer was notified of the failure and referred the contact to a dealer; however, the dealer could not accommodate the vehicle. The dealer was contacted and diagnosed the vehicle at the contact's residence. The dealer determined that unknown hoses needed to be replaced and the failure was related to NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The dealer and the manufacturer informed the contact that the vehicle could not be covered under the recall as the recall was previously marked as complete. The contact stated that the dealer had not completed the recall repair on the vehicle. The vehicle was not repaired. The failure mileage was approximately 40,000.	
The contact owns a 2022 Ford E-350. The contact stated while driving 60 MPH and depressing the brake pedal, the vehicle failed to stop as needed. There was no warning light illuminated. The contact desperately depressed on the brake pedal and the vehicle eventually came to a complete stop. The vehicle was towed to the dealer and the mechanic stated that the power steering pump needed to be replaced, and that the vehicle was previously repaired under NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The vehicle was repaired. The manufacturer was contacted but no assistance was provided. The failure mileage was 12,361.	
2022 FORD E-350. CONSUMER WRITES IN REGARD TO POWER STEERING SAFETY RECALL.	
Motorhome purchased as a demo in May 2022 with 2000 kms which dealership said were accumulated driving to RV shows, complainant later found out that the motorhome had been previously owned for eight months. \r\nIncident occurred on Oct. 23rd while driving at 80,90 kph on a two lane highway, complainant noticed that the steering was becoming stiff and that he had lost brake assist. He was familiar with the highway and so continued at 20,30 kph until he reached a rest stop where he was able to pull off and stop without incident. Vehicle was repaired at a dealership, complainant did not receive notification of recall 2022,073 and said he was told by the dealer that the repair had not been previously completed.\r\nHe will send a copy of the repair invoice if available.\r\n\r\nUpdate: \r\n\r\nThe repairs were completed on the 24th.\r\nMy motor home broke down on highway 144 at highway 560.\r\n\r\nI tired to get the motor home towed somewhere but I could not find a tow company who would touch it. \r\nThere is a fully licenced garage at that location called WATERSHED 144 LTD. One of their mechanics looked at the motor home and determined what was broken.\r\nI drove to the Ford dealership in Timmins to get the parts, returned to the WATERSHED garage and they completed the work.	
2021 FORD E-450. CONSUMER WRITES IN REGARD TO SAFETY RECALL NOTICE 22S08. THE CONSUMER REQUESTED ASSISTANCE LOCATING A DEALER WITHIN A REASONABLE DISTANCE TO PERFORM THE RECALL REPAIR.	
The contact owns a 2022 Ford E-350. The contact stated that while driving approximately 65 MPH, the steering wheel became stiff and the vehicle would pull in either direction. Additionally, and there was an abnormal odor inside the cabin of the vehicle. The contact then noticed that the brake pedal had to be pressed very hard in order to stop the vehicle. After stopping to inspect under the hood, the contact discovered a power steering fluid leak in the engine compartment. The vehicle was driven to the local dealer who diagnosed that the power steering pressure line had detached. The vehicle was not yet repaired. The manufacturer was not yet notified of the failure. The contact indicated that the vehicle was previously repaired under the NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The failure mileage was 6,300.	
The contact owns a 2021 Ford E-450. The contact received notification of NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The contact stated that the vehicle was taken to the dealer where the vehicle was inspected however, while making a turn into a service station, the steering wheel became difficult to maneuver. No warning lights were illuminated. The contact then stated that she was directed to a leak coming from the vehicle. The contact notified the dealer, and the vehicle was towed to an independent mechanic where it was diagnosed that the hydro-boost power failed and needed to be replaced. The vehicle was repaired. The manufacturer was notified of the failure and covered the cost of the tow, but no further assistance was provided. The failure mileage was 4,826.	

The contact owns a 2022 Ford E-450. The contact stated that while driving at an undisclosed speed, the steering wheel became difficult to maneuver. The contact then stated that he had to apply pressure to the brake pedal to stop the vehicle. No warning light was illuminated. The contact was able to maneuver the vehicle off the roadway. The independent mechanic was notified and went out to diagnose the vehicle. The contact was informed that the steering hose failed and needed to be replaced. The vehicle was repaired. Additionally, the contact stated that he received Manufacturer recall notification: 22S08 (Hydroboost or Hydromax Power Steering Pressure Line Inspection) however, the vehicle was inspected, and the contact was informed that the hose did not need to be replaced. The manufacturer was notified of the failure and the contact was provided a case number, but no additional assistance was provided. The failure mileage was approximately 3,200.	[redacted]
The contact owns a 2022 Forest River Forester built on a 2022 Ford E-450 chassis. The contact stated while driving 30 MPH downhill, he was depressing the brake pedal however, the RV failed to stop as needed. The contact stated that he was towing a 2000 Jeep Wrangler during the failure and the brakes on the vehicle were also applied and caused the motorhome to stop. The contact stated no warning light was illuminated. The contact stated that the brakes and steering were inoperable. The motorhome was not drivable. The contact called the local dealer and made them aware of the failure but was informed they were unable to service a trailer that size. The dealer referred the contact to another repair shop. The motorhome was towed to repair shop and was informed the power steering hose needed to be replaced. The vehicle was not repaired. The VIN was included in NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The manufacturer had been informed of the failure. The failure mileage was approximately 6,300. The contact stated that the vehicle was repaired and Ford paid for all of the expenses.	
The contact owns a 2021 Ford E-350. The contact stated that the vehicle was included in NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic) and the vehicle was inspected. During the inspection, there were no leaks found. The contact stated while driving approximately 65 MPH after the inspection, the vehicle lost power steering functionality. The contact coasted the vehicle off the highway. The contact stated that while driving afterward and attempting to depress the brake pedal, the vehicle failed to respond as designed. The contact pulled over and had the vehicle towed to the dealer where the recall repair was completed. The manufacturer was made aware of the failure. The approximate failure mileage was 10,800.	
Regarding the recall #22S08 Hydroboost or Hydromax power steering pressure line. We took our Motorhome in to have the recall addressed and for service before a planned camping trip. Apparantly the recall was worded to inspect OR replace and our vehicle was only inspected. On our ruined Mother's Day vacation, we were driving highway speeds at a downgrade coming into Nevada and lost all power steering which took our motorhome and trailer we were pulling off of the highway and dangerously close to falling off the highway and tumbling down a hill. We went to exit at the next offramp to look at the power steering issue and found that we also had no brakes. By downshifting, we were able to stop safely. There were no warning lights or signals, and no warning signs what so ever. The motorhome is currently being looked at and hopefully repaired at a Rush Truck Center in Las Vegas. Ford Motor Company and the original dealership have been notified. Our main concern is the word OR in the recall verbiage, which we blame Ford Motor Co. The problem is clearly this part must be replaced, not just inspected. A change in the verbiage literally will save lives. We really should have been dead on the side of the road, but we were lucky and are contemplating hiring a lawyer, as we feel that the unacceptable recall wording by Ford unneccessarily put our lives at risk. Our Ford Claim number is: [redacted]	
Without warning my brakes and steering failed on a Freedom Elite RV on a Ford Motor chassis. The vehicle only had 2396 miles on it at the time of occurrence. It turned out to be a pressure hose that broke. Luckily I was in a residential neighborhood with no traffic and driving very slowly when it happened. I shudder to think what would have happened on a hill or in traffic.	
The contact owns a 2021 Ford E-350. The contact stated while driving 60 mph, the contact started to smell a burning odor coming from the RV. The contact attempted to pull over the RV to the side of the roadway however, the RV became difficult to steer. The contact pulled over the RV and checked underneath the RV and the front hood and noticed that power steering fluid had leaked all over the engine. The contact continued driving to his destination and then had the RV towed to an RV lot. The RV was not diagnosed nor repaired. The manufacturer was made aware of the failure. The failure mileage was approximate 5,000.	
The contact owns a 2021 Ford E-450. The contact received notification of NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The contact stated that while driving at an undisclosed speed, several unknown warning lights illuminated. The vehicle then experienced a loss of power steering assist. The dealer was made aware of the failure but informed the contact that they were not equipped to perform recall repairs on RVs. The manufacturer was made aware of the failure and informed the contact that the nearest dealer able to perform the recall repair was more than 100 miles away. The vehicle was not repaired. The failure mileage was approximately 3,000.	
I received a recall notice on this vehicle from Ford. Ford Recall 22S08 and NHTSA recall 22V089. Ford does not seem to be aware of this recall nor do you. The earliest Big Valley Ford in Stockton CA appointment I could get was 7/19/22. This is not acceptable based on safety	

The contact owns a 2021 Ford E-350. The contact's wife was driving into a parking lot at approximately 5 MPH when the power steering and the brakes failed. The contact's wife was able to safely stop the vehicle. The contact stated that his wife had not observed any warning lights being illuminated. The contact's wife examined the vehicle and noticed that there was red fluid puddling on the ground and a hissing sound coming from the driver's side under the engine. The vehicle had not been towed to a dealer and had not been diagnosed or repaired. The contact researched online and related the failure to NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The manufacturer had not been informed of the failure. The failure mileage was approximately 22,000. Consumer purchased the unit in Las Vegas on March 13th with 21,477 miles on the odometer and it failed on April 1st, with 22,018 miles on the odometer.	[redacted]
The contact owns a 2022 Ford E-450. The contact received notification of NHTSA Campaign Number: 22V089000 (STEERING, SERVICE BRAKES, HYDRAULIC) however, the part to do the recall repair was not yet available. The dealer was made aware of the issue. The contact stated that the manufacturer had exceeded a reasonable amount of time for the recall repair. The contact had not experienced a failure.	
The contact owns a 2021 Ford E-450. The contact received notification of NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic) however, the part to do the recall repair was not yet available. The contact stated that the manufacturer had exceeded a reasonable amount of time for the recall repair. The manufacturer was made aware of the issue. The contact had not experienced a failure. Parts distribution disconnect.	
Regarding the recall #22S08 Hydroboost or Hydromax power steering pressure line. We took our Motorhome in to have the recall addressed and for service before a planned camping trip. Apparantly the recall was worded to inspect OR replace and our vehicle was only inspected. On our ruined Mother's Day vacation, we were driving highway speeds at a downgrade coming into Nevada and lost all power steering which took our motorhome and trailer we were pulling off of the highway and dangerously close to falling off the highway and tumbling down a hill. We went to exit at the next offramp to look at the power steering issue and found that we also had no brakes. By downshifting, we were able to stop safely. There were no warning lights or signals, and no warning signs what so ever. The motorhome is currently being looked at and hopefully repaired at a Rush Truck Center in Las Vegas. Ford Motor Company and the original dealership have been notified. Our main concern is the word OR in the recall verbiage, which we blame Ford Motor Co. The problem is clearly this part must be replaced, not just inspected. A change in the verbiage literally will save lives. We really should have been dead on the side of the road, but we were lucky and are contemplating hiring a lawyer, as we feel that the unacceptable recall wording by Ford unneccessarily put our lives at risk. Our Ford Claim number is [redacted]	
The contact owns a 2021 Ford E-450. The contact received notification of NHTSA Campaign Numbers: 20V795000 (Engine) and 22V089000 (Steering, Service Brakes, Hydraulics) however, the parts to do the recall repairs were not yet available. The dealer was made aware of the issue. The contact stated that the manufacturer had exceeded a reasonable amount of time for the recall repair. The contact had not experienced a failure. VIN tool confirms parts not available and Parts distribution disconnect respectively.	
Note: last digit of VIN (5) removed to prevent tripping duplicate warning from file 2021,1266\r\n\r\nFrom email:\r\n•\tCrew identified a fairly sudden loss of power to both the steering and braking systems while driving at town speeds, they immediately pulled over and a tow truck was sent for retrieval..\r\n\r\n\r\nRecall 2022,073, Issue:\r\nOn certain vehicles, the power steering pressure line may not be properly connected to the brake booster. As a result, power steering fluid could leak and cause a loss of power steering and power brake assist.\r\nNote: This recall only affects certain E,series incomplete vehicles equipped with dual rear wheels.\r\n\r\nSafety Risk:\r\nA loss of power brakes can cause a potentially sudden increase in brake pedal force and lead to an increase in stopping distance. A loss of power steering assist can cause a sudden increase in steering effort, especially at low speeds. Both could increase the risk of a crash.\r\n\r\nCorrective Actions:\r\nFord will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the connection between the power steering pressure line and the Hydroboost unit. The power steering line will be replaced if the connection is not secure.\r\nMake\tModel\tModel Year(s) Affected\r\nFORD\tE350\t2021 2022\r\nFORD\tE450\t2021 2022	
The contact owns a 2022 Forest River Forester built on a 2022 Ford E-450 chassis. The contact stated while driving 30 MPH downhill, he was depressing the brake pedal however, the RV failed to stop as needed. The contact stated that he was towing a 2000 Jeep Wrangler during the failure and the brakes on the vehicle were also applied and caused the motorhome to stop. The contact stated no warning light was illuminated. The contact stated that the brakes and steering were inoperable. The motorhome was not drivable. The contact called the local dealer and made them aware of the failure but was informed they were unable to service a trailer that size. The dealer referred the contact to another repair shop. The motorhome was towed to repair shop and was informed the power steering hose needed to be replaced. The vehicle was not repaired. The VIN was included in NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic). The manufacturer had been informed of the failure. The failure mileage was approximately 6,300.	

The contact owns a 2022 Ford E-350. The contact stated while driving 35 MPH uphill, the vehicle lost power steering functionality. The contact downshifted manually to slow the vehicle however while depressing the brake pedal, the vehicle failed to stop in a reasonable time. The contact stopped the vehicle while using the parking brake. The contact pulled over and had the vehicle towed to the dealer to be diagnosed. The contact was informed that the power steering unit needed to be replaced. The vehicle was not repaired. The manufacturer was not notified of the failure. The failure mileage was 11,000. The VIN was unavailable.	[redacted]
The contact owns a 2021 Ford E-350. The contact stated that the vehicle was included in NHTSA Campaign Number: 22V089000 (Steering, Service Brakes, Hydraulic) and the vehicle was inspected. During the inspection there was no leaks found. The contact stated while driving approximately 65 MPH after the inspection, the vehicle lost power steering functionality. The contact coasted the vehicle off the highway. The contact stated that while driving afterwards and attempting to depress the brake pedal, the vehicle failed to respond as designed. The contact pulled over and had the vehicle towed to the dealer where the recall repair was completed. The manufacturer was made aware of the failure. The approximate failure mileage was 10,800.	
The contact owns a 2021 Ford E-350. The contact stated that while driving at undisclosed speeds, the power steering and brakes became inoperable. There were no warning lights illuminated. The vehicle was towed to the local dealer where it was diagnosed with loosened brake line fittings and an unknown fluid leak. The vehicle was repaired. The contact stated the failure was related to NHTSA Campaign Number: 22V013000 (Fuel System, Diesel). The manufacturer was contacted but no additional assistance was provided. The failure mileage was approximately 13,667.	
In this file, the complainant works at a RV dealership as an operation's director and reported that they have experienced five separate hydraulic hose failures that causes a loss of braking and steering on 2022 E,350 and E,450 chassis motorhomes. In total they bought upwards of 20 units from various manufacturer (thor, forest river and winnebago) and since the five failed hose they are weary of selling the other units. All failures occurred below 5000 km. The complainant will follow by emails with details of all separate failures including VIN and a brief description of what happened. rnrnChassi Ford E,450 RV motor Home Hydro,boost steering and brakes hose fails.	
The hydraulic line from the pump detached causing a loss of power steering assist and brake assist. See the primary complain[redacted]	

RQ24-003 000169 RC

From: [redacted]
Sent: Thursday, February 1, 2024 4:46 PM
To: [redacted]
Cc: [redacted]
Subject: FW: Hydroboost VOQs
Attachments: 2021-22 MY E-Series Hydroboost VOQ update, [redacted].xlsx

Laura,

This is probably the better summary. Everything from the previous e-mail I sent was already included in [redacted] July summary, attached.

Best Regards,
Travis Henney
Automotive Safety Office-Senior Safety Engineer
thenney@ford.com
[redacted]

From: Page, Kimberly (K.A.) <kpage15@ford.com>
Sent: Friday, July 21, 2023 3:37 PM
To: Beyer, Laura (L.D.) <lbeyer4@ford.com>
Cc: Henney, Travis (J.) <thenney@ford.com>
Subject: RE: Hydroboost VOQs

Hi Laura,

Attached is the VOQ update. There are 8 new reports since your last update – 6 that had an incident after the inspection, and 2 ambiguous (incomplete VINs and not clearly stated). I added some comments about when the inspection occurred, incident dates, etc. Please let me know if you have any questions.

Kim Page
Concern Analyst, Automotive Safety Office

From: Beyer, Laura (L.D.) <lbeyer4@ford.com>
Sent: Monday, July 17, 2023 9:08 PM
To: Page, Kimberly (K.A.) <kpage15@ford.com>
Subject: Hydroboost VOQs

Hi Kim,
Thank you for pulling VOQs for the E-Series Hydroboost concern. I have attached the last file I have – from about a year ago.

Thank you again.

Laura Beyer
Manager, Safety Investigations|Truck CCRG Chair
Automotive Safety Office
Ford Motor Company
[redacted])
Vehicle Safety and Emissions Compliance & Investigations Process (OLC1203177)


RQ24-003 000170 RC

RQ24-003 000171 RC

Search Criteria	
UserID	[redacted]
Report Date Time	2023-07-18 12:13:53
Total Result Count	57
Manufacturer	FORD MOTOR COMPANY
Model	E-350;E-350 BUS;E-450
Model Year	2021;2022
Load/Received Date From	2022-07-16
Load/Received Date To	2023-07-18

Responsive (to failure after passing inspection)	yes


Row Labels	Count of ODI/Source ID #
<7/7/2021	
2021	
2022	**7**
<7/7/2021	
Jan	
Feb	
Mar	
Apr	1
May	1
Jun	1
Jul	
Aug	
Sep	2
Oct	
Nov	1
Dec	1
>7/7/2023	
2023	**2**
<7/7/2021	
Jan	
Feb	
Mar	
Apr	
May	1
Jun	
Jul	1
Aug	
Sep	
Oct	
Nov	
Dec	
>7/7/2023	
>7/7/2023	
Grand Total	**9**



Count of ODI/Source ID # Row Labels	Column Labels yes	Grand Total
2022	**7**	**7**
Apr	1	1
May	1	1
Jun	1	1
Sep	2	2
Nov	1	1
Dec	1	1
2023	**2**	**2**
May	1	1
Jul	1	1
Grand Total	**9**	**9**

prior to FSA
prior to FSA
prior to FSA
FSA 22S08 published 2/17/2022

8 new VOQ's since July 2022 update - 6 failures after passing inspection, 2 ambiguous




S.No	Source	ODI/Source ID #	CMPL ID	Incident Date	Load/Received Date	Date Added to Source/ODI Letter Date	VIN	Manufacturer	Make	Model	Model Year	Significant Event	Fatality #	Injury #	Country	State/Province	City	Odometer	Occurences	Component	Responsive (to failure after passing inspection)	Consumer Comments	[redacted]
1	NHTSA	11530672	[redacted]	[redacted]	7/10/2023	7/6/2023	[redacted]	FORD MOTOR COMPAN	FORD	E-350	2021		0	0	UNITED STATES	FL	Daytona Beach	40000	0	SERVICE BRAKES, HYDRAULIC	yes	The contact owns a 2021 Ford E-350. The stated while driving into the driveway, the vehicle mad an abnormal pooping sound. The vehicle lost	
4	NHTSA	11521237			5/15/2023	5/9/2023		FORD MOTOR COMPAN	FORD	E-350	2022		0	0	UNITED STATES	UT	Saint George	12361	0	SERVICE BRAKES, HYDRAULIC	yes	The contact owns a 2022 Ford E-350. The contac stated while driving 60 MPH and depressing the brake pedal, the vehicle failed to stop as needed	
17	TRANSPORT CANADA	20222325			11/14/2022	11/9/2022		FORD MOTOR COMPAN	FORD	E-450	2022		0	0	CANADA	Ontario	Timmins	16205	0	POWER ASSIST	yes	Motorhome purchased as a demo in May 2022 with 2000 kms which dealership said were accumulated driving to RV shows, complained	
23	NHTSA	11483429			9/12/2022	9/8/2022		FORD MOTOR COMPAN	FORD	E-350	2022		0	0	UNITED STATES	VA	Max Meadows	6300	0	SERVICE BRAKES, HYDRAULIC	yes	The contact owns a 2022 Ford E-350. The contac stated that while driving approximately 65 MPH, the steering wheel became stiff and the vehicle	
27	NHTSA	11487034			10/3/2022	9/29/2022		FORD MOTOR COMPAN	FORD	E-450	2021		0	0	UNITED STATES	FL	Molino	4826	0	STEERING	yes	The contact owns a 2021 Ford E-450. The contact received notification of NHTSA Campaign Number 22V089000 (Steering, Service Brake, Hydraulic)	
42	NHTSA	11496999			12/19/2022	12/12/2022		FORD MOTOR COMPAN	FORD	E-450	2022		0	0	UNITED STATES	MI	Spring Lake	3200	0	STEERING	yes	The contact owns a 2022 Ford E-450. The contact stated that while driving at an undisclosed speed, the steering wheel became difficult to maneuver	
27	NHTSA	11459276			4/10/2022	4/1/2022		FORD MOTOR COMPAN	FORD	E-350	2021		0	0	UNITED STATES	NV	Las Vegas	22000	0	SERVICE BRAKES, HYDRAULIC	yes	The contact owns a 2021 Ford E-350. The contact' wife was driving into a parking lot at approximatel 5 MPH when the power steering and the brakes	
22	NHTSA	11464223			5/15/2022	5/11/2022		FORD MOTOR COMPAN	FORD	E-450	2021		0	0	UNITED STATES	CA	Hemet	0	0	SERVICE BRAKES	yes	Regarding the recall #22S08 Hydroboost or Hydromax power steering pressure line. We took our Motorhome in to have the recall addressed	
15	NHTSA	11471820			7/4/2022	6/30/2022		FORD MOTOR COMPAN	FORD	E-350	2021		0	0	UNITED STATES	OH	Monroe	10800	0	SERVICE BRAKES, HYDRAULIC	yes	The contact owns a 2021 Ford E-350. The contact stated that the vehicle was included in NHTSA Campaign Number: 22V089000 (Steering, Service	

C

Row Labels	Sum of ODI/Source ID #
2022	[redacted]
2023	
Grand Total	

RQ24-003 000176 RC



RQ24-003 000177 RC

-----Original Appointment-----
From: Demski, Jacob (J.K.)
Sent: Friday, August 18, 2023 9:32 AM
To: Demski, Jacob (J.K.); Avila Magana, Luis Ricardo (LA.); Stanley, Daniel (D.J.)
Cc: Page, Kimberly (K.A.); Puleri, Michael (M.J.); Donovan, Kevin (K.M.); Frey, Martin (M.F.); Malik, Nadeem (N.); Runnion, John (J.L.); Isaacson, James (J.W.)
Subject: CCRG Prep Meeting, Hydroboost Line Leaks
When: Tuesday, August 22, 2023 11:30 AM-12:00 PM (UTC-05:00) Eastern Time (US & Canada).
Where:

Good Morning Team,

The purpose of this meeting is to align before the next Critical Concern Review Group on Thursday, August 24th. This is in regards to Hydroboost line leaks post FSA 22S08.

Thank You,

Jacob Demski
Safety Investigations Engineer
E&SC FCG

-~-~-~

RQ24-003 000178 RC

NOTICE: ***Protecting and Properly Using Company Assets: We are careful not to disclose Ford information, even accidentally. If we share non-public information outside of Ford, we follow applicable procedures and obtain proper approvals and ensure appropriate confidentiality agreements are in place. · We follow Ford's information and records retention protocols and programs. · We do not destroy information if there is a legal requirement to maintain it, such as a suspension order or other litigation hold.***

For company policies on recording
For additional help joining Webex
Can't join the meeting? Ford users



T32MC04

Search Criteria	
UserID	[redacted]
Report Date Time	2023-12-11 10:56:39
Total Result Count	132
Source	NHTSA;TRANSPORT CANADA
Manufacturer	FORD MOTOR COMPANY
Make	FORD
Model	E-350;E-350 BUS;E-450
Model Year	2021;2022

S.No	Source	ODI/Source ID #	CMPL ID	Incident Date	Load/Received Date	Date Added to Source	VIN	Manufacturer	Make	Model	Model Year	Significant Event	Fatality #	Injury #	Country	State/Province	City	Odometer	Occurences	Component	Consumer Comments	[redacted]
2	NHTSA	11535359	[redacted]	[redacted]	12/11/2023	12-06-2023	[redacted]	FORD MOTOR COMP	FORD	E-450	2022		0	0	UNITED STAT	MI	Jackson	0	0	STEERING	I am a mechanic at Huron Valley Ambulance. Ford h	[redacted]
80	NHTSA		[redacted]	[redacted]	7/10/2023	05-11-2022	[redacted]	FORD MOTOR COMP	FORD	E-450	2021		0	0	UNITED STAT	CA	Hemet	0	0	SERVICE BRAKES,	Regarding the recall #22S08 Hydroboost or Hydrom	[redacted]
10	NHTSA	11509828	[redacted]	[redacted]	7/10/2023	07-06-2023	[redacted]	FORD MOTOR COMP	FORD	E-350	2021		0	0	UNITED STAT	FL	Daytona Beach	40000	0	STEERING	The contact owns a 2021 Ford E-350. The stated wh	[redacted]
37	NHTSA	11508139	[redacted]	[redacted]	7/10/2023	09-29-2022	[redacted]	FORD MOTOR COMP	FORD	E-450	2021		0	0	UNITED STAT	FL	Molino	4826	0	SERVICE BRAKES,	The contact owns a 2021 Ford E-450. The contact re	[redacted]
56	NHTSA		[redacted]	[redacted]	7/10/2023	12-12-2022	[redacted]	FORD MOTOR COMP	FORD	E-450	2022		0	0	UNITED STAT	MI	Spring Lake	3200	0	SERVICE BRAKES,	The contact owns a 2022 Ford E-450. The contact st	[redacted]
12	NHTSA	20222325	[redacted]	[redacted]	5/15/2023	05-09-2023	[redacted]	FORD MOTOR COMP	FORD	E-350	2022		0	0	UNITED STAT	UT	Saint George	12361	0	STEERING	The contact owns a 2022 Ford E-350. The contact st	[redacted]
31	NHTSA	11459276	[redacted]	[redacted]	9/12/2022	09-08-2022	[redacted]	FORD MOTOR COMP	FORD	E-350	2022		0	0	UNITED STAT	VA	Max Meadows	6300	0	STEERING	The contact owns a 2022 Ford E-350. The contact st	[redacted]
70	NHTSA		[redacted]	[redacted]	7/4/2022	06-30-2022	[redacted]	FORD MOTOR COMP	FORD	E-350	2021		0	0	UNITED STAT	OH	Monroe	10800	0	STEERING	The contact owns a 2021 Ford E-350. The contact st	[redacted]
ADDED	NHTSA	11564944	[redacted]	[redacted]	01-15-2024	01-11-2024	[redacted]	FORD MOTOR COMP	FORD	E-450	2022		0	0	UNITED STAT	IL	Northbrook	4000	0	SERVICE BRAKES,	The contact owns a 2022 Ford E-450. The contact h	[redacted]

Vehicle speed unit	Incident Reported To Police	Medical Attention Required	Fuel Type	Defective Tire Repaired	Vehicles Towed	Complete VIN?	Does Vin Exist Twice?	Customer Alleges:	Duplicate of	Comment Me	[redacted]	Responsive?	[redacted]
	0	0			0	No	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original	Yes		A	
	0	0			0	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original	Yes		A	
	0	0			0	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original	Yes		A	
	0	0			1	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original			A	
	0	0			0	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original			A	
	0	0			1	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original			A	
	0	0			0	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original			A	
	0	0			0	Yes	Multiple Exist	Hydroboost Leak/Disconnect POST INSPECTION	Original			A	
	0	0			1				Original			A	

[redacted]

S.No	Source	ODI/Sour	CMPL_ID	Incident I	Load/Rec	Date Add	VIN	Manufac	Make	Model	Model Ye	Significa	Fatality #	Injury #	Country	State/Pro	City	Odomete	Occurren	Compone	Consumer	Vehicle S	Vehicle s	Incident	Medical A	Fuel Typ	Defective	Vehicles	Respons
80	NHTSA		[redacted]		7/10/2023	05-11-202	[redacted]	FORD MOT	FORD	E-450	2021		0	0	UNITED ST	CA	Hemet	0	0	SERVICE BI	Regarding	60		0	0			0	A
12	NHTSA	20222325			5/15/2023	05-09-202		FORD MOT	FORD	E-350	2022		0	0	UNITED ST	UT	Saint Geor	12361	0	STEERING	The contac	60		0	0			1	A
31	NHTSA	11459276			9/12/2022	09-08-202		FORD MOT	FORD	E-350	2022		0	0	UNITED ST	VA	Max Mead	6300	0	STEERING	The contac	65		0	0			0	A
70	NHTSA				7/4/2022	06-30-202		FORD MOT	FORD	E-350	2021		0	0	UNITED ST	OH	Monroe	10800	0	STEERING	The contac	65		0	0			0	A
ADDED	NHTSA	11564944			01-15-2024	01-11-202		FORD MOT	FORD	E-450	2022		0	0	UNITED ST	IL	Northbroo	4000	0	SERVICE BI	The contac	0		0	0			1	A

[redacted]

C

egory?

RQ24-003 000184 RC

[redacted]

C


[redacted]

C

Row Labels	Count of VIN
0	2
1	1
2	2
4	1
10	1
11	1
14	1
15	1
Grand Total	**10**

VOQ Alleges (NHTSA) GSAR Responsive?	Failure Post Inspection (Multiple Items) A

Row Labels	Count of VIN
17	1
59	1
84	1
139	1
344	1
Grand Total	**5**




[redacted]

C

Incident Date Before or Aft[redacted]	After
VOQ Alleges (NHTSA)	(Multiple Items)

Row Labels	Count of VIN
2022	8
(blank)	
Jan	
Feb	
Mar	
Apr	1
May	
Jun	2
Jul	1
Aug	
Sep	2
Oct	
Nov	2
Dec	
>12/12/2023	
2023	9
(blank)	
Jan	
Feb	
Mar	1
Apr	
May	1
Jun	
Jul	5
Aug	1
Sep	
Oct	
Nov	
Dec	1
>12/12/2023	
Grand Total	17



[redacted]

C

Incident Date Before or[redacted]	After
VOQ Alleges (NHTSA)	Failure Post Inspection


Row Labels	Count of VIN
2022	
(blank)	
Jan	
Feb	
Mar	
Apr	
May	
Jun	
Jul	1
Aug	
Sep	1
Oct	
Nov	
Dec	
>12/12/2023	
2023	
(blank)	
Jan	
Feb	
Mar	
Apr	
May	1
Jun	
Jul	4
Aug	
Sep	
Oct	
Nov	
Dec	1
>12/12/2023	
Grand Total	8

[redacted]

C

Customer Alleges:	(Multiple Items)


Row Labels	Count of Customer Alleges:
2021	
Jan	
Feb	
Mar	
Apr	
May	
Jun	
Jul	
Aug	
Sep	
Oct	
Nov	3
Dec	
2022	
Jan	
Feb	3
Mar	1
Apr	1
May	
Jun	2
Jul	1
Aug	
Sep	2
Oct	
Nov	2
Dec	
2023	
Jan	
Feb	
Mar	1
Apr	
May	1
Jun	1
Jul	5
Aug	1
Sep	
Oct	
Nov	
Dec	1
Grand Total	25




Customer Alleges:	Hydroboost Leak/Disconne
Row Labels	Count of Customer Alleges:
2021	
Jan	
Feb	
Mar	
Apr	
May	
Jun	
Jul	
Aug	
Sep	
Oct	
Nov	
Dec	
2022	
Jan	
Feb	
Mar	
Apr	1
May	
Jun	
Jul	1
Aug	
Sep	1
Oct	
Nov	1
Dec	
2023	
Jan	
Feb	
Mar	
Apr	
May	1
Jun	
Jul	4
Aug	
Sep	
Oct	
Nov	
Dec	1
Grand Total	10

[redacted]

Row Labels	Count of VIN
<11/24/2021	
2021	10
Qtr1	
Qtr2	
Qtr3	
Qtr4	10
2022	78
Qtr1	25
Qtr2	25
Qtr3	15
Qtr4	13
2023	44
Qtr1	11
Qtr2	12
Qtr3	18
Qtr4	3
>12/12/2023	
Grand Total	132



Count of VIN
133



RQ24-003 000189 RC

S.No	Source	ODI/Sour	CMPL_ID	Incident	Load/Re	Date Add	VIN	Manufact	Make	Model	Model Ye	Significa	Fatality #	Injury #	Country	State/Pro	City	Odometer	Occurren	Componv	Consum	Vehicle S	Vehicle s	Incident	Medical A	Fuel Typ	Defective	Vehicles	Respon	[redacted]
99	NHTSA	11459276	[redacted]		########	04-01-202	[redacted]	FORD MOT	FORD	E-350	2021		0	0	UNITED ST	NV	Las Vegas	22000	0	SERVICE BI	The contac	5		0	0	GS		0	Yes	
28	NHTSA	11483429			########	09-08-202		FORD MOT	FORD	E-350	2022		0	0	UNITED ST	VA	Max Mead	6300	0	SERVICE BI	The contac	65		0	0			0	Yes	
32	NHTSA	11487034			########	09-29-202		FORD MOT	FORD	E-450	2021		0	0	UNITED ST	FL	Molino	4826	0	STEERING	The contac	0		0	0			1	Yes	
22	TRANSPOR	20222325			########	11-09-202		FORD MOT	FORD	E-450	2022		0	0	CANADA	Ontario	Timmins	16205	0	POWER AS	Motorhom	0	KPH						Yes	
47	NHTSA	11496999			########	12-12-202		FORD MOT	FORD	E-450	2022		0	0	UNITED ST	MI	Spring Lak	3200	0	STEERING	The contac	0		0	0			0	Yes	
9	NHTSA	11521237			########	05-09-202		FORD MOT	FORD	E-350	2022		0	0	UNITED ST	UT	Saint Geor	12361	0	SERVICE BI	The contac	60		0	0			1	Yes	
55	NHTSA	11464223			########	05-11-202		FORD MOT	FORD	E-450	2021		0	0	UNITED ST	CA	Hemet	0	0	SERVICE BI	Regarding	60		0	0			0	Yes	
53	NHTSA	11471820			########	06-30-202		FORD MOT	FORD	E-350	2021		0	0	UNITED ST	OH	Monroe	10800	0	SERVICE BI	The contac	65		0	0			0	Yes	
6	NHTSA	11530672			########	07-06-202		FORD MOT	FORD	E-350	2021		0	0	UNITED ST	FL	Daytona B	40000	0	SERVICE BI	The contac	0		0	0			0	Yes	
5	NHTSA	11533403			########	07-20-202		FORD MOT	FORD	E-450	2021		0	0	UNITED ST	LA	Abita Sprir	23000	0	SERVICE BI	The contac	0		0	0			1	Yes	
1	NHTSA	11535359			8/7/2023	07-30-202		FORD MOT	FORD	E-450	2021		0	0	UNITED ST	NC	Summerfie	0	0	SERVICE BI	My RV is n	60		0	0			0	Yes	

S.No	Source	ODI/Sou	CMPL ID	Incident	Load/Re	Date Ad	VIN	Manufac	Make	Model	Model Y	Significa	Fatality #	Injury #	Country	State/Pr	City	Odometr	Occuren	Compon	Respons	Consum
1	NHTSA	1.2E+07	[redacted]		#######	7/6/2023	[redacted]	FORD MO	FORD	E-350	2021		0	0	UNITED S	FL	Daytona B	40000	0	SERVICE B	yes	The conta
4	NHTSA	1.2E+07			#######	5/9/2023		FORD MO	FORD	E-350	2022		0	0	UNITED S	UT	Saint Geo	12361	0	SERVICE B	yes	The conta
17	TRANSPO	2E+07			#######	#######		FORD MO	FORD	E-450	2022		0	0	CANADA	Ontario	Timmins	16205	0	POWER A	yes	Motorho
23	NHTSA	1.1E+07			#######	9/8/2022		FORD MO	FORD	E-350	2022		0	0	UNITED S	VA	Max Mead	6300	0	SERVICE B	yes	The conta
27	NHTSA	1.1E+07			#######	#######		FORD MO	FORD	E-450	2021		0	0	UNITED S	FL	Molino	4826	0	STEERING	yes	The conta
42	NHTSA	1.1E+07			#######	#######		FORD MO	FORD	E-450	2022		0	0	UNITED S	MI	Spring Lak	3200	0	STEERING	yes	The conta
27	NHTSA	1.1E+07			#######	4/1/2022		FORD MO	FORD	E-350	2021		0	0	UNITED S	NV	Las Vegas	22000	0	SERVICE B	yes	The conta
22	NHTSA	1.1E+07			#######	#######		FORD MO	FORD	E-450	2021		0	0	UNITED S	CA	Hemet	0	0	SERVICE B	yes	Regarding
15	NHTSA	1.1E+07			7/4/2022	#######		FORD MO	FORD	E-350	2021		0	0	UNITED S	OH	Monroe	10800	0	SERVICE B	yes	The conta

S.No	Source	ODI/Sour	CMPL ID	Incident	Load/Re	Date Add	VIN	Manufact	Make	Model	Model Ye	Significa	Fatality #	Injury #	Country	State/Pro	City	Odometer	Occurren	Compone	Consumer	Vehicle S	Vehicle s	Incident	Medical A	Fuel Typ	Defective	Vehicles	[redacted]
2	NHTSA	11535359	[redacted]		########	12-06-202	[redacted]	FORD MOT	FORD	E-450	2022		0	0	UNITED ST	MI	Jackson	0	0	STEERING	I am a mec	55		0	0			0	
80	NHTSA				########	05-11-202		FORD MOT	FORD	E-450	2021		0	0	UNITED ST	CA	Hemet	0	0	SERVICE B	Regarding	60		0	0			0	
70	NHTSA				7/4/2022	06-30-202		FORD MOT	FORD	E-350	2021		0	0	UNITED ST	OH	Monroe	10800	0	STEERING	The contac	65		0	0			0	
10	NHTSA	11509828			########	07-06-202		FORD MOT	FORD	E-350	2021		0	0	UNITED ST	FL	Daytona B	40000	0	STEERING	The contac	0		0	0			0	
31	NHTSA	11459276			########	09-08-202		FORD MOT	FORD	E-350	2022		0	0	UNITED ST	VA	Max Mead	6300	0	STEERING	The contac	65		0	0			0	
12	NHTSA	20222325			########	05-09-202		FORD MOT	FORD	E-350	2022		0	0	UNITED ST	UT	Saint Geor	12361	0	STEERING	The contac	60		0	0			1	
56	NHTSA				########	12-12-202		FORD MOT	FORD	E-450	2022		0	0	UNITED ST	MI	Spring Lak	3200	0	SERVICE B	The contac	0		0	0			0	

Plant [AAG]	Assembly Plant Desc	Style (NA VIN) Desc	Body/Cab Desc	Type [BS/CA]	Claim Key	Condition Code	Country Repaired	Country Sold	Comments	Concern Code	Document Number	Drive Type [DR]	Engine [EN]	Authorization	Labor Hours	Code Desc	Operation Code	Load Date	Derived [MD]	Material Cost	FSA Mileage	Model Year	Year (Fixed)	Base (Causal)	Prefix (Causal)	Suffix (Causal)	Production Date	Region Repaired
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3010501	*	USA	USA	ADD, PERFI	*	395553D	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	34288	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	223178	*	USA	USA	22S08 Rec	*	2256491	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1300	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2967782	*	USA	USA	22S08 Rec	*	R60101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	22991	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	222912	*	USA	USA		*	5385901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	15671	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2825997	*	USA	USA	22S08 Rec	*	2270181	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/8/2022	F	0	19088	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	223461	*	USA	USA	A99 22S08	*	39995501	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19726	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3047479	*	USA	USA	REPAIR rec	*	13844601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8609	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2997534	*	USA	USA		*	5390661	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	14330	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	211605	*	USA	USA	PERFORM I	*	737888B	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	29067	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	237858	*	USA	USA	Manufactu	*	5831001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9769	2022	2021	*	*	*	4/8/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	250305	*	USA	USA	Manufactu	*	6053631	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	20928	2022	2021	*	*	*	1/6/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	270497	*	CAN	CAN	FAIRE LE R/	*	15271301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	11110	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	301193	*	USA	USA	PERFORM I	*	13863201	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	16440	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2939127	*	USA	USA	22S08 POV	*	70763103	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	13456	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	285565	*	USA	USA	RECALL #2:	*	16465101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/6/2022	F	0	12170	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	286424	*	USA	USA	22S08 Rec	*	J921701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/6/2022	F	0	6831	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	278623	*	USA	USA	Manufactu	*	6156531	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	16358	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	237550	*	USA	USA	RECALL 22(	*	29164803	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19263	2022	2021	*	*	*	3/9/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	267783	*	USA	USA	RECALL 22(	*	90685002	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	16838	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 STRIP	STRIPPED (	T/CA	361029	*	USA	USA	22S08 HYD	*	8066440	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	29387	2022	2021	*	*	*	3/2/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	219486	*	CAN	CAN	Inspection	*	19066003	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16659	2022	2021	*	*	*	3/2/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	304262	*	USA	USA	Manufactu	*	7291331	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	18306	2022	2021	*	*	*	2/5/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	237860	*	USA	USA	Manufactu	*	5831801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9131	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	265179	*	CAN	CAN	RECALL / 2	*	33649801	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	17098	2022	2021	*	*	*	1/4/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3264463	*	USA	USA	RECALL 22(	*	97324A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	4343	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	304217	*	USA	USA	Manufactu	*	7321241	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	14734	2022	2021	*	*	*	4/8/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	312055	*	USA	USA	CUSTOMEF	*	2790211	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4230	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	222396	*	USA	USA	PERFORME	*	33941301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	28196	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3215703	*	USA	USA	Customer S	*	2789451	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12422	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	285872	*	CAN	CAN	RECALL 22(	*	459449A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	4/6/2022	F	0	18486	2022	2021	*	*	*	1/7/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3713932	*	USA	USA	PERFORM I	*	71805402	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12346	2021	2021	*	*	*	9/3/2020	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	250257	*	USA	USA	Manufactu	*	6067091	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12372	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2984054	*	USA	USA		*	5390051	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	26418	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3151416	*	USA	USA	CUSTOMEF	*	139051C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/7/2022	F	0	23905	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3495873	*	USA	USA	22S08	*	58072401	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/4/2022	F	0	31015	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	328129	*	USA	USA	22S08 HYD	*	59617101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19565	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	308012	*	USA	USA	PERFORM I	A99	801074B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6920	2022	2021	*	*	*	2/1/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3139684	*	USA	USA	COMPLETE	A99	3681631	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/6/2022	F	0	8110	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3398155	*	USA	USA	PERFORM I	*	364571	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4958	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3483334	*	USA	USA	RECALL 22(	*	730249C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/3/2022	F	0	4354	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	445358	*	CAN	CAN	RECALL 22(	*	209807A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	25536	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	250202	*	USA	USA	Manufactu	*	5971741	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	15720	2022	2021	*	*	*	2/4/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3311387	*	USA	USA	22S08 P/S I	*	30844801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2496	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3152963	*	CAN	CAN	HYDROBO(	*	368695C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/7/2022	F	0	34281	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	426417	*	USA	USA	PERFORME	*	34181701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	21027	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	351316	*	USA	USA	Manufactu	*	8469511	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	15828	2022	2021	*	*	*	1/7/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	241568	*	USA	USA	Manufactu	*	6002741	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8082	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	281753	*	USA	USA	PERFORM I	*	018035A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/5/2022	F	0	14793	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	366830	*	USA	USA	PERFORME	*	34137601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	30658	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	377560	*	USA	USA	22S08 FSA	*	96212303	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/2/2022	F	0	11463	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	323829	*	CAN	CAN	RECALL 22(	*	459874A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	12022	2022	2021	*	*	*	1/4/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	390038	*	USA	USA	FACTORY R	*	14931902	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/4/2022	F	0	18806	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3225294	*	USA	USA	Campaign I	*	025192B	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	11012	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3296244	*	USA	USA	Perform Re	*	9417132	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	11804	2021	2021	*	*	*	########	NA

RQ24-003 000193 RC

BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	571999	*	USA	USA	CERTAIN 2(	*	693754A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	6/3/2022	F	0	17143	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	250254	*	USA	USA	Manufactu	*	6187781	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	17728	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	251235	*	USA	USA	22S08 HYD	*	15226901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	18221	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	474221	*	USA	USA	PERFORME	*	34200301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	25570	2022	2021	*	*	*	2/9/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3062772	*	USA	USA	CUSTOMEF	*	5490501	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4686	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3277861	*	USA	USA	PERFORM	*	5140803	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	5685	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	273338	*	USA	USA	PERFORME	*	34027701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/1/2022	F	0	15616	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	250663	*	CAN	CAN	VERF RAPP	*	491301A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	11399	2022	2021	*	*	*	1/6/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	338432	*	USA	USA	PERFORME	*	34112701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	22824	2022	2021	*	*	*	4/7/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	309612	*	USA	USA	Customer s	*	094522A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8060	2022	2021	*	*	*	3/3/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	326921	*	USA	USA	Customer s	*	094548A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9616	2022	2021	*	*	*	3/3/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	526243	*	USA	USA	HYDROBO(	*	285896A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3562	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	312140	*	USA	USA	RECALL 22	*	10612702	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2408	2022	2021	*	*	*	2/8/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3655137	*	CAN	CAN	HYDROBO(	*	636419D	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	32702	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	278685	*	USA	USA	Manufactu	*	6630921	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	9721	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3788840	*	USA	USA	HYDROBO(	*	117906A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	11691	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	564151	*	USA	USA	RECALL 22	*	311265D	T/B	T/J0	S	0.3	HYDROBO(	22S08A	6/1/2022	F	0	5672	2022	2021	*	*	*	4/7/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	278708	*	USA	USA	Manufactu	*	6729311	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	8544	2022	2021	*	*	*	2/1/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3300297	*	USA	USA	PERFORM	*	53413502	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3661	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	304165	*	USA	USA	Manufactu	*	7155421	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12136	2022	2021	*	*	*	1/4/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3012587	*	USA	USA	22S08 HYD	A99	749842A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	14796	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3164862	*	USA	USA	CAMPAIGN	*	78750A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/8/2022	F	0	3071	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3208954	*	USA	USA	RECALIBRA	*	68952302	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4204	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3434017	*	USA	USA	22S08 HYD	*	51769701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6988	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3112415	*	USA	USA	RECALL 22	*	36909001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	4944	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	247240	*	USA	USA		*	5390471	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6622	2022	2021	*	*	*	3/2/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	263883	*	USA	USA	RECALL-22	*	54662701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8068	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	379354	*	USA	USA	Customer s	*	034692B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/2/2022	F	0	9841	2022	2021	*	*	*	2/2/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	276357	*	CAN	CAN	RECALL 22	*	785092A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	2018	2022	2021	*	*	*	2/4/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3205216	*	USA	USA	RECALL CU	*	77201	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16433	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	304137	*	USA	USA	Manufactu	*	7269111	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8921	2022	2021	*	*	*	3/8/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	371950	*	USA	USA	PERFORM	*	10914501	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	10	2022	2021	*	*	*	2/1/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3013017	*	USA	USA	22S08 HYD	*	15219801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	14775	2021	2020	*	*	*	2/6/2020	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	254762	*	CAN	CAN	HYDROBO(	*	784483A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1890	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	454724	*	CAN	USA	FAIRE RAPI	*	17683901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2686	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	298951	*	USA	USA	PERFORME	*	34063801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	17601	2022	2021	*	*	*	4/7/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4250494	*	USA	USA	HYDROBO(	*	100329A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8464	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	689197	*	USA	USA		A99	8502301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4535	2022	2021	*	*	*	3/5/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2774755	*	USA	USA	PERFORM	*	1154201	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/3/2022	F	0	8315	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	444378	*	USA	USA	PERFORME	*	34186701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16827	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	278600	*	USA	USA	Manufactu	*	6720161	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	16901	2022	2021	*	*	*	2/4/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4195191	*	USA	USA	RECALL 22	*	763825A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6372	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	580306	*	USA	USA	RECALL 22	*	723874A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	6/6/2022	F	0	3021	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	408026	*	USA	USA	22S08 HYD	*	424290A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/9/2022	F	0	21851	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4464661	*	USA	USA		*	5450331	T/B	T/J0	S	0.3	HYDROBO(	22S08A	7/1/2022	F	0	24850	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4522529	*	USA	USA	PERFORM	*	33252205	T/B	T/J0	S	0.3	HYDROBO(	22S08A	7/6/2022	F	0	3729	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	688846	*	USA	USA	PERFORM	*	11343401	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	5	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3499324	*	USA	USA	CHECK ALL	*	5204601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/4/2022	F	0	11485	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	371252	*	USA	USA	DIAGNOST	*	5541501	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	949	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	761494	*	USA	USA	22S08 HYD	A99	1931740	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	15303	2022	2021	*	*	*	3/4/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	297834	*	USA	USA	RECALL 22	*	358607D	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	14913	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3481659	*	USA	USA	COMPLETE	A99	3712101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/3/2022	F	0	1483	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4276259	*	USA	CAN	FIELD SERV	A99	57283202	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	32395	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2811280	*	USA	USA	RECALL 22	*	2390601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/7/2022	F	0	13432	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4248733	*	USA	USA	22S08 HYD	*	13067601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	27467	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3173868	*	USA	USA	SERVICE C/	*	12595703	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/8/2022	F	0	2986	2021	2021	*	*	*	########	NA

RQ24-003 000194 RC

BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	395587	*	CAN	CAN	22S08 HYD	*	785275A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	5/5/2022	F	0	10765	2022	2021	*	*	*	3/2/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	298944	*	USA	USA	PERFORME	*	34062901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	20690	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4920302	*	USA	USA	Field servic	A99	24007501	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/5/2022	F	0	38561	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4145317	*	CAN	USA	FAIRE RAPI	*	06639D	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	11671	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	337460	*	USA	USA	PERFORME	*	34104401	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16731	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	278796	*	USA	USA	Manufactu	*	6457871	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	18216	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	336010	*	USA	USA	HYDROBO(	*	782280A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	10061	2022	2021	*	*	*	2/2/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4876622	82	USA	USA	FORD RECA	A99	045239C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/4/2022	F	0	2468	2021	2021	3A717	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	337757	*	USA	USA	PERFORME	*	34106301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	11949	2022	2021	*	*	*	4/1/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	2835354	*	USA	USA	22S08 Recc	*	J871301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/9/2022	F	0	27250	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	351299	*	USA	USA	Manufactu	*	8627811	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	5706	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5460198	*	USA	USA	Perform Re	*	9465752	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	13988	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	218994	*	USA	USA	PERFORME	*	33914201	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	28086	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	337511	*	USA	USA	PERFORME	*	34105001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	24468	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	351171	*	USA	USA	Manufactu	*	8449801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12112	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2994644	*	USA	USA	PERFORM I	*	48071	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1181	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	218982	*	USA	USA	PERFORME	*	33914001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16121	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1001754	*	USA	USA	Field servic	A99	31012801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	18907	2022	2021	*	*	*	3/3/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	278637	*	USA	USA	Manufactu	*	6656341	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	9730	2022	2021	*	*	*	3/3/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	937118	*	USA	USA	Field servic	A99	31014601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/5/2022	F	0	19145	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3390185	*	USA	USA	22S08	*	57369502	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	7453	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5455974	*	USA	USA	22S08 HYD	*	236879B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	20283	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3047296	*	USA	USA	22S08 Recc	*	J888801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12152	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	572969	*	USA	USA	recall 22s0	*	52171	T/B	T/J0	S	0.3	HYDROBO(	22S08A	6/3/2022	F	0	8432	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1026953	*	USA	USA		*	5514601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16049	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3127586	*	USA	USA	recall 22s0	*	1290251	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/5/2022	F	0	883	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1026832	*	USA	USA		*	5514181	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	20425	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	341715	*	USA	USA	RECALL 22	*	273591A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	7293	2022	2021	*	*	*	2/5/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	427074	*	USA	USA	22S08 HYD	*	71899801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4129	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1059981	*	USA	USA		*	5523151	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	10602	2022	2021	*	*	*	2/9/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	709995	*	USA	USA	PERFORME	*	34278101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8759	2022	2021	*	*	*	3/2/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1026945	*	USA	USA		*	5514271	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	32953	2022	2021	*	*	*	2/1/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	464081	*	USA	USA	22S08 POV	*	134307A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3726	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4920317	*	USA	USA	Field servic	A99	31009801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/5/2022	F	0	18267	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5740845	*	USA	USA	22S08 HYD	*	2489952	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	5381	2021	2020	*	*	*	2/4/2020	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1026859	*	USA	USA		*	5513281	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	21085	2022	2021	*	*	*	2/3/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3862840	*	USA	USA	PERFORM I	*	11074201	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	417	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3643886	*	USA	USA	RECALL 22	*	133740A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	7811	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2881003	*	USA	USA	PERFORM I	*	83082402	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	23338	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5435178	*	USA	USA		*	5555371	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	21271	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1040715	*	USA	USA		*	5520301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	26452	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1025707	*	USA	USA	22S08 HYD	*	270998A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3710	2022	2021	*	*	*	2/5/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1026964	*	USA	USA		*	5514551	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8406	2022	2021	*	*	*	3/5/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	700415	*	CAN	CAN	VERF RAPP	*	494840B	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	20333	2022	2021	*	*	*	1/6/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	323830	*	CAN	CAN	RECALL 22	*	459800A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	12679	2022	2021	*	*	*	1/6/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4832154	*	USA	USA	RECALL 22	A99	359486B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/1/2022	F	0	17713	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1040825	*	USA	USA		*	5518281	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19964	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3009149	*	USA	USA	Customer S	*	9409041	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2104	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	5725081	*	USA	USA	CUSTOMEF	*	26038601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	13188	2021	2020	*	*	*	2/5/2020	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3632225	*	USA	USA	22S08 HYD	*	258005A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6114	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1069028	*	USA	USA		*	5525371	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	14263	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	666129	*	CAN	CAN	FAIRE RAPI	*	07045A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	15440	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	259734	*	USA	USA	C/S RECALL	*	49264B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6952	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4920264	*	USA	USA	Field servic	A99	24009001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/5/2022	F	0	19529	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	250164	*	USA	USA	Manufactu	*	6156731	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	7354	2022	2021	*	*	*	2/2/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5405761	*	USA	USA		*	5547971	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	20891	2021	2021	*	*	*	########	NA

RQ24-003 000195 RC

BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5433310	*	USA	USA	*	5553941	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	24450	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	633949	*	USA	USA	RECALL 22(	556439A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12	2022	2021	*	*	*	3/8/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4790349	*	USA	USA	CUSTOMEF	65008404	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	25903	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5420634	*	USA	USA	*	5549061	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	22149	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1050192	*	USA	USA	*	5522401	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19350	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5083534	*	USA	USA	*	5515081	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	18433	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4878986	*	USA	USA	22S08 HYD	308516A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/4/2022	F	0	2183	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2074280	*	USA	USA	22S08 HYD	20794901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	1/4/2023	F	0	6045	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5460066	*	USA	USA	Perform Re	9471772	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	26569	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	453751	*	USA	USA	CERTAIN 2(	401870A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	22265	2022	2021	*	*	*	1/5/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	312937	*	USA	USA	Campaign i	019350C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	685	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	338211	*	USA	USA	CUSTOMEF	22149501	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3302	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	232528	*	USA	USA	PERFORM i	158682A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	10120	2022	2021	*	*	*	1/4/2021	NA
BH	OHIO ASSE	E450 STRIP	STRIPPED (	T/CA	994067	*	CAN	CAN	PERFORM i	48513202	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	15099	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5689031	*	USA	USA	RECALL 22(	103559A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2147	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	360964	*	USA	USA	RECALL 22(	36561401	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	112	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	7467868	*	CAN	CAN	HYDROBO(	53212503	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	32652	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5359119	*	USA	USA	RECALL 22(	217051B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3576	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3097345	*	USA	USA	22S08 REC	9806402	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/1/2022	F	0	2542	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	299257	*	USA	USA	RECALL 22(	9816301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4385	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2706422	*	USA	USA	Customer S	1338333	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6291	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	425803	*	USA	USA	RECALL 22(	1288201	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1135	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	6495847	*	USA	USA	RECALL 22(	136172A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9883	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	322404	*	USA	USA	PERFORME	34093201	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	16914	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3408820	*	USA	USA	*	5408881	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	24291	2021	2021	*	*	*	9/2/2020	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3326793	*	USA	USA	RECALL 22(	8119701	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1667	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3173163	*	USA	USA	PERFORM i	10187802	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/8/2022	F	0	7709	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	948149	*	USA	USA	Field servic	A99	31015101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/8/2022	F	0	11868	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	921026	*	USA	USA	22S08 HYD	268916A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/4/2022	F	0	4171	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5336283	*	USA	USA	CUSTOMEF	837864A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	9/8/2022	F	0	6318	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2812991	*	USA	USA	22S08 Rec	2260261	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/7/2022	F	0	20216	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	6904395	*	USA	USA	CUSTOMEF	060622D	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	19859	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3094469	*	USA	USA	Recalls 22S	7701806	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/1/2022	F	0	12790	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	382523	*	CAN	USA	FAIRE RAPI	17631103	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/3/2022	F	0	1208	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	322797	*	USA	USA	RECALL 22(	192191A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	450	2022	2021	*	*	*	4/7/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3158023	*	USA	USA	22S08 HYD	253354A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/7/2022	F	0	8889	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4376648	*	USA	USA	RECALL RE(	6664702	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19039	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	388538	*	USA	USA	Perform Re	9424411	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/4/2022	F	0	1646	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	999502	*	USA	USA	HYDROBO(	570386A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	25262	2022	2021	*	*	*	3/5/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	305033	*	USA	USA	22S08 HYD	890040	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2225	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1494988	*	USA	USA	22S08 HYD	2487001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12903	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3465282	*	USA	USA	RECALL 22(	852889A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/2/2022	F	0	2999	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	1020008	*	USA	USA	Field servic	A99	24022901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	11151	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	7832821	*	USA	USA	PERFORM i	30832001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2968	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	223618	*	USA	USA	COMPLETE	A99	3667351	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	23	2022	2021	*	*	*	4/8/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	409423	*	USA	USA	Campaign i	055336A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/9/2022	F	0	2461	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3282139	*	USA	USA	GUEST REC	6211002	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9344	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	1001751	*	USA	USA	Field servic	A99	24019301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	24269	2022	2021	*	*	*	3/3/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	281684	*	USA	USA	RECALL 22(	796357A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/5/2022	F	0	2033	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	342409	*	USA	USA	22S08 HYD	8079540	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1280	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4740098	*	USA	USA	RECALL 22(	11141001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1627	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	845694	*	USA	USA	RECALL 22(	681265A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	12315	2022	2021	*	*	*	4/6/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	836234	*	USA	USA	RECALL 22(	75694201	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2819	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	278644	*	USA	USA	RECALL 22(	315322A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	4408	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	195844	*	USA	USA	22S08 Rec	2280251	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/3/2022	F	0	16150	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	5606455	*	USA	USA	CUSTOMEF	030785B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	5415	2021	2021	*	*	*	########	NA

RQ24-003 000196 RC

RQ24-003 000197 RC

BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	260007	*	USA	USA	PERFORM	*	18838901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1708	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3460290	*	USA	USA	CUSTOMEI	*	32078801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/2/2022	F	0	8188	2021	2020	*	*	*	3/9/2020	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	906519	*	USA	USA	C/S: 22S08	*	1589301	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/2/2022	F	0	4526	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4127140	*	USA	USA	22s08 reca	*	025332A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3855	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2998312	*	CAN	CAN	PERFORM	*	17923101	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2129	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	277110	*	USA	USA	RECALL 22	*	10550303	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/4/2022	F	0	1712	2022	2021	*	*	*	3/8/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	286434	*	USA	USA	PERFORM	*	15268001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	4/6/2022	F	0	5560	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3494200	*	USA	USA	Perform Re	*	9424391	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/4/2022	F	0	5603	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1362547	*	USA	USA	PERFORM	*	239092A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2546	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3266775	*	USA	USA	PERFORM	*	273132A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3814	2021	2020	*	*	*	2/3/2020	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	1334727	*	USA	USA	22S08 HYD	A99	1949940	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4012	2022	2021	*	*	*	1/4/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	2998280	*	CAN	CAN	PERFORM	*	17923901	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	458	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	2835120	*	USA	USA	22S08 HYD	*	253098C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	3/9/2022	F	0	2941	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3055430	*	USA	USA	CUSTOMEI	*	138889A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4915	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4966509	*	USA	USA	PERFORM	*	577656A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3714	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4202550	*	USA	USA	22S08 HYD	*	59676001	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	12832	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	538190	*	USA	USA	22S08 HYD	*	59303601	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9624	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	382352	*	USA	USA	22S08-HYD	*	507969A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	5/3/2022	F	0	1975	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3676174	*	CAN	CAN	FAIRE RAPI	*	05788C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1034	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	3672229	*	USA	USA	HYDROBO(	*	401776D	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	8107	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	254899	*	CAN	CAN	22S08 HYD	*	527470A	T/B	T/K0	S	0.3	HYDROBO(	22S08A	########	F	0	17966	2022	2021	*	*	*	3/3/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3599448	*	USA	USA	22S08	*	414284C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	3301	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	3127437	*	CAN	CAN	RAPPEL DE	*	30801001	T/B	T/K0	S	0.3	HYDROBO(	22S08A	4/5/2022	F	0	3544	2021	2020	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	349655	*	USA	USA	Campaign	*	017636C	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4075	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	5753546	*	USA	USA	RECALL 22	*	789160A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	13542	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	2884157	*	USA	USA	RECALL #2	*	492290A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9305	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4854602	*	USA	USA	22S08 HYD	A99	704872A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	8/2/2022	F	0	3626	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	4355554	*	USA	USA	RECALL - 2	*	533791A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4146	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	7569816	*	USA	USA	PERFORM	*	035185A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	22568	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	263459	*	USA	USA	RECALL 22	*	36750603	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1705	2022	2021	*	*	*	3/1/2021	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	4820559	*	USA	USA	22S08 POV	*	508318B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	4308	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	9858340	*	USA	USA	PERFORM	*	7936801	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	19505	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E350 SUPE	CUTAWAY	T/CD	1346729	*	USA	USA	HYDROBO(	*	526793B	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	6146	2022	2021	*	*	*	3/5/2021	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	308006	*	USA	USA	SERVICE C/	*	12625002	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	2186	2022	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	6195811	*	USA	USA	22S08-CER	*	932046A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	9056	2021	2021	*	*	*	########	NA
BH	OHIO ASSE	E450 SUPE	CUTAWAY	T/CD	317487	*	CAN	CAN	22S08 HYD	*	785865A	T/B	T/J0	S	0.3	HYDROBO(	22S08A	########	F	0	1766	2022	2021	*	*	*	########	NA

RQ24-003 000198 RC

FSA Date	Dealer Name	Dealer State	Replace Flag	embly Plant	y/Cab Type	Right_Clai m Key	dition Code	ntry Repaired	Right_Coun try Sold	tomer Comment	tomer Concern	ument Number	e Type [DR]	Right_Eng ine [EN]	Right_Lab or Hours	rket Derived	Right_Mat erial Cost	Repair Mileage	Right_Mo del Year	del Year (Fixed)	Right_Part Num Base (Causal)	Num Prefix (Causal)	Num Suffix (Causal)	roducti on Date	t_Re gion	Line Repair Date	air Dealer Name
2/16/2022	WORLD FO	FL		BH	T/CD	3052163	D8	USA	USA	CUSTOMEI	L63	395553A	T/B	T/J0	8.9	F	1236.22	34288	2021	2020	2005	LC2Z	B	######	NA	2/16/2022	WORLD FO
3/7/2022	ROAD BEAI	CA		BH	T/CD	212774	1	USA	USA	Power stee	L68	2256491	T/B	T/J0	1	F	212.23	13002	2022	2021	3A717	LC2Z	C	######	NA	3/10/2022	ROAD BEAI
3/14/2022	ROAD BEAI	CA		BH	T/CD	2896393	1	USA	USA	Power stee	L68	2260101	T/B	T/J0	1	F	212.23	22991	2021	2021	3A717	LC2Z	C	######	NA	3/14/2022	ROAD BEAI
3/14/2022	U-HAUL - S	PA		BH	T/CD	244517	16	USA	USA	POWER ST	L68	5390131	T/B	T/J0	0.7	F	63.96	15671	2022	2021	3A717	BC2Z	E	######	NA	3/14/2022	U-HAUL - S
3/8/2022	ROAD BEAI	CA		BH	T/CD	3364277	D8	USA	USA	STEERING	L68	14237202	T/B	T/J0	5	F	654.45	19881	2021	2021	3A717	LC2Z	C	######	NA	3/16/2022	ANDERSON
3/8/2022	PLANET FO	TX		BH	T/CD	268624	42	USA	USA	L68 CUSTO	L68	40192201	T/B	T/J0	1.2	F	245.39	19872	2022	2021	3A717	LC2Z	C	######	NA	3/17/2022	PLANET FO
3/21/2022	OSSEO FOF	WI		BH	T/CD	3047260	D8	USA	USA	check caus	L68	13844602	T/B	T/J0	3.5	F	574.17	8609	2021	2021	3A674	LC2Z	A	######	NA	3/21/2022	OSSEO FOF
3/23/2022	U-HAUL - S	PA		BH	T/CD	3122401	D4	USA	USA	NO POWEI	L68	5395251	T/B	T/J0	0.7	F	144	14330	2021	2021	3A717	LC2Z	C	######	NA	3/23/2022	U-HAUL - S
3/8/2022	ALL AMERI	NJ		BH	T/CD	259204	D8	USA	USA	CUSTOMEI	L68	739044A	T/B	T/K0	2.5	F	728.21	30514	2022	2021	3A674	LC2Z	A	######	NA	3/25/2022	ALL AMERI
3/21/2022	EAN HOLDI	NY		BH	T/CD	419457	D8	USA	USA	CHECK ENC	L68	377640A	T/B	T/J0	2	F	341.8	10419	2022	2021	3A717	LC2Z	C	######	NA	3/26/2022	PACIFICO F
3/23/2022	EAN HOLDI	CT		BH	T/CD	309196	D8	USA	USA	NO BRAKE!	L68	2727801	T/B	T/J0	1.5	F	306.77	21280	2022	2021	3A717	LC2Z	D	######	NA	3/28/2022	PERFORMA
3/30/2022	AUTOS J G	QC		BH	T/CD	315845	D8	CAN	CAN	SELON LE (	L68	15285202	T/B	T/J0	3.3	F	238.126	11186	2022	2021	3A719	4C2Z	B	######	NA	4/6/2022	AUTOS J G
4/5/2022	WOODHOL	NE		BH	T/CD	301273	42	USA	USA	CHECK FOF	L68	13873301	T/B	T/K0	2	F	331.23	16455	2022	2021	3A719	4C2Z	B	######	NA	4/6/2022	WOODHOL
3/15/2022	FORD OF M	TN		BH	T/CD	3212800	42	USA	USA	Customer s	L68	27125701	T/B	T/J0	1.2	F	364.91	14522	2021	2020	3A719	4C2Z	B	######	NA	4/7/2022	FORD OF C
4/5/2022	BIDLEMAN	NY		BH	T/CD	323054	D8	USA	USA	CUSTOMEI	L68	16471701	T/B	T/J0	1.4	F	270.6	13136	2022	2021	3A717	LC2Z	C	######	NA	4/7/2022	BIDLEMAN
2/24/2022	EL MONTE	CA		BH	T/CD	581112	1	USA	USA	POWER ST	L68	45896601	T/B	T/J0	2.6	F	565.4	8165	2022	2021	3A674	*	*	######	NA	4/7/2022	RUSH TRUC
3/31/2022	ENTERPRIS	WV		BH	T/CD	303176	34	USA	USA	C/S THAT S	L68	085030A	T/B	T/J0	1	F	168	16901	2022	2021	3A717	LC2Z	C	######	NA	4/8/2022	TODD JUDY
3/18/2022	HERITAGE	CA		BH	T/CD	317237	42	USA	USA	SUSP CUST	L68	29272003	T/B	T/J0	4	F	709.71	23152	2022	2021	3A674	LC2Z	A	######	NA	4/8/2022	HERITAGE
3/28/2022	PLANET FO	TX		BH	T/CD	470198	42	USA	USA	CUSTOMEI	L68	90840602	T/B	T/K0	4	F	665.77	17599	2022	2021	3A674	LC2Z	A	######	NA	4/13/2022	PLANET FO
4/18/2022	BONDY'S F	AL		BH	T/CA	360920	42	USA	USA	CS HAS NO	L68	8066451	T/B	T/K0	1.9	F	496.69	29387	2022	2021	3A674	LC2Z	A	######	NA	4/18/2022	BONDY'S F
3/10/2022	VAL ESTRIE	QC		BH	T/CD	349441	42	CAN	CAN	FUITE MAJ	L68	19215502	T/B	T/J0	3	F	640.1057	19601	2022	2021	3A674	LC2Z	A	######	NA	4/19/2022	VAL ESTRIE
4/6/2022	EAN HOLDI	VA		BH	T/CD	580750	34	USA	USA	Customer s	L68	065230B	T/B	T/J0	2	F	139.99	18885	2022	2021	3A719	4C2Z	B	######	NA	4/19/2022	YES FORD
3/21/2022	EAN HOLDI	NY		BH	T/CD	446347	42	USA	USA	CUSTOMEI	L68	249435A	T/B	T/J0	1	F	572.98	10466	2022	2021	3A717	LC2Z	C	######	NA	4/19/2022	GIBBONS F
3/28/2022	TIMBERLAI	ON		BH	T/CD	361177	D8	CAN	CAN	INSPECT FO	L68	33688001	T/B	T/K0	1.9	F	168.5167	21740	2022	2021	3A717	LC2Z	C	######	NA	4/20/2022	TIMBERLAI
4/13/2022	COURTESY	IA		BH	T/CD	3388750	42	USA	USA	POWER ST	L68	97482A	T/B	T/K0	1.5	F	247.6	4393	2021	2020	3A717	LC2Z	C	######	NA	4/21/2022	COURTESY
4/7/2022	EAN HOLDI	OH		BH	T/CD	386751	D4	USA	USA	tow in cust	L68	036479A	T/B	T/J0	2.1	F	228.71	15706	2022	2021	3A717	LC2Z	C	######	NA	4/22/2022	BOB GILLIN
4/12/2022	THE FORD	CA		BH	T/CD	377981	42	USA	USA	CUST STAT	L68	371361A	T/B	T/J0	1.7	F	379.72	5614	2022	2021	3A719	4C2Z	B	######	NA	4/22/2022	AUTONATI
3/9/2022	PENSKE TR	TX		BH	T/CD	424218	D4	USA	USA	Complaint:	L68	34178101	T/B	T/J0	4.3	F	204.72	34530	2022	2021	3A717	LC2Z	C	######	NA	4/23/2022	PENSKE TR
4/11/2022	THE FORD	CA		BH	T/CD	3494173	42	USA	USA	CUST STAT	L68	699048A	T/B	T/J0	3.2	F	717.74	12571	2021	2021	3A674	LC2Z	A	######	NA	4/25/2022	JIM BURKE
4/5/2022	MID-TOWI	MB		BH	T/CD	364783	D8	CAN	CAN	CHECK ANI	L68	460380A	T/B	T/K0	2.2	F	246.6583	20904	2022	2021	3A717	LC2Z	C	######	NA	4/25/2022	MID-TOWI
4/28/2022	RUSH TRUC	CA		BH	T/CD	3713468	D8	USA	USA	DURING IN	L68	71805403	T/B	T/J0	3	F	238.84	12346	2021	2021	3A719	*	*	######	NA	4/28/2022	RUSH TRUC
3/23/2022	EAN HOLDI	NH		BH	T/CD	557509	69	USA	USA	CUSTOMEI	L68	247541A	T/B	T/J0	4.4	F	673.54	14833	2022	2021	3A674	LC2Z	A	######	NA	4/28/2022	SALEM FOF
3/22/2022	U-HAUL - S	PA		BH	T/CD	3622378	D4	USA	USA	NO POWEI	L68	5411131	T/B	T/J0	1	F	322.01	28326	2021	2021	3A717	LC2Z	C	######	NA	4/29/2022	U-HAUL - S
4/7/2022	DAVIES FO	PA		BH	T/CD	3730593	D1	USA	USA	CUSTOMEI	L68	139450A	T/B	T/J0	1.8	F	241.31	27409	2021	2021	3A717	LC2Z	C	######	NA	5/3/2022	DAVIES FO
4/28/2022	SHEEHY FO	VA		BH	T/CD	5139654	42	USA	USA	C/S LINE BI	L68	5906303	T/B	T/J0	3	F	541.54	31392	2021	2021	3A674	LC2Z	A	######	NA	5/3/2022	MALLOY FC
4/14/2022	LANCE CUI	TN		BH	T/CD	625203	41	USA	USA	CUSTOMEI	L68	59706701	T/B	T/J0	3.6	F	569.48	20579	2022	2021	3A674	LC2Z	A	######	NA	5/5/2022	LANCE CUI
4/13/2022	CAVENDER	TX		BH	T/CD	559441	D8	USA	USA	CUSTOMEI	L68	59034401	T/B	T/J0	3	F	447.79	7908	2022	2021	3A674	LC2Z	A	######	NA	5/9/2022	SANDERSO
3/29/2022	MIDWAY F	MO		BH	T/CD	3621992	42	USA	USA	MEDIUM D	L68	16090701	T/B	T/J0	1.6	F	286.3	8926	2021	2021	3A719	4C2Z	B	######	NA	5/9/2022	BORGMAN
4/25/2022	TS&S FORE	OR		BH	T/CD	3833524	42	USA	USA	CHECK SER	L68	854664A	T/B	T/J0	3.1	F	485.72	6518	2021	2021	3A674	LC2Z	A	######	NA	5/9/2022	EARNHARD
5/3/2022	ANDERSON	IL		BH	T/CD	3676256	1	USA	USA	HEARD A L	L68	730660B	T/B	T/J0	1.2	F	236.6	4379	2021	2021	3A719	4C2Z	B	######	NA	5/10/2022	ANDERSON
5/9/2022	WATERLOC	AB		BH	T/CD	525535	D8	CAN	CAN	CHECK ANI	L68	210135A	T/B	T/J0	2.7	F	139.2032	26106	2022	2021	3A719	LC2Z	B	######	NA	5/17/2022	WATERLOC
3/22/2022	EAN HOLDI	CT		BH	T/CD	559807	42	USA	USA	Hydroboos	L68	862821	T/B	T/J0	1.2	F	180.34	20519	2022	2021	3A719	4C2Z	B	######	NA	5/18/2022	EAN HOLDI
4/19/2022	PLACE MO	MA		BH	T/CD	4171315	1	USA	USA	C/S STATES	L68	192830A	T/B	T/J0	2.6	F	485.97	3653	2021	2021	3A717	LC2Z	C	######	NA	5/18/2022	MID-TENN
3/31/2022	MARKVILLI	ON		BH	T/CD	4526896	D8	CAN	CAN	CHECK ANI	L68	101785A	T/B	T/J0	2	F	198.5782	35736	2021	2020	3A717	LC2Z	C	######	NA	5/18/2022	WHITEOAK
5/4/2022	PENSKE TR	TX		BH	T/CD	730687	D4	USA	USA	Complaint:	L68	34281001	T/B	T/J0	5.2	F	317.4	22177	2022	2021	3A674	LC2Z	A	######	NA	5/19/2022	PENSKE TR
4/20/2022	EAN HOLDI	MO		BH	T/CD	556194	24	USA	USA	C/S THE BR	L68	092777A	T/B	T/J0	4.7	F	404.49	19750	2022	2021	3A717	*	*	######	NA	5/19/2022	BROADWA
3/22/2022	ENTERPRIS	GA		BH	T/CD	597302	D4	USA	USA	09-TRU DIE	L68	73956401	T/B	T/J0	1.4	F	256	9968	2022	2021	3A719	4C2Z	A	######	NA	5/24/2022	COURTESY
4/1/2022	MIKE BURC	GA		BH	T/CD	637550	42	USA	USA	CUSTOMEI	L68	018896A	T/B	T/J0	2	F	213.63	21606	2022	2021	3A674	LC2Z	A	######	NA	5/26/2022	MIKE BURC
4/22/2022	PENSKE TR	TX		BH	T/CD	638759	D4	USA	USA	OVERHEAT	L68	34255801	T/B	T/J0	5.2	F	297.6	33822	2022	2021	3A674	LC2Z	A	######	NA	5/26/2022	PENSKE TR
3/7/2022	BIG VALLE	CA		BH	T/CD	604060	D4	USA	USA	Complaint:	L68	34250601	T/B	T/J0	1.6	F	144	15112	2022	2021	3A717	LC2Z	C	######	NA	5/27/2022	PENSKE TR
4/12/2022	MID-TOWI	MB		BH	T/CD	612710	D8	CAN	CAN	CHECK ANI	L68	53139901	T/B	T/K0	1.1	F	191.9004	13447	2022	2021	3A719	4C2Z	B	######	NA	5/30/2022	CAPITAL FC
5/4/2022	GROOVE FI	CO		BH	T/CD	603014	42	USA	USA	CUSTOMEI	L68	13020601	T/B	T/J0	3.5	F	616.39	20063	2022	2021	3A674	LC2Z	A	######	NA	5/31/2022	LOVELAND
4/11/2022	FRIENDLY I	NY		BH	T/CD	4074066	42	USA	USA	Customer s	L68	053755B	T/B	T/K0	3.1	F	468.15	12596	2021	2021	3A674	LC2Z	A	######	NA	6/1/2022	NORTH EAS
4/14/2022	PERFORMA	UT		BH	T/CD	4659597	42	USA	USA	C/S THE PC	L68	627592A	T/B	T/J0	2.7	F	206.08	12008	2021	2021	3A717	LC2Z	C	######	NA	6/1/2022	LARRY H. M

5/26/2022	CAPITOL CI	IN	BH	T/CD	775795	42	USA	USA	C/S THE ST	L68	694071A	T/B	T/J0	1.5	F	447.8	17550	2022	2021	3A674	LC2Z	A	######	NA	6/2/2022	CAPITOL CI
3/24/2022	EAN HOLDI	CT	BH	T/CD	659958	42	USA	USA	Previously	L68	2139821	T/B	T/J0	2	F	172.07	24438	2022	2021	3A717	LC2Z	C	######	NA	6/3/2022	EAN HOLDI
3/21/2022	LAIRD NOL	KS	BH	T/CD	634360	D1	USA	USA	VEHICLE TC	L68	752701	T/B	T/J0	1.3	F	223.11	30113	2022	2021	3A717	LC2Z	C	######	NA	6/3/2022	LAIRD NOL
5/13/2022	PENSKE TR	TX	BH	T/CD	662376	D4	USA	USA	OVERHEAT	L68	34264401	T/B	T/J0	5.2	F	297.6	27519	2022	2021	3A674	LC2Z	A	######	NA	6/3/2022	PENSKE TR
3/29/2022	RONNIE W	AL	BH	T/CD	4482796	42	USA	USA	CUSTOMEI	L68	68697001	T/B	T/J0	1.8	F	588.3	7496	2021	2021	3A674	LC2Z	A	######	NA	6/3/2022	BELL FORD
4/14/2022	ROD BAKEI	IL	BH	T/CD	4175940	42	USA	USA	CUST PREV	L68	5426001	T/B	T/J0	2	F	225.23	5696	2021	2021	3A717	LC2Z	C	######	NA	6/4/2022	ROD BAKEI
3/11/2022	PENSKE TR	TX	BH	T/CD	639066	D4	USA	USA	OVERHEAT	L68	34257701	T/B	T/J0	5.2	F	153.6	17460	2022	2021	3A674	LC2Z	A	######	NA	6/5/2022	PENSKE TR
3/23/2022	CHARTRAN	QC	BH	T/CD	658659	D8	CAN	CAN	VERF P/S N	L68	494530B	T/B	T/K0	1.9	F	191.9004	14126	2022	2021	3A717	LC2Z	C	######	NA	6/6/2022	CHARTRAN
4/14/2022	PENSKE TR	TX	BH	T/CD	664082	D4	USA	USA	OVERHEAT	L68	34266801	T/B	T/J0	5.2	F	317.4	27608	2022	2021	3A674	LC2Z	A	######	NA	6/7/2022	PENSKE TR
4/11/2022	BELL FORD	WI	BH	T/CD	714792	D1	USA	USA	Customer s	L68	096200A	T/B	T/J0	0.9	F	273.89	9001	2022	2021	3A717	LC2Z	C	######	NA	6/8/2022	BELL FORD
4/12/2022	BELL FORD	WI	BH	T/CD	615635	1	USA	USA	CHECK VEH	L68	720236A	T/B	T/J0	3.9	F	447.8	12215	2022	2021	3A717	LC2Z	C	######	NA	6/9/2022	BOB THOM
5/24/2022	ALEXANDE	AZ	BH	T/CD	640741	42	USA	USA	POWER ST	L68	348634A	T/B	T/J0	4.1	F	565.67	4552	2022	2021	3A674	LC2Z	A	######	NA	6/10/2022	LARRY H. M
4/13/2022	GERALD JO	GA	BH	T/CD	621189	42	USA	USA	DIESEL REP	L68	10929101	T/B	T/J0	0.9	F	250.37	3431	2022	2021	3A717	LC2Z	C	######	NA	6/11/2022	GERALD JO
4/26/2022	FREEDOM	AB	BH	T/CD	4179222	D8	CAN	CAN	L68-CHECK	L68	532770A	T/B	T/K0	3.4	F	360.814	36827	2021	2021	3A674	LC2Z	A	######	NA	6/13/2022	BIG WEST I
3/30/2022	EAN HOLDI	NM	BH	T/CD	980512	42	USA	USA	STEERING I	L68	15784804	T/B	T/J0	1.9	F	500.25	13888	2022	2021	3A674	LC2Z	A	######	NA	6/13/2022	POWER FO
5/18/2022	MIKE WHIT	ID	BH	T/CD	4655879	42	USA	USA	CUSTOMEI	L68	119527A	T/B	T/J0	1.4	F	476.69	11898	2021	2021	3A674	LC2Z	A	######	NA	6/14/2022	MIKE WHIT
5/31/2022	MOORESVI	NC	BH	T/CD	631505	D8	USA	USA	Customer s	L68	038171A	T/B	T/J0	1.1	F	261.33	6264	2022	2021	3A717	LC2Z	C	######	NA	6/14/2022	BOB GILLIN
3/31/2022	EAN HOLDI	VA	BH	T/CD	686092	42	USA	USA	CUSTOMEI	L68	413295A	T/B	T/J0	2.5	F	442.5	11300	2022	2021	3A717	LC2Z	C	######	NA	6/15/2022	PRIORITY F
4/14/2022	RUSH MED	CO	BH	T/CD	4379526	7	USA	USA	TOWED IN	L68	33320401	T/B	T/J0	1.4	F	389.59	6304	2021	2020	3A674	*	*	######	NA	6/15/2022	RUSH MED
4/5/2022	EAN HOLDI	KY	BH	T/CD	761717	1	USA	USA	Diag custor	L68	33733001	T/B	T/J0	1.6	F	200.75	15497	2022	2021	3A717	*	*	######	NA	6/16/2022	RUSH TRUC
3/18/2022	AUTONATI	TX	BH	T/CD	4672494	42	USA	USA	CUSTOMEI	L68	794358B	T/B	T/J0	3.3	F	620.1	29448	2021	2021	3A674	LC2Z	A	######	NA	6/16/2022	AUTONATI
4/7/2022	IRISH HILLS	MI	BH	T/CD	4465243	1	USA	USA	CHECK ANI	L68	2929401	T/B	T/J0	2	F	253.48	5379	2021	2020	3A717	LC2Z	C	######	NA	6/17/2022	ALBION MC
4/11/2022	PARKS FOR	FL	BH	T/CD	4388392	42	USA	USA	Customer s	L68	012981A	T/B	T/J0	3.6	F	456.26	6753	2021	2021	3A674	LC2Z	A	######	NA	6/17/2022	GERVAIS IN
4/22/2022	KARL FLAN	FL	BH	T/CD	4380741	42	USA	USA	CUSTOMEI	L68	602001	T/B	T/J0	2.7	F	389.59	13633	2021	2021	3A674	LC2Z	A	######	NA	6/21/2022	WHITEFAC
3/31/2022	RUSH MED	CO	BH	T/CD	4524211	30	USA	USA	POWER ST	L68	41726301	T/B	T/J0	1.2	F	396.28	9231	2021	2021	3A717	*	*	######	NA	6/22/2022	RUSH MED
3/23/2022	U-HAUL - S	PA	BH	T/CD	943235	D4	USA	USA	POWER ST	L68	5459861	T/B	T/J0	0.7	F	144	12019	2022	2021	3A717	LC2Z	C	######	NA	6/24/2022	U-HAUL - S
3/29/2022	SHEEHY FC	VA	BH	T/CD	810142	42	USA	USA	C/S POWEI	L68	84760901	T/B	T/J0	1.9	F	267.54	8069	2022	2021	3A717	LC2Z	C	######	NA	6/27/2022	SHEEHY FO
5/2/2022	SUSQUEHA	PA	BH	T/CD	768062	1	USA	USA	C/S BRAKE	L68	294795C	T/B	T/J0	2.7	F	486.78	14411	2022	2021	3A674	LC2Z	A	######	NA	6/29/2022	HOFFMAN
3/30/2022	UNIVERSAI	AB	BH	T/CD	717941	D8	CAN	CAN	DIAGNOSE	L68	65670601	T/B	T/J0	2.9	F	437.0858	5650	2022	2021	3A674	LC2Z	A	######	NA	6/29/2022	FAIRLEY &
4/12/2022	MANISTEE	MI	BH	T/CD	4464798	42	USA	USA	CUSTOMEI	L68	055376A	T/B	T/J0	2.2	F	250.89	21125	2021	2021	3A717	LC2Z	C	######	NA	6/29/2022	BETTEN BA
4/6/2022	EAN HOLDI	PA	BH	T/CD	744346	42	USA	USA	CUSTOMEI	L68	87770A	T/B	T/J0	1.2	F	221.1	10937	2022	2021	3A717	LC2Z	C	######	NA	6/30/2022	ALLEGHEN
4/29/2022	RANDY MA	NC	BH	T/CD	747019	D8	USA	USA	C/S THAT F	L68	3057803	T/B	T/K0	2.5	F	211.27	3050	2022	2021	3A717	LC2Z	C	######	NA	7/1/2022	BOB JOHNS
3/17/2022	LAIRD NOL	KS	BH	T/CD	5993082	D8	USA	USA	CUSTOMEI	L68	43319701	T/B	T/J0	0.6	F	694.23	32712	2021	2020	3A674	LC2Z	A	######	NA	7/1/2022	BOB ALLEN
3/21/2022	UNIVERSAI	AB	BH	T/CD	830978	42	CAN	CAN	CONCERN I	L68	84143801	T/B	T/J0	3.1	F	385.7393	7214	2022	2021	3A674	LC2Z	A	######	NA	7/5/2022	TITANIUM
5/13/2022	LES VENTE	QC	BH	T/CD	1353362	D8	CAN	USA	POWER ST	L68	70835101	T/B	T/J0	2.1	F	479.2512	5875	2022	2021	3A719	4C2Z	B	######	NA	7/7/2022	HUMBER M
4/1/2022	PENSKE TR	TX	BH	T/CD	973312	D4	USA	USA	Complaint:	L68	34314601	T/B	T/J0	3.2	F	163.8	21619	2022	2021	3A717	LC2Z	C	######	NA	7/7/2022	PENSKE TR
6/15/2022	HOPE AUT	AR	BH	T/CD	4652586	42	USA	USA	CUSTOMEI	L68	60237901	T/B	T/J0	1	F	397.7	9391	2021	2021	3A674	LC2Z	A	######	NA	7/8/2022	CRAIN FOR
6/27/2022	BIRD KULT	TX	BH	T/CD	1128829	42	USA	USA	CUSTOMEI	L68	802163A	T/B	T/J0	2.4	F	199.5	5009	2022	2021	3A719	4C2Z	B	######	NA	7/8/2022	CAVENDER
3/2/2022	FRANKFOR	KY	BH	T/CD	4867606	d8	USA	USA	C/S they lo	L68	6080171	T/B	T/J0	1.9	F	177.65	12859	2021	2021	3A717	LC2Z	C	######	NA	7/11/2022	LAKE POW
5/5/2022	PENSKE TR	TX	BH	T/CD	805199	D4	USA	USA	Complaint:	L68	34293701	T/B	T/J0	1.9	F	317.4	23659	2022	2021	3A674	LC2Z	A	######	NA	7/13/2022	PENSKE TR
3/31/2022	EAN HOLDI	PA	BH	T/CD	853808	42	USA	USA	TOW IN C/	L68	295839C	T/B	T/J0	2.5	F	508.73	22455	2022	2021	3A674	LC2Z	A	######	NA	7/18/2022	HOFFMAN
6/13/2022	MARCOTTE	MA	BH	T/CD	4746505	42	USA	USA	CUST STAT	L68	766113B	T/B	T/J0	2.3	F	237.1	8056	2021	2021	3A719	4C2Z	B	######	NA	7/18/2022	MARCOTTE
6/3/2022	BLUEBONN	TX	BH	T/CD	818516	D1	USA	USA	LOOSE P/S	L68	39662901	T/B	T/J0	2	F	232.05	3815	2022	2021	3A717	LC2Z	C	######	NA	7/18/2022	HILBISH MC
5/7/2022	LITHIA FOR	MT	BH	T/CD	1097261	1	USA	USA	CUSTOMEI	L68	568589A	T/B	T/J0	5	F	534.41	34285	2022	2021	3A674	LC2Z	A	######	NA	7/18/2022	LITHIA FOR
6/30/2022	U-HAUL - S	PA	BH	T/CD	4793460	D4	USA	USA	POWER ST	L68	5464861	T/B	T/J0	0.7	F	144	26122	2021	2021	3A717	LC2Z	C	######	NA	7/18/2022	U-HAUL - S
6/15/2022	RUSH MED	CO	BH	T/CD	4995048	42	USA	USA	MISC Diagr	L68	3880202	T/B	T/J0	1	F	443.14	5473	2021	2021	3A674	LC2Z	A	######	NA	7/19/2022	HERITAGE
6/27/2022	RANDY MA	NC	BH	T/CD	881741	42	USA	USA	Customer s	L68	7136151	T/B	T/K0	1.8	F	278.32	1857	2022	2021	3A717	LC2Z	C	######	NA	7/20/2022	JC LEWIS FI
4/26/2022	BRADLEY F	AZ	BH	T/CD	4831085	D8	USA	USA	ELECTRICA	L68	5460501	T/B	T/J0	1.8	F	253.02	11510	2021	2021	3A674	LC2Z	A	######	NA	7/20/2022	BRADLEY F
4/20/2022	COUGHLIN	OH	BH	T/CD	874828	7	USA	USA	POWER ST	L68	77420101	T/B	T/J0	1.2	F	214.11	2945	2022	2021	3A717	*	*	######	NA	7/21/2022	RUSH MED
5/3/2022	FRIENDLY I	NV	BH	T/CD	920764	1	USA	USA	Customer s	L68	019294A	T/B	T/J0	3	F	474.99	16800	2022	2021	3A674	LC2Z	A	######	NA	7/25/2022	GREEN COU
4/4/2022	ZEIGLER FC	IN	BH	T/CD	951426	42	USA	USA	STEERING I	L68	145033C	T/B	T/J0	3	F	247.97	18921	2022	2021	3A717	LC2Z	C	######	NA	7/26/2022	FREEWAY F
5/2/2022	MIDWAY F	MO	BH	T/CD	4993759	D8	USA	USA	CUSTOMEI	L68	3787241	T/B	T/J0	4.1	F	411.18	1921	2021	2020	3A717	LC2Z	C	######	NA	7/26/2022	MIDWAY F
4/21/2022	SHEEHY FC	VA	BH	T/CD	5280236	30	USA	CAN	SUSPENSIC	L68	83889403	T/B	T/J0	4	F	574.26	36982	2021	2020	3A674	LC2Z	A	######	NA	7/28/2022	RICH FORD
3/4/2022	RUSH MED	CO	BH	T/CD	4959497	1	USA	USA	CUSTOMEI	L68	87379501	T/B	T/J0	0	F	0	15922	2021	2021	3A717	LC2Z	C	######	NA	7/28/2022	RUSH MED
6/20/2022	ALL-STATE	KY	BH	T/CD	4862758	D8	USA	USA	COMPRESS	L68	13138601	T/B	T/J0	2.5	F	394.84	34211	2021	2021	3A674	LC2Z	A	######	NA	7/29/2022	ALL-STATE
4/7/2022	LOVELAND	CO	BH	T/CD	5514895	D4	USA	USA	CUSTOMEI	L68	2503901	T/B	T/J0	1.4	F	139.82	12360	2021	2021	3A717	LC2Z	C	######	NA	8/1/2022	KEN GARFF

RQ24-003 000199 RC

4/1/2022	UNIVERSAI	AB		BH	T/CD	936684	1	CAN	CAN	CLIENT STA	L68	793775B	T/B	T/K0	1.4	F	191.9768	14230	2022	2021	3A717	LC2Z	C	######	NA	8/3/2022	UNIVERSAL
4/1/2022	PENSKE TR	TX		BH	T/CD	1214276	D4	USA	USA	Complaint:	L68	34339301	T/B	T/J0	5.2	F	221.52	22932	2022	2021	3A674	LC2Z	A	######	NA	8/8/2022	PENSKE TR
8/4/2022	CRUISE AN	IL		BH	T/CD	5008369	42	USA	USA	GUEST STA	L68	190346A	T/B	T/J0	0.9	F	102.34	35148	2021	2021	3A717	LC2Z	C	######	NA	8/8/2022	ED MORSE
6/9/2022	ELITE FORI	QC		BH	T/CD	5053305	42	CAN	USA	REPORTS P	L68	364316A	T/B	T/J0	1.7	F	113.1026	15796	2021	2021	3A717	LC2Z	C	######	NA	8/8/2022	TAYLOR FO
4/12/2022	PENSKE TR	TX		BH	T/CD	1266893	D4	USA	USA	Complaint:	L68	34343201	T/B	T/J0	4.1	F	250.2	25387	2022	2021	3A674	LC2Z	A	######	NA	8/11/2022	PENSKE TR
3/28/2022	EAN HOLDI	MA		BH	T/CD	1058090	D4	USA	USA	TOW IN ST	L68	113239A	T/B	T/J0	1.6	F	155.28	32210	2022	2021	3A717	LC2Z	C	######	NA	8/12/2022	RODMAN F
4/14/2022	MULLINAX	WA		BH	T/CD	1186502	42	USA	USA	CUSTOMEI	L68	17462901	T/B	T/J0	3	F	347.54	19490	2022	2021	3A674	LC2Z	A	######	NA	8/15/2022	TITUS-WILL
5/17/2022	ALL ROADS	MD	N	BH	T/CD	5129757	X2	USA	USA	TOWED IN	L68	319633E	T/B	T/J0	3.7	F	163.78	3758	2021	2021	2005	LC2Z	B	######	NA	8/15/2022	PRESTON F
4/14/2022	PENSKE TR	TX		BH	T/CD	1168087	D4	USA	USA	Complaint:	L68	34335001	T/B	T/J0	5.2	F	241.32	23022	2022	2021	3A674	LC2Z	A	######	NA	8/16/2022	PENSKE TR
2/22/2022	EL MONTE	CA		BH	T/CD	5770092	42	USA	USA	Tow to sho	L68	500802	T/B	T/J0	3.2	F	310.48	34756	2021	2021	3A674	LC2Z	A	######	NA	8/17/2022	DESOTO FC
4/22/2022	EAN HOLDI	PA		BH	T/CD	1087434	42	USA	USA	CUSTOMEI	L68	88172A	T/B	T/J0	2.1	F	112.72	12404	2022	2021	3A717	LC2Z	C	######	NA	8/19/2022	ALLEGHEN
8/23/2022	PERFORMA	UT		BH	T/CD	5460161	D4	USA	USA	Customer S	L68	9465751	T/B	T/J0	1.7	F	38.42	13988	2021	2021	3A719	4C2Z	B	######	NA	8/23/2022	PERFORMA
3/1/2022	PENSKE TR	TX		BH	T/CD	1134676	D4	USA	USA	Complaint:	L68	34328901	T/B	T/J0	2.9	F	67.92	35523	2022	2021	3A717	LC2Z	C	######	NA	8/24/2022	PENSKE TR
4/12/2022	PENSKE TR	TX		BH	T/CD	1331489	42	USA	USA	VEHICLE H	L68	046072A	T/B	T/J0	2.4	F	343.4	34425	2022	2021	3A674	LC2Z	A	######	NA	8/25/2022	ALL ROADS
4/20/2022	EAN HOLDI	MO		BH	T/CD	1210681	1	USA	USA	Customer S	L68	45707401	T/B	T/J0	2	F	281.24	18941	2022	2021	3A717	LC3Z	J	######	NA	8/25/2022	JOE MACHI
3/24/2022	RAYSTOWI	PA		BH	T/CD	5467964	D8	USA	USA	Customer S	L68	023721A	T/B	T/J0	1.3	F	126.47	1402	2021	2021	3A717	LC2Z	C	######	NA	8/26/2022	STUCKEY F
2/28/2022	PENSKE TR	TX		BH	T/CD	1286533	D4	USA	USA	Complaint:	L68	34338701	T/B	T/J0	5.2	F	241.32	30600	2022	2021	3A674	LC2Z	A	######	NA	8/29/2022	PENSKE TR
8/15/2022	CRUISE AN	IL		BH	T/CD	1196010	1	USA	USA	C/S POWEI	L68	12839701	T/B	T/J0	1	F	121.49	20454	2022	2021	3A717	LC2Z	C	######	NA	8/29/2022	PERFORMA
3/30/2022	EAN HOLDI	KY		BH	T/CD	1518557	1	USA	USA	Perform di	L68	35169101	T/B	T/J0	2.3	F	129.67	15380	2022	2021	3A717	*	*	######	NA	9/1/2022	RUSH TRUC
8/4/2022	CRUISE AN	IL		BH	T/CD	1288375	D1	USA	USA	EXPRESS A	L68	114221	T/B	T/J0	1.2	F	111.19	21498	2022	2021	3A717	LC2Z	C	######	NA	9/1/2022	BAYSHORE
4/22/2022	SHEEHY FO	VA		BH	T/CD	5939239	42	USA	USA	CUSTOMEI	L68	71611	T/B	T/J0	4	F	310.48	10619	2021	2020	3A674	LC2Z	A	######	NA	9/6/2022	MINUTEM/
9/6/2022	FRANK FLE	MO		BH	T/CD	5455930	42	USA	USA	CUST STAT	L68	236879A	T/B	T/J0	2.8	F	120.18	20283	2021	2021	3A717	LC2Z	C	######	NA	9/6/2022	FRANK FLE
3/24/2022	EL MONTE	CA		BH	T/CD	5426459	D8	USA	USA	CS VEHICLE	L68	42351801	T/B	T/J0	3.4	F	354.9	19763	2021	2021	3A674	*	*	######	NA	9/7/2022	RUSH TRUC
5/3/2022	BRADFORD	PA		BH	T/CD	1172864	42	USA	USA	CUSTOMEI	L68	61601	T/B	T/J0	1	F	121.63	11799	2022	2021	3A719	4C2Z	B	######	NA	9/8/2022	BRADFORD
8/12/2022	U-HAUL - S	PA		BH	T/CD	1243468	D8	CAN	USA	no power s	L68	77824801	T/B	T/J0	1.6	F	106.0585	14923	2022	2021	3A717	LC2Z	C	######	NA	9/8/2022	JIM KEAY F
4/4/2022	PAOLI FOR	PA		BH	T/CD	5479627	42	USA	USA	CUSTOMEI	L68	1324231	T/B	T/J0	1.5	F	140.56	3265	2021	2021	3A717	LC2Z	C	######	NA	9/10/2022	PAOLI FOR
8/12/2022	U-HAUL - S	PA		BH	T/CD	1369902	16	USA	USA	NO POWEI	L68	5568491	T/B	T/J0	0	F	476.03	27678	2022	2021	3A717	*	*	######	NA	9/14/2022	U-HAUL - S
4/20/2022	WHITED FC	ME		BH	T/CD	1752126	1	USA	USA	VEHICLE TC	L68	236981A	T/B	T/J0	2	F	111.99	7501	2022	2021	3A717	LC2Z	C	######	NA	9/15/2022	RAY HASKE
5/3/2022	SUNSET AL	MO		BH	T/CD	1553945	42	USA	USA	CUSTOMEI	L68	72460701	T/B	T/J0	0	F	0	8000	2022	2021	3A674	LC2Z	A	######	NA	9/16/2022	SUNSET AL
8/12/2022	U-HAUL - S	PA		BH	T/CD	1402189	D4	USA	USA	NO POWEI	L68	5570381	T/B	T/J0	0	F	221.52	19090	2022	2021	3A717	LC2Z	C	######	NA	9/21/2022	U-HAUL - S
6/22/2022	PENSKE TR	TX		BH	T/CD	1360056	D4	USA	USA	Complaint:	L68	34347701	T/B	T/J0	5	F	241.32	15806	2022	2021	3A674	LC2Z	A	######	NA	9/26/2022	PENSKE TR
8/12/2022	U-HAUL - S	PA		BH	T/CD	1375186	D8	USA	USA	HEAVY LIN	L68	265901	T/B	T/J0	3.3	F	441.05	35367	2022	2021	3A674	LC2Z	A	######	NA	9/26/2022	BABBITT FC
5/16/2022	SIGNATURI	MI		BH	T/CD	1417617	42	USA	USA	CHECK AN	L68	3142401	T/B	T/J0	2	F	416.48	6533	2022	2021	3A674	LC2Z	A	######	NA	9/27/2022	ALBION MC
8/4/2022	CRUISE AN	IL		BH	T/CD	6053460	42	USA	USA	ACCESSOR	L68	813506	T/B	T/J0	3.8	F	410.01	18543	2021	2021	3A674	LC2Z	A	######	NA	9/29/2022	AUTO PARI
10/3/2022	O. C. WELC	SC		BH	T/CD	5740739	D1	USA	USA	CUSTOMEI	L68	2489953	T/B	T/J0	2.1	F	589.8	5381	2021	2020	2005	LC2Z	B	######	NA	10/3/2022	O. C. WELC
8/12/2022	U-HAUL - S	PA		BH	T/CD	1497127	D4	USA	USA	NO POWEI	L68	5577911	T/B	T/J0	0	F	356.52	27724	2022	2021	3A717	LC2Z	C	######	NA	10/3/2022	U-HAUL - S
5/23/2022	RANDY MA	NC		BH	T/CD	6468971	42	USA	USA	C/S BRAKE	L68	11737601	T/B	T/K0	2.5	F	193.48	3132	2021	2021	3A717	LC2Z	C	######	NA	10/10/2022	PARKS FOR
5/11/2022	ANDY MOI	IN		BH	T/CD	5834423	42	USA	USA	CUSTOMEI	L68	13766001	T/B	T/J0	0.7	F	158.56	16844	2021	2021	3A719	4C2Z	B	######	NA	10/10/2022	KEN WILSC
3/11/2022	RUSH TRUC	CA		BH	T/CD	6322831	D8	USA	USA	DURING IN	L68	21825002	T/B	T/J0	3	F	121.63	33356	2021	2020	3A717	*	*	######	NA	10/14/2022	RUSH TRUC
8/12/2022	U-HAUL - S	PA		BH	T/CD	6162172	D4	USA	USA	NO POWEI	L68	5576981	T/B	T/J0	1.9	F	243.06	30793	2021	2021	3A717	LC2Z	C	######	NA	10/18/2022	U-HAUL - S
8/12/2022	U-HAUL - S	PA		BH	T/CD	1473864	D8	USA	USA	CUSTOMEI	L68	910773A	T/B	T/J0	1.6	F	151.41	31038	2022	2021	3A717	LC2Z	C	######	NA	10/18/2022	TASCA FOR
8/17/2022	FUTURE FC	CA		BH	T/CD	1465425	D8	USA	USA	CUST STAT	L68	279477A	T/B	T/J0	0	F	0	5357	2022	2021	3A717	*	*	######	NA	10/19/2022	FUTURE FC
8/12/2022	U-HAUL - S	PA		BH	T/CD	1963434	D4	USA	USA	POWER ST	L68	5591711	T/B	T/J0	0.7	F	89.46	19283	2022	2021	3A717	LC2Z	C	######	NA	11/3/2022	U-HAUL - S
6/13/2022	CHARTRAN	QC		BH	T/CD	1684611	D8	CAN	CAN	VERRIFIER	L68	238239A	T/B	T/K0	2.5	F	105.9516	23298	2022	2021	3A717	LC2Z	C	######	NA	11/4/2022	DERAGON
4/11/2022	MID-TOWI	MB		BH	T/CD	1760794	D8	CAN	CAN	VEHICLE AI	L68	472057A	T/B	T/K0	3.2	F	133.1665	16163	2022	2021	3A717	LC2Z	C	######	NA	11/7/2022	MID-TOWI
7/29/2022	MANDERB/	PA		BH	T/CD	6399935	X2	USA	USA	CUSTOMEI	H50	3774501	T/B	T/J0	1.5	F	132.02	20271	2021	2021	3A717	LC2Z	C	######	NA	11/8/2022	GALPIN FO
8/12/2022	U-HAUL - S	PA		BH	T/CD	1899049	D4	USA	USA	LARGE PO\	L68	5594501	T/B	T/J0	0	F	67.92	35523	2022	2021	3A717	LC2Z	C	######	NA	11/9/2022	U-HAUL - S
3/24/2022	PERFORMA	UT		BH	T/CD	6171635	1	USA	USA	CUSTOMEI	L68	234189A	T/B	T/J0	1.3	F	111.11	21481	2021	2021	3A717	LC2Z	C	######	NA	11/10/2022	STEVENS F
10/5/2022	SUNSHINE	NY		BH	T/CD	6307835	42	USA	USA	VEHICLE TC	L68	26140501	T/B	T/J0	1.5	F	278.27	18045	2021	2020	3A717	LC2Z	D	######	NA	11/11/2022	SUNSHINE
5/11/2022	FUTURE FC	CA		BH	T/CD	6373876	D8	USA	USA	TOWED IN	L68	284023A	T/B	T/J0	4.2	F	134.94	8902	2021	2021	3A717	LC2Z	C	######	NA	11/21/2022	FUTURE FC
8/12/2022	U-HAUL - S	PA		BH	T/CD	1835252	61	USA	USA	CUST. STA	L68	289239A	T/B	T/J0	3	F	411.84	23908	2022	2021	3A674	LC2Z	A	######	NA	11/23/2022	SOUTHWO
6/22/2022	ELITE FORI	QC		BH	T/CD	1872869	D8	CAN	CAN	VERF CAIO	L68	501533A	T/B	T/K0	2.1	F	99.1899	25250	2022	2021	3A717	LC2Z	C	######	NA	11/29/2022	CHARTRAN
3/28/2022	FORRESTEI	PA		BH	T/CD	1863365	D4	USA	USA	pwr steerir	L68	57726B	T/B	T/J0	1.8	F	137.58	17564	2022	2021	3A717	LC2Z	C	######	NA	12/2/2022	FORRESTEF
8/4/2022	CRUISE AN	IL		BH	T/CD	6631788	42	USA	USA	CUSTOMEI	L68	424005A	T/B	T/J0	1.5	F	152.24	21000	2021	2021	3A717	LC2Z	C	######	NA	12/2/2022	ROBERT HC
3/24/2022	ENTERPRIS	VA		BH	T/CD	2028605	D4	USA	USA	CUSTOMEI	L68	756457A	T/B	T/J0	1.4	F	98.53	24624	2022	2021	3A717	LC2Z	C	######	NA	12/8/2022	MOTOR MI
8/12/2022	U-HAUL - S	PA		BH	T/CD	6559330	16	USA	USA	NO POWEI	L68	5598161	T/B	T/J0	0	F	1301.8	26983	2021	2021	3A717	*	*	######	NA	12/11/2022	U-HAUL - S

RQ24-003 000200 RC

8/12/2022	U-HAUL - S	PA	BH	T/CD	6769829	16	USA	USA	POWER ST	L68	5606951	T/B	T/J0	0	F	115.2	30564	2021	2021	3A719	LC2Z	B	######	NA	12/13/2022	U-HAUL - S
6/16/2022	JORDAN FC	IN	BH	T/CD	1979273	42	USA	USA	Customer s	L68	011543A	T/B	T/J0	1.4	F	125.51	5784	2022	2021	3A717	LC2Z	C	######	NA	12/19/2022	BUCKEYE F
7/25/2022	BILL KNIGH	OK	BH	T/CD	6833488	42	USA	USA	POWER ST	L68	79286605	T/B	T/K0	1.6	F	301.71	30704	2021	2020	3A674	LC2Z	A	######	NA	12/21/2022	KEN GARFF
8/12/2022	U-HAUL - S	PA	BH	T/CD	6746244	16	USA	USA	POWER ST	L68	5605551	T/B	T/J0	0.7	F	71.28	32050	2021	2021	3A717	BC2Z	E	######	NA	12/22/2022	U-HAUL - S
8/12/2022	U-HAUL - S	PA	BH	T/CD	2077078	16	USA	USA	NO POWEF	L68	5605461	T/B	T/J0	0	F	402.19	28240	2022	2021	3A717	*	*	######	NA	12/22/2022	U-HAUL - S
8/12/2022	U-HAUL - S	PA	BH	T/CD	6885561	D4	USA	USA	POWER ST	L68	5607911	T/B	T/J0	0.7	F	67.92	28258	2021	2021	3A717	LC2Z	C	######	NA	1/6/2023	U-HAUL - S
8/1/2022	WHITE'S FC	OH	BH	T/CD	6917683	42	USA	USA	CUSTOMEI	L68	88521201	T/B	T/J0	0	F	0	3893	2021	2021	3A674	*	*	######	NA	1/11/2023	SAM GALL(
12/16/2022	TROPICAL I	FL	BH	T/CD	2414853	42	USA	USA	CUSTOMEI	L68	524068B	T/B	T/J0	3.3	F	482.8	6241	2022	2021	3A674	LC2Z	A	######	NA	1/16/2023	COGGIN FC
9/13/2022	PERFORM/	UT	BH	T/CD	7105665	42	USA	USA	cst sts brak	L63	9511691	T/B	T/J0	2.5	F	668.3	35590	2021	2021	2005	LC2Z	B	######	NA	1/19/2023	PERFORM/
5/13/2022	FUTURE FC	CA	BH	T/CD	2348590	D8	USA	USA	TOW IN - C	L68	702722A	T/B	T/J0	2	F	93.11	29557	2022	2021	3A717	LC2Z	C	######	NA	1/19/2023	FUTURE FC
4/14/2022	BUCKEYE F	OH	BH	T/CD	2737457	42	USA	USA	CUSTOMEI	H50	687891A	T/B	T/J0	6.4	F	625.55	15191	2022	2021	3A674	LC2Z	A	######	NA	2/7/2023	DAVE ARB(
4/18/2022	IMLAY CITY	MI	BH	T/CD	2417830	1	USA	USA	FRONT SUS	L68	1625901	T/B	T/J0	1.5	F	118.75	16395	2022	2021	3A719	4C2Z	B	######	NA	2/8/2023	FRED GRAI
3/17/2022	TOM'S TRU	CA	BH	T/CD	2493662	D8	USA	USA	TRANSMIS	L68	662701	T/B	T/J0	1	F	374.24	23640	2022	2021	3A674	LC2Z	A	######	NA	2/9/2023	BABBITT FC
8/8/2022	CAMBRIAN	ON	BH	T/CA	2819102	D8	CAN	CAN	inspect for	L68	49363705	T/B	T/K0	1.5	F	200.7533	29060	2022	2021	3A717	LC2Z	D	######	NA	3/2/2023	CAMBRIAN
10/3/2022	MARSHALL	KY	BH	T/CD	7879106	1	USA	USA	CUSTOMEI	L68	104454A	T/B	T/J0	1.9	F	234.75	2279	2021	2021	3A717	LC2Z	C	######	NA	3/2/2023	MARSHALL
4/26/2022	SHEPARD E	NY	BH	T/CD	2723583	D8	USA	USA	CK OVER FI	L68	37461901	T/B	T/J0	3	F	198.04	29506	2022	2021	3A717	4C2Z	A	######	NA	3/6/2023	SHEPARD E
3/9/2023	ORCHARD	BC	BH	T/CD	7531715	D8	CAN	CAN	DIAGNOSE	L68	53212505	T/B	T/K0	4	F	232.9135	32652	2021	2021	3A674	LC2Z	A	######	NA	3/9/2023	ORCHARD
8/23/2022	FREMONT	WY	BH	T/CD	7495297	42	USA	USA	CUSTOMEI	L68	63991501	T/B	T/J0	2.5	F	386.87	6687	2021	2021	3A674	LC2Z	A	######	NA	3/9/2023	SANDERSO
4/1/2022	BILL MACD	MI	BH	T/CD	7520170	1	USA	USA	CUSTOMEI	L68	2004601	T/B	T/J0	1.5	F	378.38	13183	2021	2021	3A717	LC2Z	C	######	NA	3/13/2023	LANCE CUI
4/5/2022	BILL MACD	MI	BH	T/CD	2961040	42	USA	USA	*SUSPENSI	L68	2300601	T/B	T/J0	0.4	F	107.05	6377	2022	2021	3A717	LC2Z	C	######	NA	3/14/2023	ED CORLEY
2/25/2022	RON TIRAP	IL	BH	T/CD	7518299	42	USA	USA	Customer S	L68	1499251	T/B	T/J0	2.2	F	139	18518	2021	2021	3A719	4C2Z	B	######	NA	3/15/2023	RON TIRAP
5/11/2022	FRANKFOR	KY	BH	T/CD	3058786	42	USA	USA	C/S HOSE E	L68	1918901	T/B	T/J0	1.9	F	310.76	2189	2022	2021	3A674	LC2Z	A	######	NA	4/4/2023	FRANKFOR
12/7/2022	ANDY MOH	IN	BH	T/CD	7874551	42	USA	USA	STEERING \	L68	64761	T/B	T/J0	1.5	F	143.69	13166	2021	2021	3A717	LC2Z	C	######	NA	4/4/2023	PEACH STA
4/11/2022	PENSKE TR	TX	BH	T/CD	3257632	D4	USA	USA	Complaint:	L68	34436401	T/B	T/J0	4.3	F	359.64	36000	2022	2021	3A674	LC2Z	A	######	NA	4/5/2023	PENSKE TR
4/27/2022	U-HAUL - S	PA	BH	T/CD	7881141	D4	USA	USA	POWER ST	L68	5671001	T/B	T/J0	0.7	F	67.92	34464	2021	2021	3A717	LC2Z	C	######	NA	4/7/2023	U-HAUL - S
4/13/2022	ROGER SHI	SC	BH	T/CD	7925904	42	USA	USA	TOWED IN	L68	206181A	T/B	T/J0	2.4	F	297.44	5350	2021	2021	3A674	LC2Z	A	######	NA	4/11/2023	LARRY H. M
4/6/2022	CHAMPION	PA	BH	T/CD	8101172	D8	USA	USA	CUSTOMEI	L68	929177A	T/B	T/J0	5.5	F	405.98	30510	2021	2021	3A674	LC2Z	A	######	NA	4/21/2023	LIBERTY FC
8/5/2022	CRUISE AM	IL	BH	T/CD	3362817	1	USA	USA	CUST STAT	L68	197568A	T/B	T/J0	3.5	F	517.49	20971	2022	2021	3A717	LC2Z	C	######	NA	4/21/2023	MID-TENN
8/2/2022	FUTURE FC	CA	BH	T/CD	3194326	D8	USA	USA	STEERING (	L68	15898402	T/B	T/J0	1.2	F	131.99	7378	2022	2021	3A717	LC2Z	C	######	NA	4/24/2023	ANDERSOI
8/23/2022	RIVERTOW	GA	BH	T/CD	8440847	42	USA	USA	CUSTOMEI	L68	855235A	T/B	T/J0	4.1	F	332.15	12773	2021	2021	3A674	LC2Z	A	######	NA	5/12/2023	RIVERTOW
3/3/2022	ROAD BEAI	CA	BH	T/CD	8628452	D8	USA	USA	C.S. WAS H	L68	621452A	T/B	T/J0	2.4	F	404.94	23652	2021	2021	3A674	LC2Z	A	######	NA	5/15/2023	PEORIA FO
1/19/2023	ALL WORLI	WI	BH	T/CD	8312000	42	USA	USA	CUSTOMEI	L68	063906A	T/B	T/K0	3.2	F	367.33	23785	2021	2021	3A674	*	*	######	NA	5/17/2023	ALL WORLI
3/9/2022	RUSH MED	CO	BH	T/CD	8365804	42	USA	USA	CUSTOMEI	L68	5233381	T/B	T/J0	0.5	F	276.98	23934	2021	2021	3A719	LC2Z	B	######	NA	5/22/2023	ALPINE FOI
4/26/2022	LES VENTE	QC	BH	T/CD	3602171	D8	CAN	USA	LE SERVO I	L68	15618A	T/B	T/J0	2	F	119.4675	5565	2022	2021	3A717	LC2Z	C	######	NA	5/24/2023	ELITE FORI
4/11/2022	CURRIE MC	IN	BH	T/CD	3615498	42	USA	USA	C/S POWEI	L68	634210A	T/B	T/J0	2	F	362.63	6765	2022	2021	3A674	LC2Z	A	######	NA	5/25/2023	DON HINDS
4/5/2022	FUTURE FC	CA	BH	T/CD	8390211	42	USA	USA	DRIVETRAI	L68	2381701	T/B	T/J0	3.5	F	392.06	16584	2021	2021	3A674	LC2Z	A	######	NA	6/1/2023	ED CORLEY
6/27/2022	CARIBOU F	ID	BH	T/CD	8715240	1	USA	USA	DIAGNOSE	L68	7479901	T/B	T/J0	2.5	F	146.99	21012	2021	2021	3A717	LC2Z	C	######	NA	6/5/2023	CARIBOU F
5/3/2022	PERFORM/	UT	BH	T/CD	3814976	D4	USA	USA	Customer S	L68	9556201	T/B	T/J0	1.8	F	109.84	2209	2022	2021	3A717	LC2Z	C	######	NA	6/7/2023	PERFORM/
8/11/2022	AUTONATI	TN	BH	T/CD	3754552	42	USA	USA	FLUID LEAI	L68	8049001	T/B	T/J0	3.4	F	572.18	30773	2022	2021	3A674	LC2Z	A	######	NA	6/7/2023	GATOR FOI
4/12/2022	NICK NICHI	FL	BH	T/CD	3739875	42	USA	USA	C/S HEARD	L68	525859D	T/B	T/J0	2.5	F	574.84	8560	2022	2021	3A717	LC2Z	D	######	NA	6/12/2023	SUBURBAN
10/24/2022	TRANSWES	CA	BH	T/CD	3701683	42	USA	USA	CUSTOMEI	L68	278312	T/B	T/J0	2.5	F	142.97	14400	2022	2021	3A719	*	*	######	NA	6/12/2023	TRANSWES
4/20/2022	EARNHARI	AZ	BH	T/CD	8648252	33	USA	USA	ELECTRICA	L68	6444201	T/B	T/J0	5.8	F	531.15	6189	2021	2021	3A674	LC2Z	A	######	NA	6/12/2023	BRADLEY F
8/17/2022	CRUISE AM	IL	BH	T/CD	3806865	42	USA	USA	CUST STAT	L68	413856B	T/B	T/J0	2.5	F	159.58	23386	2022	2021	3A719	4C2Z	B	######	NA	6/13/2023	SETH WAD
4/14/2023	RUSH TRU(	CA	BH	T/CD	8569255	41	USA	USA	CUST STAT	L68	311545A	T/B	T/J0	2	F	557.6	5627	2021	2021	3A674	LC2Z	A	######	NA	6/20/2023	FUTURE FC
3/10/2022	MIDWAY F	MO	BH	T/CD	3800878	D8	USA	USA	CUSTOMEI	L68	673951	T/B	T/J0	1.3	F	146.35	5244	2022	2021	3A717	LC2Z	C	######	NA	6/22/2023	WHITEFAC
5/5/2022	WAY SCAR	WA	BH	T/CD	4805899	1	USA	USA	C/S THEY H	L68	82233301	T/B	T/J0	1	F	145.39	8360	2022	2021	3A717	LC2Z	C	######	NA	6/23/2023	O'MEARA F
4/13/2022	GATOR FOI	FL	BH	T/CD	8567542	42	USA	USA	CUSTOMEI	L68	10024301	T/B	T/J0	3.6	F	520.71	20900	2021	2021	3A674	LC2Z	A	######	NA	6/26/2023	ED MARTIN
8/15/2022	CRUISE AM	IL	BH	T/CD	4005469	42	USA	USA	Customer S	L68	5366531	T/B	T/J0	3.3	F	112.27	34288	2022	2021	3A719	4C2Z	B	######	NA	6/26/2023	LEE-SMITH
3/25/2022	LEIF JOHN	TX	BH	T/CD	3931022	42	USA	USA	CUSTOMEI	L68	820865A	T/B	T/J0	3.2	F	385.66	2890	2022	2021	3A674	LC2Z	A	######	NA	6/29/2023	LEIF JOHN
4/20/2022	BONDY'S F	AL	BH	T/CD	4037781	42	USA	USA	C/S THAT T	H20	416660A	T/B	T/J0	2	F	0	5425	2022	2021	2005	*	*	######	NA	7/3/2023	CAVENAUC
7/22/2022	GERALD JO	GA	BH	T/CD	8810839	42	USA	USA	DIESEL REP	L68	13099101	T/B	T/J0	3	F	638.11	7282	2021	2021	3A674	LC2Z	A	######	NA	7/5/2023	GERALD JO
7/21/2022	DAVE ARB(	OH	BH	T/CD	3934886	1	USA	USA	CUSTOMEI	L68	93317601	T/B	T/K0	1.8	F	144.55	24686	2022	2021	3A717	LC2Z	C	######	NA	7/6/2023	BEAU TOW
7/20/2022	RUSH MED	CO	BH	T/CD	4024443	42	USA	USA	CS/ THE M	L68	82346101	T/B	T/J0	1.8	F	682.71	3399	2022	2021	3A719	4C2Z	B	######	NA	7/10/2023	O'MEARA F
4/4/2022	BOB MOOI	OK	BH	T/CD	4006593	D8	USA	USA	Power stee	L68	16861202	T/B	T/J0	3.7	F	479.28	10731	2022	2021	3A674	LC2Z	A	######	NA	7/10/2023	MHC FORD
3/1/2022	ROAD BEAI	CA	BH	T/CD	3944911	25	USA	USA	C/S LOSS C	L68	5098501	T/B	T/J0	1	F	142.13	100	2022	2021	3A717	LC2Z	C	######	NA	7/10/2023	GALPIN FO
9/27/2022	FRIENDLY I	NY	BH	T/CD	8788827	D1	USA	USA	C/S LOSS C	L68	118459A	T/B	T/J0	2.5	F	139.12	6059	2021	2021	3A717	LC2Z	C	######	NA	7/12/2023	GABRIELLI

RQ24-003 000201 RC

3/28/2022	DEPAULA F	NY	BH	T/CD	4921547	42	USA	USA	CUSTOMEI	L68	70301801	T/B	T/J0	0	F	0	20503	2022	2021	3A719	*	*	######	NA	7/13/2023	KENDALL F
4/22/2022	GARY YEOI	FL	BH	T/CD	8790370	42	USA	USA	LOST POW	L68	1686332	T/B	T/J0	3.7	F	473.72	23711	2021	2020	3A674	LC2Z	A	######	NA	7/14/2023	MHC FORD
8/2/2022	LAFONTAI	MI	BH	T/CD	3999642	42	USA	USA	CHECK VEI	L68	321412A	T/B	T/J0	4	F	654.49	7577	2022	2021	3A674	LC2Z	A	######	NA	7/17/2023	FULLER FO
4/19/2022	HODGES F(	GA	BH	T/CD	8771866	42	CAN	USA	POWER ST	L68	61757701	T/B	T/J0	3	F	97.03774	15525	2021	2021	3A717	LC2Z	C	######	NA	7/18/2023	C.S.L. FORI
3/22/2022	KEY WEST	BC	BH	T/CD	9287034	1	CAN	CAN	CUSTOMEI	L68	52339101	T/B	T/J0	3.4	F	571.3589	22696	2021	2021	3A674	LC2Z	A	######	NA	7/21/2023	CAM CLARI
4/1/2022	GERALD JO	GA	BH	T/CD	4134235	42	USA	USA	STATES PO	L68	539687A	T/B	T/J0	1.4	F	142.59	3539	2022	2021	3A717	LC2Z	C	######	NA	7/26/2023	VIC BAILEY
4/6/2022	RAZZARI F(	CA	BH	T/CD	4147531	42	USA	USA	CUSTOMEI	L68	284082	T/B	T/J0	6	F	464.07	10123	2022	2021	3A674	LC2Z	A	######	NA	7/27/2023	TRANSWES
5/3/2022	PERFORM/	UT	BH	T/CD	9288687	42	USA	USA	C/S THE VE	L68	666005B	T/B	T/J0	7	F	447.36	20395	2021	2021	3A674	LC2Z	A	######	NA	7/27/2023	LARRY H. M
9/26/2022	PIEDMONT	NC	BH	T/CD	4157060	D8	USA	USA	C/S THE PC	L68	152831	T/B	T/J0	2.5	F	421.4	4891	2022	2021	3A674	LC2Z	A	######	NA	7/31/2023	FEYER FOR
4/18/2022	FORD FAIR	CA	BH	T/CD	9236415	D8	USA	USA	C/S THE PC	L68	666951A	T/B	T/J0	6	F	509.8	14002	2021	2020	3A674	LC2Z	A	######	NA	8/7/2023	LARRY H. M
9/28/2022	CHALMERS	NM	BH	T/CD	4593938	42	CAN	USA	Steering/S	L68	16846101	T/B	T/J0	1.8	F	100.6857	8624	2022	2021	3A717	LC2Z	C	######	NA	8/21/2023	KOCH FORI
3/22/2022	KEY WEST	BC	BH	T/CD	9250491	42	CAN	CAN	customer r	L68	11599401	T/B	T/J0	4	F	652.1181	20072	2021	2021	3A674	*	*	######	NA	8/22/2023	APPLEWOC
3/4/2022	MOUNTAIN	ID	BH	T/CD	9466424	42	USA	USA	POWER ST	L68	270467B	T/B	T/J0	0	F	0	4325	2021	2021	3A719	LC2Z	B	######	NA	8/25/2023	ONTARIO A
3/28/2022	DAVIES FO	PA	BH	T/CD	9239667	42	USA	USA	CUSTOMEI	L68	352280A	T/B	T/J0	0	F	0	13753	2021	2021	3A674	*	*	######	NA	8/25/2023	C. HARPER
8/8/2022	COGSWELL	AR	BH	T/CD	9532460	42	USA	USA	DIAGNOSIS	L68	63131302	T/B	T/J0	3.8	F	897.58	10273	2021	2021	3A717	LC2Z	C	######	NA	8/28/2023	BILL KNIGH
6/17/2022	SANDERSO	AZ	BH	T/CD	9398669	42	USA	USA	CUSTOMEI	L68	66861301	T/B	T/J0	3.1	F	622.85	16982	2021	2021	3A719	*	*	######	NA	8/28/2023	SANDERSO
5/25/2022	SANDERSO	AZ	BH	T/CD	4684168	42	USA	USA	CUSTOMEI	L68	66939001	T/B	T/J0	6.2	F	625.36	23451	2022	2021	3A674	LC2Z	A	######	NA	9/1/2023	SANDERSO
4/27/2022	RODEO FO	AZ	BH	T/CD	4565799	42	USA	USA	C/S POWEI	L68	199934A	T/B	T/J0	3.5	F	535.76	6234	2022	2021	3A717	LC2Z	C	######	NA	9/5/2023	MID-TENN
5/12/2022	ELITE FORI	QC	BH	T/CD	9403394	D8	CAN	CAN	FUITE HUII	L68	18128B	T/B	T/J0	0.9	F	112.6676	7994	2021	2020	3A717	LC2Z	C	######	NA	9/13/2023	ELITE FORI
6/14/2023	FAMILY FO	CT	BH	T/CD	4702958	42	USA	USA	ADD-ON, V	L68	404215E	T/B	T/J0	0.3	F	124.19	11847	2022	2021	3A717	LC2Z	C	######	NA	9/19/2023	FAMILY FO
3/25/2022	BIG WEST I	AB	BH	T/CD	5053497	1	CAN	CAN	H22-CHEC	L68	563303A	T/B	T/K0	5	F	591.7585	31775	2022	2021	3A674	LC2Z	A	######	NA	9/21/2023	BIG WEST I
5/10/2022	KEN GANLI	OH	BH	T/CD	9782166	D8	USA	USA	C/S POWEI	L68	671134A	T/B	T/J0	6.5	F	597.49	10990	2021	2021	3A674	LC2Z	A	######	NA	9/21/2023	LARRY H. M
4/5/2022	ST.ONGE F	QC	BH	T/CD	9465883	D8	CAN	CAN	Fuite de liq	L68	31249301	T/B	T/K0	1.3	F	90.21496	21565	2021	2020	3A717	LC2Z	C	######	NA	9/26/2023	ST.ONGE F
4/21/2022	STUCKEY F	PA	BH	T/CD	4924523	33	USA	USA	CUSTOMEI	L68	060228A	T/B	T/J0	0.9	F	178.44	11901	2022	2021	3A717	LC2Z	C	######	NA	9/26/2023	CONWAY F
10/3/2022	WATERMA	IL	BH	T/CD	9646409	D8	USA	USA	LOST POW	L68	10540901	T/B	T/J0	2.4	F	143.89	19649	2021	2021	3A717	*	*	######	NA	9/28/2023	RUSS HUBL
3/10/2022	AUBURN F(	CA	BH	T/CD	9743707	D8	USA	USA	CUSTOMEI	L68	508458A	T/B	T/J0	5.7	F	558.88	14488	2021	2021	3A719	4C2Z	B	######	NA	9/29/2023	AUBURN F(
7/15/2022	AWESOME	WA	BH	T/CD	9914981	D8	USA	USA	CUSTOMEI	L68	51421501	T/B	T/J0	1.6	F	121.67	5304	2021	2021	3A717	LC2Z	C	######	NA	10/6/2023	TITUS-WILL
8/21/2023	HAWK FOR	IL	BH	T/CD	5004568	42	USA	USA	CUSTOMEI	L68	523199A	T/B	T/J0	2.4	F	129.86	4400	2022	2021	3A717	LC2Z	C	######	NA	10/9/2023	CASTLE FO
3/20/2023	HOLT MOT	MN	BH	T/CD	9768227	D4	USA	USA	Customer s	L68	039325A	T/B	T/J0	2.4	F	145.73	35803	2021	2021	3A717	LC2Z	C	######	NA	10/11/2023	HOLT MOT
3/25/2022	FORD OF P	FL	BH	T/CD	5109547	42	USA	USA	CUSTOMEI	L68	41177401	T/B	T/J0	0	F	0	16263	2022	2021	3A717	*	*	######	NA	10/13/2023	FORD OF P
10/3/2023	GAUDIN FC	NV	BH	T/CD	5229181	D8	USA	USA	CUST STAT	L68	509565B	T/B	T/J0	3.2	F	571.72	4905	2022	2021	3A719	4C2Z	B	######	NA	10/17/2023	GAUDIN FC
10/17/2023	EVERETT FI	AR	BH	T/CD	9858407	D8	USA	USA	C/S SEEING	L68	7936804	T/B	T/J0	2	F	255.2	19505	2021	2021	3A717	4C2Z	B	######	NA	10/17/2023	EVERETT F(
9/28/2022	VIC BAILEY	SC	BH	T/CD	5209500	42	USA	USA	CUSTOMEI	L68	543834A	T/B	T/J0	1.1	F	142.22	14410	2022	2021	3A717	LC2Z	C	######	NA	10/31/2023	VIC BAILEY
4/12/2022	LOVELAND	CO	BH	T/CD	5330290	D1	USA	USA	CUSTOMEI	L68	77621A	T/B	T/J0	1.4	F	128.86	5447	2022	2021	3A717	LC2Z	C	######	NA	11/1/2023	DESTINATI(
11/10/2022	BICKFORD	WA	BH	T/CD	10090683	68	USA	USA	CUSTOMEI	L68	948646A	T/B	T/J0	0	F	0	13660	2021	2021	3A719	4C2Z	B	######	NA	11/6/2023	BICKFORD
4/11/2022	UNIVERSAI	AB	BH	T/CD	5511026	42	CAN	CAN	CUSTOMEI	L68	919376A	T/B	T/J0	1.3	F	91.2834	25491	2022	2021	3A717	LC2Z	C	######	NA	11/10/2023	WHITEHOR

RQ24-003 000202 RC

Right_Repair Dealer State	Right_Technician Comments	Right_TIS	al Cost Gross	nsaction Code	nsmission [TR]	icle Line AWS	icle Line WERS	sion/Serie s [VS/SE]	Right_VIN	ranty Start Date	Right_WCC	n Comment	TIS	Total Cost Gross	Transactio n Code	Transactio n Desc	Transmiss ion [TR]	Vehicle Line AWS	Line AWS Desc	Line WERS	eries [VS/SE]	VIN	Warranty Start Date	WCC
FL	PERFORMED VISUA	24	2517.82	E84	T/CP	E1	T/E4	T/CD	[redacted]	3/27/2020	5V07	PERFORME	24	43.2	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD	[redacted]	3/27/2020	*
CA	Power steering insp	7	582.54	E84	T/CP	E1	T/E4	T/CD		8/31/2021	5Q02	22S08 Rec	7	26.88	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		8/31/2021	*
CA	Power steering insp	12	582.54	E84	T/CP	E1	T/E4	T/DB		4/8/2021	5Q02	22S08 Rec	12	26.88	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		4/8/2021	*
PA	PRESSURE HOSE BLI	11	126.64	E84	T/CP	E1	T/E4	T/DB		4/19/2021	5Q02		11	26.86	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		4/19/2021	*
AZ	3A717 Verified cust	13	1274.45	E84	T/CP	E1	T/E4	T/DB		3/11/2021	5Q02	22S08 Rec	13	26.88	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		3/11/2021	*
TX	VERIFIED CONCERN	11	392.56	E84	T/CP	E1	T/E4	T/CD		5/1/2021	5Q02	INSPECTED	11	36.79	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		5/1/2021	*
WI	check cause for no	18	954.41	E84	T/CP	E1	T/E4	T/CD		########	5I01	recall 22s0	18	32.59	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		10/27/2020	*
PA	POWER STEERING P	14	206.68	E84	T/CP	E1	T/E4	T/DB		2/8/2021	5Q02		14	26.86	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		2/8/2021	*
NJ	VERIFIED THE CONC	11	1078.21	E84	T/CP	E1	T/E4	T/CD		5/12/2021	5I01	PERFORM	11	42	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		5/12/2021	*
PA	VERIFIED CUSTOME	12	596.3	1	T/CP	E1	T/E4	T/CD		4/23/2021	5Q02	Inspect po	12	21.36	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/23/2021	*
NJ	TECH VERIFIED NO I	15	510.31	E84	T/CP	E1	T/E4	T/CD		1/22/2021	5Q02	Inspect po	15	23.3	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		1/22/2021	*
QC	CONFIRME ANOMA	10	514.2046	1	T/CP	E1	T/E4	T/DB		6/14/2021	5Q02	RAPPEL 22	10	25.10084	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		6/14/2021	*
NE	diag power steering	10	573.65	E84	T/CP	E1	T/E4	T/CD		6/28/2021	5Q02	followed 2	10	36.36	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		6/28/2021	*
TN	CONFIRM CUSTOMI	18	532.85	E84	T/CP	E1	T/E4	T/DB		########	5Q02	passed ins	17	33.13	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		11/12/2020	*
NY	POWER STEERING L	7	437.56	E84	T/CP	E1	T/E4	T/CD		9/20/2021	5Q02	TECH VERII	7	35.78	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		9/20/2021	*
NV	INSPECTED AND FO	7	869.28	1	T/CP	E1	T/E4	T/DB		9/13/2021	5I01	22S08 Rec	6	33.5	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		9/13/2021	*
WV	verified no power st	10	276	E84	T/CP	E1	T/E4	T/CD		7/7/2021	5Q02	Inspect po	9	20.65	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		7/7/2021	*
CA	verified concern fou	13	1323.51	E84	T/CP	E1	T/E4	T/CD		3/24/2021	5I01	performed	12	46.04	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		3/24/2021	*
TX	VERIFY CONCERN. F	12	1146.97	E84	T/CP	E1	T/E4	T/CD		4/19/2021	5I01	PERFORM	12	36.09	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/19/2021	*
AL	CS HAS NO BRAKES	6	677.46	E84	T/CP	E1	T/E4	T/DB		11/1/2021	5I01	22S08 HYD	6	28.54	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		11/1/2021	*
QC	CONFIRMATION DE	11	936.6909	E84	T/CP	E1	T/E4	T/CD		6/8/2021	5I01	FAIRE LE R	10	29.65699	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		6/8/2021	*
WV	verified concern fail	15	330.65	E84	T/CP	E1	T/E4	T/CD		2/20/2021	5Q02	Inspect po	14	25.81	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		2/20/2021	*
PA	VERIFIED CONCERN	14	679.27	E84	T/CP	E1	T/E4	T/DB		3/13/2021	5Q02	Inspect po	13	21.36	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		3/13/2021	*
ON	INSPECT POWER SR	13	335.5911	E84	T/CP	E1	T/E4	T/DB		4/22/2021	5Q02	PERFORME	12	26.38297	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		4/22/2021	*
IA	4393 VERIFY CUSTO	21	426.85	E84	T/CP	E1	T/E4	T/CD		8/27/2020	5Q02	INSPECT LI	20	35.85	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		8/27/2020	*
OH	power steering line;	13	468.45	E84	T/CP	E1	T/E4	T/CD		4/27/2021	5Q02	Inspect po	12	25.19	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/27/2021	*
CA	POWER STEERING H	14	656.82	E84	T/CP	E1	T/E4	T/CD		3/3/2021	5Q02	ACCESSED,	14	63	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		3/3/2021	*
TX	Correction: REMOV	13	604.19	E84	T/CP	E1	T/E4	T/CD		4/28/2021	5Q02	PERFORME	11	27.87	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/28/2021	*
CA	CONFIRM CONCERN	17	1140.52	E84	T/CP	E1	T/E4	T/CD		########	5I01	CUSTOMEF	16	63	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		12/22/2020	*
MB	INSPECTED AND FO	12	440.398	E84	T/CP	E1	T/E4	T/DB		5/27/2021	5Q02	PERFORME	11	26.42113	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		5/27/2021	*
CA	The brake Hydroma	13	642.67	E84	T/CP	E1	T/E4	T/DB		4/13/2021	5Q02	PERFORM	13	40.38	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		4/13/2021	*
NH	VERIFEDCONCERN F	14	1185.52	E84	T/CP	E1	T/E4	T/CD		3/30/2021	5I01	Inspect po	12	24.22	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		3/30/2021	*
PA	POWER STEERING H	16	411.55	E84	T/CP	E1	T/E4	T/DB		1/25/2021	5Q02		15	26.86	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		1/25/2021	*
PA	CUSTOMER STATES	13	428.26	E84	T/CP	E1	T/E4	T/CD		4/17/2021	5Q02	Inspect po	12	31.16	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/17/2021	*
VA	verified customer c	17	910.54	E84	T/CP	E1	T/E4	T/DB		########	5I01	PERFORME	17	40.94	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		12/23/2020	*
TN	FOUND POWER STE	16	1071.68	E84	T/CP	E1	T/E4	T/CD		1/27/2021	5I01	PASSES RE	15	41.85	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		1/27/2021	*
AZ	P.S. PRESSURE HOSI	7	876.79	1	T/CP	E1	T/E4	T/DB		########	5I01	INSPECTED	6	36.18	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		10/22/2021	*
MI	Inspected and foun	13	478.49	E84	T/CP	E1	T/E4	T/DB		4/29/2021	5Q02	COMPLETE	12	42.09	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		4/29/2021	*
AZ	INSPECTED AND FO	19	884.66	E84	T/CP	E1	T/E4	T/DB		########	5I01	POWERSTE	19	35.22	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		10/28/2020	*
IL	verified diag found	14	390.66	E84	T/CP	E1	T/E4	T/DB		3/26/2021	5Q02	inspect has	14	57.78	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		3/26/2021	*
AB	REMOVED LEAKING	14	437.1239	E84	T/CP	E1	T/E4	T/DB		3/29/2021	5Q02	INSPECT P(	14	33.09891	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		3/29/2021	*
CT	Line passed recall in	16	273.54	E84	T/CP	E1	T/E4	T/CD		2/19/2021	5Q02	Inspect po	14	23.3	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		2/19/2021	*
TN	#12 WF40 VERIFIED	15	813.57	E84	T/CP	E1	T/E4	T/DB		3/22/2021	5Q02	PERFROM	14	28.68	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		3/22/2021	*
ON	VERIFY CUSTOMER	28	383.9077	E84	T/CP	E1	T/E4	T/DB		2/28/2020	5Q02	22S08A 03	26	28.24512	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		2/28/2020	*
TX	Correction: REMOV	12	832.77	E84	T/CP	E1	T/E4	T/CD		5/25/2021	5I01	PERFORME	12	27.87	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		5/25/2021	*
MO	8428 5/21/2022 WI	16	1052.77	E84	T/CP	E1	T/E4	T/DB		1/26/2021	5Q02	Inspect po	15	29.43	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		1/26/2021	*
GA	NOTE RECALL 22S08	15	425.37	E84	T/CP	E1	T/E4	T/CD		3/27/2021	5Q02	Inspect po	13	26.19	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		3/27/2021	*
GA	VERIFIED CUSTOME	15	461.63	E84	T/CP	E1	T/E4	T/CD		3/31/2021	5I01	PERFORME	13	37.2	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		3/31/2021	*
TX	REMOVE AND REPL	14	812.97	E84	T/CP	E1	T/E4	T/CD		4/26/2021	5I01	PERFORME	13	27.87	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/26/2021	*
TX	Correction: REMOV	12	302.58	E84	T/CP	E1	T/E4	T/CD		6/29/2021	5Q02	PREFORME	9	42.89	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		6/29/2021	*
MB	VERIFIED CONCERN	13	297.6918	E84	T/CP	E1	T/E4	T/DB		5/27/2021	5Q02	PERFORME	11	26.42113	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		5/27/2021	*
CO	verified the custom	15	1130.89	E84	T/CP	E1	T/E4	T/CD		3/16/2021	5I01	505 .3 22s(	14	54	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		3/16/2021	*
NY	internal defect with	14	812.47	E84	T/CP	E1	T/E4	T/CD		4/27/2021	5I01	Campaign	12	37.9	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/CD		4/27/2021	*
UT	VERIFIED CUSTOME	20	574.17	E84	T/CP	E1	T/E4	T/DB		11/4/2020	5Q02	perform In	18	37.35	22S08	HYDROBO(	T/CP	E1	ECONOLIN	T/E4	T/DB		11/4/2020	*

IN	INSPECTED VEHICLE	11	629.5	E84	T/CP	E1	T/E4	T/CD	[redacted]	7/26/2021	5I01	PASS	11	33.34	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD	[redacted]	7/26/2021	*
CT	Connector defect. R	17	327.41	E84	T/CP	E1	T/E4	T/CD		1/26/2021	5Q02	Inspect pov	15	23.3	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		1/26/2021	*
KS	POWER STEERING L	15	374.6	E84	T/CP	E1	T/E4	T/CD		4/1/2021	5Q02	ORIGINAL I	12	34.96	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/1/2021	*
TX	REMOVE AND REPL	14	812.97	E84	T/CP	E1	T/E4	T/CD		4/26/2021	5I01	PERFORME	13	29.73	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/26/2021	*
AZ	VERIFIED CUSTOME	16	831.3	E84	T/CP	E1	T/E4	T/DB		2/27/2021	5I01	performed	14	33	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		2/27/2021	*
IL	POWER STEERING P	19	476.37	E84	T/CP	E1	T/E4	T/DB		########	5Q02	22s08 has	18	56.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/16/2020	*
TX	REMOVE AND REPL	14	668.97	E84	T/CP	E1	T/E4	T/CD		4/25/2021	5I01	PERFORME	11	27.87	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/25/2021	*
QC	761 LA HOSE EST DE	16	380.1911	E84	T/CP	E1	T/E4	T/DB		3/9/2021	5Q02	761 RAPPE	13	29.73331	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/9/2021	*
TX	REMOVE AND REPL	13	832.77	E84	T/CP	E1	T/E4	T/CD		5/27/2021	5I01	PERFORME	11	27.87	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		5/27/2021	*
WI	INSPECT AND FOUN	12	388.19	1	T/CP	E1	T/E4	T/DB		6/18/2021	5Q02	PERFORME	10	38.1	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/18/2021	*
IN	DIAG, FOUND POW	12	924.73	E84	T/CP	E1	T/E4	T/DB		6/17/2021	5Q02	PERFORME	10	38.1	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/17/2021	*
CO	VERIFY CUSTOMERS	11	1173.04	1	T/CP	E1	T/E4	T/CD		8/12/2021	5I01	AFTER GAR	10	37.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		8/12/2021	*
GA	verified customer c	16	358.34	E84	T/CP	E1	T/E4	T/DB		2/19/2021	5Q02	i preforme	14	35.99	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		2/19/2021	*
AB	3A674 (D8) TECH 92	17	718.5067	E84	T/CP	E1	T/E4	T/CD		2/8/2021	5I01	PERFORME	15	33.44998	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/8/2021	*
NM	ON INSPECTION FO	16	756.52	E84	T/CP	E1	T/E4	T/CD		3/4/2021	5I01	Inspect pov	14	23.96	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/4/2021	*
ID	PERFORMED A POW	13	633.7	E84	T/CP	E1	T/E4	T/CD		6/10/2021	5I01	FSA 22S08	12	33.65	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		6/10/2021	*
OH	power steering line	7	398.2	1	T/CP	E1	T/E4	T/DB		12/2/2021	5Q02	RECALL 22S	7	41.85	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/2/2021	*
VA	CHECK NO POWER S	17	821	E84	T/CP	E1	T/E4	T/CD		2/17/2021	5Q02	Inspect pov	14	26.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/17/2021	*
CO	MT3A674 TO REPLA	25	600.81	E84	T/CP	E1	T/E4	T/DB		6/25/2020	5I01	PERFORM	22	41.52	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/25/2020	*
OH	Cause> Inspected &	18	369.91	E84	T/CP	E1	T/E4	T/CD		1/22/2021	5Q02	Inspect pov	15	23.19	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		1/22/2021	*
TX	REQUEST 3.3 HRS M	20	1078.8	E84	T/CP	E1	T/E4	T/DB		########	5I01	INSPECT PC	17	41.1	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/19/2020	*
MI	BROKEN POWER ST	13	492.84	E84	T/CP	E1	T/E4	T/DB		6/2/2021	5Q02		11	33.58	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/2/2021	*
MA	FOUND PRESSURE L	19	853.74	E84	T/CP	E1	T/E4	T/DB		########	5I01	CHECKED C	16	40.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/22/2020	*
TX	FOUND FLUID TO BI	15	733.2	E84	T/CP	E1	T/E4	T/CD		4/13/2021	5I01	recall 22o0	13	42	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/13/2021	*
CO	MT3A674 1.2 THERI	10	577.32	1	T/CP	E1	T/E4	T/CD		8/28/2021	5Q02	RECALL 22S	8	41.52	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		8/28/2021	*
PA	PRESSURE HOSE BLI	15	206.68	E84	T/CP	E1	T/E4	T/DB		4/5/2021	5Q02		12	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/5/2021	*
VA	FAILED OLD STYLE P	12	565.21	1	T/CP	E1	T/E4	T/CD		7/9/2021	5Q02	PREFORME	9	43.2	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		7/9/2021	*
PA	VERIFIED NO POWE	17	825.87	E84	T/CP	E1	T/E4	T/CD		2/17/2021	5I01	Hydroboos	15	38.3	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/17/2021	*
NS	can confirm compla	6	657.1474	1	T/CP	E1	T/E4	T/DB		1/28/2022	5I01	656237 22S	3	36.79268	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/28/2022	*
MI	CHECKED FOR NO P	19	453.09	E84	T/CP	E1	T/E4	T/DB		########	5Q02	Recall 22s0	16	28.46	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/23/2020	*
PA	CHECK CUSTOMER	16	363.22	E84	T/CP	E1	T/E4	T/CD		3/23/2021	5Q02	Inspect pov	13	22.32	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/23/2021	*
NY	Cause: VERIFIED AN	1	486.27	1	T/CP	E1	T/E4	T/CD		6/7/2022	5Q02	OLD STYLE	0	34.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		6/7/2022	*
KS	PERFORMED 22S08	29	774.47	E84	T/CP	E1	T/E4	T/CD		2/25/2020	5I01	ORIGINAL I	26	34.96	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/25/2020	*
BC	LACK OF POWER ST	14	707.5399	E84	T/CP	E1	T/E4	T/CD		5/19/2021	5I01	656237 22S	11	36.79268	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		5/19/2021	*
NL	checked power stee	5	657.6282	2	T/CP	E1	T/E4	T/CD		3/7/2022	5Q02	EFFECTUEF	3	32.74022	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/7/2022	*
TX	Correction: REMOV	14	480.95	E84	T/CP	E1	T/E4	T/CD		6/1/2021	5Q02	PERFORME	11	27.87	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		6/1/2021	*
AR	POWER STEERING L	15	544.2	E84	T/CP	E1	T/E4	T/DB		4/30/2021	5I01	PERFORME	14	27.93	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/30/2021	*
TX	VERIFY CONCERN (F	16	618.88	E84	T/CP	E1	T/E4	T/DB		3/17/2021	5Q02	Inspect pov	16	42.9	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/17/2021	*
AZ	Verified there is no	11	405.65	E84	T/CP	E1	T/E4	T/DB		8/26/2021	5Q02	PERFORME	7	31.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		8/26/2021	*
TX	Correction: REMOV	14	505.71	E84	T/CP	E1	T/E4	T/CD		6/1/2021	5I01	PERFORME	12	27.87	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		6/1/2021	*
PA	VERIFIED NO POWE	18	822.71	E84	T/CP	E1	T/E4	T/CD		2/20/2021	5I01	Inspect pov	14	21.94	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/20/2021	*
MA	VERIFIED STEERING	14	637.3	E84	T/CP	E1	T/E4	T/CD		5/26/2021	5Q02	PERFORME	13	52.2	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		5/26/2021	*
NC	VERIFY CONCERN, P	16	475.25	E84	T/CP	E1	T/E4	T/CD		3/26/2021	5Q02	COMPLETE	15	49.18	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/26/2021	*
ID	VERIFIED CUSTOME	17	1134.41	E84	T/CP	E1	T/E4	T/CD		3/12/2021	5I01	T175629 -	15	57.01	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/12/2021	*
PA	PRESSURE HOSE BLI	19	206.68	E84	T/CP	E1	T/E4	T/DB		1/4/2021	5Q02		19	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/4/2021	*
UT	found that the high	20	565.79	E84	T/CP	E1	T/E4	T/DB		########	5I01	PERFORM	19	45.26	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/14/2020	*
GA	verify concern chec	1	502.53	E84	T/CP	E1	T/E4	T/CD		7/1/2022	5Q02	PASSED INS	0	37.61	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		7/1/2022	*
AZ	No brakes. Verified	16	504.75	E84	T/CP	E1	T/E4	T/DB		4/9/2021	5I01	perform re	13	38.49	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/9/2021	*
CO	REPLACED POWER S	6	395.15	1	T/CP	E1	T/E4	T/CD		2/21/2022	5Q02	22s08 reca	2	36.9	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/21/2022	*
OK	verified customer c	16	766.32	E84	T/CP	E1	T/E4	T/DB		4/5/2021	5I01	PERFORM	14	45	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/5/2021	*
IL	VERIFIED CONCERN	17	623.12	E84	T/CP	E1	T/E4	T/CD		3/6/2021	5Q02	INSPECT AS	14	30.82	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/6/2021	*
MO	ON INSPECTION FO	13	1038.24	1	T/CP	E1	T/E4	T/DB		7/27/2021	5Q02	COMPLETE	10	42.09	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		7/27/2021	*
NM	Power steering pres	21	1116.66	E84	T/CP	E1	T/E4	T/CD		########	5I01	OPEN FIELI	18	40.29	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		11/23/2020	*
CO	WHILE THE CUSTOM	21	1549.19	E84	T/CP	E1	T/E4	T/DB		########	5Q02	RECALL 22S	16	41.52	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/18/2020	*
KY	found 2 piece high p	21	600.06	E84	T/CP	E1	T/E4	T/CD		########	5I01	22s08a pas	20	35.28	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		11/21/2020	*
CO	INSPECTED FOR LEA	17	338.62	E84	T/CP	E1	T/E4	T/DB		3/26/2021	5Q02	RECALL 22S	13	44.1	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/26/2021	*

RQ24-003 000204 RC

| | | |

PA	PRESSURE HOSE BLI	25	365.2	E84	T/CP	E1	T/E4	T/DB	[redacted]	2/7/2020	5Q02		21	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB	[redacted]	12/7/2020	*
OH	Verified no power s	6	306.11	1	T/CP	E1	T/E4	T/DB		/13/2022	5Q02	INSPECT OI	0	33.71	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		7/13/2022	*
UT	verified customer c	25	557.71	E84	T/CP	E1	T/E4	T/CD		2/8/2020	5I01	completed	20	32.79	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		12/8/2020	*
PA	PRESSURE HOSE BLI	26	133.96	E84	T/CP	E1	T/E4	T/DB		########	5Q02		21	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/23/2020	*
PA	PRESSURE HOSE BLI	22	1519.69	E84	T/CP	E1	T/E4	T/DB		/29/2021	5Q02		17	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/29/2021	*
PA	PRESSURE HOSE BLI	26	130.6	E84	T/CP	E1	T/E4	T/DB		########	5Q02		21	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/30/2020	*
FL	POWER STEERING H	25	1014.55	E84	T/CP	E1	T/E4	T/CD		/20/2021	5I01	INSPECT P(	19	26.53	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		1/20/2021	*
FL	VERIFIED COMPLAIN	14	888.47	E84	T/CP	E1	T/E4	T/DB		########	5I01	RECALL NE	13	42.49	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/10/2021	*
UT	found hydroboost l	20	1007.57	E84	T/CP	E1	T/E4	T/DB		6/1/2021	5V07	PERFORM	16	40.71	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/1/2021	*
CA	VERIFIED CONCERN	25	456.25	E84	T/CP	E1	T/E4	T/DB		/22/2021	5Q02	PERFORME	16	51.24	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/22/2021	*
OH	FOUND BOTH POW	18	1431.95	E84	T/CP	E1	T/E4	T/CD		/24/2021	5I01	inspected l	8	29.59	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		8/24/2021	*
MI	INSPECT POWER ST	15	283.77	E84	T/CP	E1	T/E4	T/DB		########	5Q02	recall perfo	6	35.48	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/17/2021	*
AZ	CONFORMED CONC	25	501.24	E84	T/CP	E1	T/E4	T/DB		/22/2021	5I01	PERFORM	14	60.3	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/22/2021	*
ON	Verified concern, in	19	360.6003	E84	T/CP	E1	T/E4	T/DB		/24/2021	5Q02	. PREF 22S(	12	29.76384	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		8/24/2021	*
KY	CUSTOMER STATES	27	435.6	E84	T/CP	E1	T/E4	T/DB		########	5Q02	INSPECT OI	22	31.71	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/22/2020	*
NY	CK VERIFY PERFORM	14	524.8	E84	T/CP	E1	T/E4	T/DB		/21/2022	5Q02	PERFORME	4	29.98	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/21/2022	*
BC	. *** 32001 MTDIA(	20	611.0821	E84	T/CP	E1	T/E4	T/DB		/10/2021	5I01	. *** 3200:	20	28.3596	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		8/10/2021	*
AZ	P.S. LINE CAME APA	17	744.37	E84	T/CP	E1	T/E4	T/DB		1/3/2021	5I01	Inspect po\	10	37.65	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/3/2021	*
TN	ONE PRESSURE LINE	18	606.59	E84	T/CP	E1	T/E4	T/DB		/24/2021	5Q02	FSA BOTH I	7	31.24	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		9/24/2021	*
NM	ADDED P/S FLUID F(	18	150.37	E84	T/CP	E1	T/E4	T/CD		/29/2021	5Q02	INSPECTED	7	31.24	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		9/29/2021	*
IL	M time no labor op	27	465.35	E84	T/CP	E1	T/E4	T/DB		1/7/2021	5Q02	Perform re	14	61.25	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/7/2021	*
KY	found p/s pressure	26	567.26	E84	T/CP	E1	T/E4	T/CD		/11/2021	5I01	PERFORME	15	31.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/11/2021	*
GA	50757 - Verified cus	25	439.19	E84	T/CP	E1	T/E4	T/DB		/16/2021	5Q02	00284515(	22	36.55	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/16/2021	*
TX	Correction: REMOV	25	785.81	E84	T/CP	E1	T/E4	T/CD		/13/2021	5I01	PERFORME	13	27.87	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/13/2021	*
PA	PRESSURE HOSE BLI	31	130.6	E84	T/CP	E1	T/E4	T/DB		########	5Q02		19	26.86	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		10/12/2020	*
AZ	INSPECTION FOUNI	21	654.56	E84	T/CP	E1	T/E4	T/DB		8/5/2021	5I01	INSPECTIO	9	28.55	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		8/5/2021	*
OH	INSPECTED FOR PO\	25	1203.48	E84	T/CP	E1	T/E4	T/DB		4/5/2021	5I01	Inspected I	13	31.4	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/5/2021	*
TN	#12 VERIFIED CUST(	22	982.29	E84	T/CP	E1	T/E4	T/DB		/20/2021	5Q02	Open field	13	15	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		7/20/2021	*
AZ	verified concern. Pe	26	280.79	E84	T/CP	E1	T/E4	T/CD		/22/2021	5Q02	RECALL 22S	17	57.08	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/22/2021	*
GA	CUSTOMER STATES	29	865.15	E84	T/CP	E1	T/E4	T/DB		/18/2021	5I01	PERFORME	20	39	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/18/2021	*
AZ	VERIFY NO P/S & NO	27	791.34	E84	T/CP	E1	T/E4	T/DB		/22/2021	5I01	22S08 Reca	12	26.88	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/22/2021	*
WI	diag found/ hydroli(	24	794.08	E84	T/CP	E1	T/E4	T/CD		/21/2021	5I01	FSA REQUI	20	40.01	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		6/21/2021	*
CO	FOUND HOSE LINE I	32	344.73	E84	T/CP	E1	T/E4	T/DB		########	5Q02	Recalls 22S	17	41.52	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		10/28/2020	*
QC	CONFIRMÉ, CONSTA	19	316.9925	E84	T/CP	E1	T/E4	T/DB		########	5Q02	PPEL 22S08	6	32.74022	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/12/2021	*
IN	VERIFIED CUSTOME	20	627.13	E84	T/CP	E1	T/E4	T/DB		0/6/2021	5I01	PERFORME	7	38.18	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		10/6/2021	*
NM	VERIFIED THE CUST(	30	792.01	E84	T/CP	E1	T/E4	T/DB		########	5I01	AS PER REC	16	57.08	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/17/2020	*
ID	Verified the custom	27	500.52	E84	T/CP	E1	T/E4	T/DB		/23/2021	5Q02	performed	16	42.42	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/23/2021	*
UT	Power steering inop	29	354.13	E84	T/CP	E1	T/E4	T/CD		2/9/2021	5Q02	COMPLETE	15	37.35	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/9/2021	*
FL	VISUALLY INSPECTE	18	1292.98	E84	T/CP	E1	T/E4	T/DB		########	5I01	COMPLETE	8	40.95	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/30/2021	*
MI	CONFIRMED CONCE	16	1156.72	E84	T/CP	E1	T/E4	T/CD		/14/2022	5Q02	VERIFIED C	1	29.02	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/14/2022	*
CA	WENT OUT TO THE	24	597.9	E84	T/CP	E1	T/E4	T/DB		/25/2021	5Q02	CONFIRME	17	40.37	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/25/2021	*
AZ	INSPECTED AND VE	25	1386.88	E84	T/CP	E1	T/E4	T/DB		/22/2021	5I01	INSPECT P(	11	38.61	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/22/2021	*
OK	INSPECT AND FOUN	24	629.58	E84	T/CP	E1	T/E4	T/CD		/14/2021	5Q02	Open field	14	15	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		7/14/2021	*
CA	TECH FOUND POWE	28	997.36	E84	T/CP	E1	T/E4	T/DB		/28/2021	5I01	PERFORME	25	48.07	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/28/2021	*
TX	VERIFIED THE CUST(	15	334.85	E84	T/CP	E1	T/E4	T/DB		/11/2022	5Q02	COMPLETE	0	42.09	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/11/2022	*
CO	CP 3A719 MO 8369	14	313.39	E84	T/CP	E1	T/E4	T/DB		/28/2022	5Q02	Campaign I	0	42.9	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/28/2022	*
IN	.HIGH PRESSURE PC	27	893.67	E84	T/CP	E1	T/E4	T/CD		4/8/2021	5I01	performed	13	49.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/8/2021	*
TN	7/3/2023 4:24:04 P!	25	561	E84	T/CP	E1	T/E4	T/CD		6/9/2021	5Q02	Open field	15	15	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		6/9/2021	*
TX	VERIFIED CUSTOME	29	1009.66	E84	T/CP	E1	T/E4	T/DB		/11/2021	5I01	PERFORME	13	43.65	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/11/2021	*
AR	FOUND LINE AT HYI	28	260	E84	T/CP	E1	T/E4	T/DB		/26/2021	5V07	22S08 HYD	14	28.54	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/26/2021	*
GA	power steering pun	31	1088.11	E84	T/CP	E1	T/E4	T/CD		########	5I01	completed	20	45	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		12/21/2020	*
OH	VERIFY CUSTOMER	22	358.75	E84	T/CP	E1	T/E4	T/CD		/30/2021	5Q02	PERFORME	10	37.8	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		9/30/2021	*
CO	CP 3A719 MO 3409	30	985.11	E84	T/CP	E1	T/E4	T/CD		/12/2021	5Q02	RECALL 22S	18	45.26	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/12/2021	*
TN	Verified complaint a	29	1030.58	E84	T/CP	E1	T/E4	T/DB		3/3/2021	5I01	PERFORME	14	35.4	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/3/2021	*
AZ	POWERSTEERING LI	24	285.59	E84	T/CP	E1	T/E4	T/DB		8/5/2021	5Q02	22S08 Reca	7	26.88	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		8/5/2021	*
CT	VERIFY CUSTOMER	32	622.1	E84	T/CP	E1	T/E4	T/DB		########	5Q02	perform 22	22	41.31	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/15/2020	*

RQ24-003 000206 RC

AK	TRAILERCRAFT FOU	30	1261.36	E84	T/CP	E1	T/E4	T/DB	[redacted]	2/1/2021	5Q02	22S08A .3	15	32.34	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB	[redacted]	2/1/2021	*
TN	INSPECTED AND VE	36	1025.02	E84	T/CP	E1	T/E4	T/DB		8/20/2020	5I01	PASSED IN	21	46.2	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		8/20/2020	*
OH	INSPECT AND FOUN	30	1161.45	E84	T/CP	E1	T/E4	T/DB		2/19/2021	5I01	22S08A .3 I	18	40.16	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		2/19/2021	*
AB	broken p/s line repl	32	329.997	E84	T/CP	E1	T/E4	T/DB		########	5Q02	22s08 reca	16	44.07	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/30/2020	*
AB	CUSTOMER CONCEI	26	972.8807	E84	T/CP	E1	T/E4	T/DB		6/4/2021	5I01	POWER STI	10	30.33622	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		6/4/2021	*
SC	VERIFIED CONCERN	29	314.79	E84	T/CP	E1	T/E4	T/DB		3/17/2021	5Q02	inspect line	13	35.99	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/17/2021	*
CA	PERFORM A VISUAL	31	1555.89	E84	T/CP	E1	T/E4	T/CD		2/1/2021	5I01	performed	15	50.22	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		2/1/2021	*
UT	VERIFIED CUSTOME	34	1454.18	E84	T/CP	E1	T/E4	T/DB		11/5/2020	5I01	COMPLETE	19	37.35	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/5/2020	*
NC	TESTED & VERIFIED	27	766.13	E84	T/CP	E1	T/E4	T/DB		5/28/2021	5I01	TECH INSPI	17	43.05	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/28/2021	*
UT	VERIFIED CUSTOME	37	1372.79	E84	T/CP	E1	T/E4	T/CD		8/22/2020	5I01	PERFORME	21	67.29	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		8/22/2020	*
AB	. INSPECTED FOR PC	28	314.5885	E84	T/CP	E1	T/E4	T/DB		5/27/2021	5Q02	PERFORME	17	39.98	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/27/2021	*
BC	VERIFIED CUSTOME	31	1021.739	E84	T/CP	E1	T/E4	T/CD		3/2/2021	5I01	POWER STI	13	30.33622	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/2/2021	*
OR	VERIFIED THE CUST	29	0	E84	T/CP	E1	T/E4	T/CD		4/17/2021	5Q02	PERFORME	11	35.72	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		4/17/2021	*
PA	CUSTOMER WAS OI	30	2853.23	E84	T/CP	E1	T/E4	T/DB		4/6/2021	5I01	INSPECTED	12	31.16	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/6/2021	*
OK	3A717 POWER STEE	35	1575.88	E84	T/CP	E1	T/E4	T/DB		########	5Q02	VERIFIED IT	22	34.5	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		10/27/2020	*
AZ	P.S. PRESSURE LINE	32	1125.05	E84	T/CP	E1	T/E4	T/DB		1/15/2021	5Q02	RECALL INS	18	42.9	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/15/2021	*
AZ	STARTED VEHICLE, I	32	1629.76	E84	T/CP	E1	T/E4	T/CD		1/29/2021	5I01	RECALL INS	17	42.9	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		1/29/2021	*
TN	#1 VERIFIED CONCE	32	1026.11	E84	T/CP	E1	T/E4	T/DB		2/12/2021	5Q02	INSPECTED	15	38.82	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		2/12/2021	*
QC	VÉRIFIER ET REMPL	17	201.5546	E84	T/CP	E1	T/E4	T/DB		5/3/2022	5Q02	FAIT RAPPE	1	27.58879	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/3/2022	*
CT	FOUND BROKEN HY	33	163.49	E84	T/CP	E1	T/E4	T/CD		1/29/2021	5Q02	PERFORME	29	39.3	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		1/29/2021	*
AB	3A674 (01) - **TECI	30	1156.707	E84	T/CP	E1	T/E4	T/DB		5/3/2021	5I01	22S08 CON	11	31.56493	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/3/2021	*
UT	VERIFIED CUSTOME	30	1532.4	E84	T/CP	E1	T/E4	T/DB		4/23/2021	5I01	LINES PASS	13	38.75	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/23/2021	*
QC	FUITE POWER STEEI	22	216.7418	E84	T/CP	E1	T/E4	T/DB		########	5Q02	rappel de f	4	27.18431	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/10/2021	*
SC	verified concern, fo	29	310.11	E84	T/CP	E1	T/E4	T/DB		5/28/2021	5Q02	PREFROME	11	32.19	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/28/2021	*
IN	3A717 FOUND POW	36	410.46	E84	T/CP	E1	T/E4	T/CD		########	5Q02	PERFORME	24	53.98	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		10/29/2020	*
CA	CUSTOMER STATES	35	1530.73	E84	T/CP	E1	T/E4	T/DB		12/3/2020	5Q02	PERFORME	16	41.79	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/3/2020	*
WA	VERIFY NO POWER	12	427.51	1	T/CP	E1	T/E4	T/DB		11/2/2022	5Q02	VEHICLE IS	0	40.26	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/2/2022	*
IN	PERFORMED INSPE(	32	530.66	E84	T/CP	E1	T/E4	T/DB		3/23/2021	5Q02	PERFORME	30	73.8	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		3/23/2021	*
MN	INSPECTED AND FO	34	420.53	E84	T/CP	E1	T/E4	T/DB		########	5Q02	CAMPAIGN	28	34.35	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		12/30/2020	*
FL	CUSTOMER HAD TC	25	671.59	E84	T/CP	E1	T/E4	T/CD		9/25/2021	5Q02	AS PER REC	7	38.25	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		9/25/2021	*
NV	DIAG POWER STEEF	21	1166.12	E84	T/CP	E1	T/E4	T/CD		1/30/2022	5Q02	INSPECT PC	21	55.73	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		1/30/2022	*
AR	FOUND HYDRAULIC	34	521.24	E84	T/CP	E1	T/E4	T/DB		1/4/2021	5Q02	22S08 BOT	34	39.91	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		1/4/2021	*
SC	VERIFIED CONCERN	32	277.52	E84	T/CP	E1	T/E4	T/CD		3/17/2021	5Q02	PERFORME	19	36.9	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/CD		3/17/2021	*
TX	VERIFIED THE CUST	31	246.19	E84	T/CP	E1	T/E4	T/DB		4/19/2021	5Q02	PERFORM	12	44.1	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		4/19/2021	*
WA	CUSTOMER REQUES	25	526.37	E84	T/CP	E1	T/E4	T/DB		########	5Q02	SAFETY REC	13	47.7	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		11/12/2021	*
YT	VERIFIED THE LEAK.	31	238.271	E84	T/CP	E1	T/E4	T/DB		5/19/2021	5Q02	656237 22	11	36.79268	22S08	HYDROBO(T/CP	E1	ECONOLIN T/E4	T/DB		5/19/2021	*