INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

SEWELL GMC

3205 W Wall St Midland TX US 79701 teamsewell.com

Customer Pay Invoice
$0.00

[redacted]

[redacted]

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2024 GMC Yukon XL-
Black
[redacted]
42,159 Mi In / 42,
Out
[redacted]

Service Advisor
[redacted]

1.	MPVI	PERFORM CERTIFIED MULTI-POINT VEHICLE INSPECTION	Internal Pay	$0.00

Job adde [redacted]

Op.1 MPVI -PERFORM CERTIFIED MULTI-POINT VEHICLE INSPECTION

1. By requesting or agreeing to a multipoint inspection, the customer acknowledges that the inspection is a visual and functional check of key vehicle components based on its condition at the time. It does not guarantee the detection of all issues or hidden defects, and results may change with time or usage. The inspection does not replace full diagnostics, and the service provider is not liable for any post-inspection failures, damages, or repair costs. This inspection report is for informational purposes only.

2.	ENGDIAG	Customer states after repairs on RO 881898, vehicle has a long extended crank. Please check and advise	Customer Pay	$0.00

Job added by Krystee Love on Tue Jan 27, 2026 | 2:24 PM

Op.1 ENGDIAG -ENGINE DIAGNOSTIC

1. Replaced starter and started vehicle. Vehicle started up immediately and no longer had an extended crank. Vehicle is operating as designed.

3.	RECOMMENDATION	Starter Replacement - The starter motor needs to be replaced as the current one is not functioning properly. Testing with another starter confirmed that the vehicle starts correctly with a working starter, ensuring reliable engine ignition.	Internal Pay	$0.00

[redacted]

Op.1 RECOMMENDATION -RECOMMENDATION

© Tekion Corp 2026