TOYOTA

**Toyota Motor Engineering &
Manufacturing North America, Inc.**

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

August 19, 2014

Ms. Nancy Lummen Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-215)
1200 New Jersey Ave, SE
Washington, D.C. 20590

Re: Recall # 14V-272
       Toyota/ Highlander and Highlander HV
       Part 573, <u>Non Compliance Information Report</u>

Dear Ms. Lewis:

In connection with the above referenced matter, this supplements Toyota's letter of May 22, 2014.

The involved vehicles VIN range and corresponding number of affected vehicles are indicated below:

<u>Identification of Involved Vehicles:</u>

Make/ Car Line	Model Year	Manufac- turer	VIN		Production Period
			VDS	VIS	
Toyota/ Highlander and Highlander HV	2014	TMMI	**RFH	ES004251-ES048817	November 20, 2013 – May 16, 2014

Note: Although the involved vehicles are within the above VIN range, not all vehicles in this range were sold in the U.S.
       No other Toyota or Lexus vehicles use the same airbag electronic control unit with incorrect software as the subject vehicles.

Total Number of Vehicles Involved:

Total: 48,840

Should you have any questions about this report, please contact me at (310) 468-8551.

Sincerely,

Abbas Saadat
Vice President
Toyota Motor Engineering & Manufacturing
North America, Inc.

cc: J. Timian