CALL (724) 658-6500 TO SCHEDULE YOUR FREE REPAIR

TOYOTA

099 *AUTO**ALL FOR AADC 150
F2R1-0000001 2-004 11/147/234
[redacted]

VIN: [redacted]

DON'T IGNORE THIS URGENT SAFETY RECALL.

Your front driver airbag may not deploy properly. This could result in underinflation of the airbag or an inflator rupture. Metal fragments from such a rupture could strike the driver or other occupants.

CONDITION

In certain 1997–1998 Model Year Supra vehicles, certain 1998–1999 Model Year Celica vehicles, certain 1998–2000 Model Year RAV4 vehicles and certain 1998–1999 Model Year RAV4 EV vehicles: The subject vehicles are equipped with a front driver airbag with an inflator made by Takata. According to information provided by Takata, the airbag may not deploy properly. This could result in underinflation of the airbag or the chance of an inflator rupture that could result in metal fragments striking the driver or other occupants. **If underinflation or inflator rupture occurs, this could increase the risk of injury or death to vehicle occupants.**

REMEDY

Any authorized Toyota dealer will inspect and, if necessary, replace the front driver airbag inflator **FREE OF CHARGE**.

DURATION

The remedy will take approximately one hour. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

SCHEDULE YOUR FREE REPAIR TODAY

Contact us at: **Preston Toyota**
1502 Wilmington Road
New Castle, PA 16105
(724) 658-6500

Or call our National Brand Engagement Center at **1-888-270-9371**.

If you are not the current owner of the vehicle, please update your records at www.toyota.com/recall/update-info-toyota.

Para español, mira el reverso.

LLAMA AL (724) 658-6500 PARA PROGRAMAR TU REPARACIÓN GRATUITA

TOYOTA

VIN: [redacted]

NO IGNORES ESTE LLAMADO A REVISIÓN URGENTE.

Es posible que la bolsa de aire delantera del conductor no se despliegue correctamente. Esto podría causar que la bolsa de aire no se infle lo suficiente o que se rompa el inflador. Esto podría provocar que fragmentos de metal golpeen al conductor u otros ocupantes.

CONDICIÓN

En ciertos modelos de vehículos Supra 1997-1998, Celica 1998-1999, RAV4 1998-2000 y RAV4 EV 1998-1999: Los vehículos indicados están equipados con una bolsa de aire delantera del conductor con un inflador fabricado por Takata. Según la información proporcionada por Takata, es posible que la bolsa de aire no se despliegue correctamente. Esto podría causar que la bolsa de aire no se infle lo suficiente o habría la posibilidad de que se rompa el inflador, lo que podría provocar que fragmentos de metal golpeen al conductor u otros ocupantes. **Si no se infla lo suficiente o se rompe el inflador, esto podría aumentar el riesgo de lesiones o muerte para los ocupantes del vehículo.**

REMEDIO

Cualquier concesionario Toyota autorizado inspeccionará y, de ser necesario, reemplazará el inflador de la bolsa de aire delantera del conductor **GRATIS**.

DURACIÓN

Remediar el problema tardará aproximadamente una hora. Sin embargo, dependiendo del horario de trabajo del concesionario, podría ser necesario que tu vehículo esté disponible por un período de tiempo más largo.

PROGRAMA TU REPARACIÓN GRATUITA HOY

Contáctanos en: **Preston Toyota**
1502 Wilmington Road
New Castle, PA 16105
(724) 658-6500

O llama a nuestro National Brand Engagement Center al **1-888-270-9371**.

Si no eres el propietario actual del vehículo, por favor, actualiza tus registros en www.toyota.com/espanol/recall/update-info-toyota.