26-01-025H - DTC P1A9096 Check for ICCU & Fuse Rep & ICCU Software Up (Recall 272) (posted 03.03.26).pdf
Recall 272 - ICCU - Dealer Notification (Remedy) (posted 03.03.2026).pdf

Hyundai Motor America (HMA) has re-launched Recall 272: DTC P19A9096 Check for ICCU & Fuse Replacement & ICCU Software Update - with the following revisions:
- TSB 26-01-025H has been revised to:
- Add additional ICCU part numbers & corresponding op codes
- Notate that ICCU 'QQH' and 'AQQH' parts may be used interchangeably until 'QQH' stock is depleted

As required by federal law, dealers must not deliver new vehicles for sale or for lease to customers until all open recalls have been performed. Dealers must perform all open recalls on used vehicles, demo, and rental vehicles prior to placing them into customer use and whenever an affected vehicle is in the shop for any maintenance or repair.

A. Campaign Document(s):

1. TSB 26-01-025H; supersedes existing TSB 24-01-068H-1
a. Available on Hyundaidealer.com > Service > HMA Tech Info > Campaign
2. Dealer Notification; supersedes existing document
Available on Hyundaidealer.com > Service > HMA Tech Info > Service News

B. Parts Information – Refer to TSB for further details.

1. Integrated Charge Control Unit (ICCU)
a. Order per normal WebDCS process.
b. VIN required to order
c. Notate that ICCU 'QQH' and 'AQQH' parts may be used interchangeably
2. No changes to ordering of the fuse or coolant.

C. Important Notes:

1. Confirm VIN eligibility for recall via WebDCS.
2. Follow TSB 26-01-025H to perform the service procedure.
3. Submit campaign claim once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.
Thank you for your patience and understanding.
Warranty Campaign Team
Hyundai Motor America