U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 25V813

Manufacturer Name: Foretravel, Inc.
Submission Date: Dec 08, 2025
NHTSA Recall No.: 25V813
Manufacturer Recall No.: 25V-813

Manufacturer Information

Manufacturer Name: Foretravel, Inc.
Address: 1221 N.W. Stallings Drive
Nacogdoches TX, 75964

Population

Total number of potentially involved: 7
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2022-2022 Foretravel Realm 450
Product Category: Buses, Medium & Heavy Vehicles
Product Type: Recreational Vehicle
Fuel / Propulsion: Compression Ignition Fuel
Production Dates: Sep 10, 2021 - Oct 11, 2021
Number of potentially involved: 3
Descriptive Information:
Villa International notified Foretravel Motor coach on 11/17/25

Vehicle 2: 2020-2022 Foretravel Realm
Product Category: Buses, Medium & Heavy Vehicles
Product Type: Recreational Vehicle
Fuel / Propulsion: Compression Ignition Fuel
Production Dates: Oct 14, 2019 - Oct 08, 2021
Number of potentially involved: 4
Descriptive Information:
Villa International notified Foretravel Motor coach on 11/17/25

Defect / Noncompliance Description

Description of the defect or noncompliance:

Part 573 Safety Recall Report 25V813

The pedestal incorrectly welded.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The pedestal incorrectly welded could fail in the event of a crash increasing the risk of injury.

Description of the cause:

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Villa International

Address: 13760 Midway Street, Cerritos, CA. 90703
4733 Eastland Drive, Elkhart, IN. 46516
Cerritos CA, 90703

Country: United States

Involved Components

Component Name 1: Seat Pedestal

Component Description: Rotating seat base

Component Part Number: 400004

Chronology

On November 17, 2025 Villa International informed Foretravel Motorcoach they had determined that certain Foretravel motor homes equipped with Villa driver and passenger seating fail to conform to Federal Motor Vehicle Safety Standard NO. 207, "seating systems"

The Villa seats affected were fabricated and delivered to Foretravel Motorcoach on or around July 27,2021 through August 18,2021. These seats were installed in Foretravel coaches numbered 7123,

Part 573 Safety Recall Report 25V813

7124, 7125,9082, 9128, 9130, 9132.

On November 21,2025 Foretravel Motorcoach decided to instigate a Safety Recall on the involved vehicles above.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

The recall remedy is to inspect for the incorrect pedestal weld of the can to the mounting plate among the vehicles determined to be affected. If the vehicle inspection reveals that a pedestal does have an improper weld, then the pedestal is required to be replaced for that seat.

How remedy component differs from recalled component:

Can to base is completely welded and not just tacked welded.

Identify how/when recall condition was corrected in production:

Foretravel uses a different seat and base assembly on production.

Reimbursement Plan

Description of reimbursement program:
Owners who have made repairs prior to recall notification of the recall may be eligible for reimbursement by contacting Foretravel Warranty and Customer assistance.
The necessary time to inspect for the defective pedestal would be less than 5 minutes.
Replacement of the pedestal will take approximately one hour labor. If replacement needed then dealer will contact Foretravel parts department at 800-955-6226, parts department will send out replacement part at no charge to dealer. Dealer performing recall will file a claim with Foretravel warranty department for labor involved and we will reimburse with credit card payment

Period of reimbursement:
Until all involved coaches are completed or declared destroyed or totaled.

Costs to be reimbursed:
Foretravel will reimburse if they desire to check or have a local shop check for the missing welds, due to the nature of the replacement process a recommended shop or dealer would have to perform replacement of the pedestal.
1 hour labor, parts shipped at no charge if part needed.
.01(6 minutes) for check

Address for reimbursement claims:

Part 573 Safety Recall Report 25V813

1221 NW Stallings Dr,
811 NW Stallings Dr.
Nacogdoches TX, 75964

Recall Schedule

Description of recall schedule:

Planned Dealer Notification Date: Nov 24, 2025 - Jan 24, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Dec 02, 2025 - Feb 02, 2026 ☐ Phased Recall

Date when VIN will be searchable: