U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26E069

Manufacturer Name: Roadmaster Inc.
Submission Date: Oct 09, 2026
NHTSA Recall No.: 26E069
Manufacturer Recall No.: 910-RPR

Manufacturer Information

Manufacturer Name: Roadmaster Inc.
Address: 6110 NE 127th Ave.
Vancouver WA, 98682

Population

Total number of potentially involved: 24,656
Estimated percentage with defect: 100%

Equipment Information

Brand / Trade 1: Roadmaster
Model: Sterling
Part Number: 576
Type:
Function / Version:
Size / Configuration:
Production Dates: Mar 18, 2022 - Sep 23, 2026
Number of potentially involved: 2,623
Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 2: Roadmaster
Model: Nighthawk
Part Number: 676
Type:
Function / Version:
Size / Configuration:
Production Dates: Mar 17, 2022 - Sep 23, 2026
Number of potentially involved: 9,638
Descriptive Information:

Part 573 Safety Recall Report 26E069

The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 3: Roadmaster

Model: Liberty

Part Number: 1776

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 27, 2026 - Sep 23, 2026

Number of potentially involved: 45

Descriptive Information:

The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 4: Roadmaster

Model: Nighthawk

Part Number: 677

Type:

Function / Version:

Size / Configuration:

Production Dates: Mar 17, 2022 - Sep 23, 2026

Number of potentially involved: 1,324

Descriptive Information:

The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 5: Roadmaster

Model: Falcon 3HD

Part Number: 627

Type:

Function / Version:

Size / Configuration:

Part 573 Safety Recall Report 26E069

Production Dates: Jan 13, 2025 - Sep 23, 2026

Number of potentially involved: 61

Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 6: Roadmaster

Model: Blackhawk All Terrain

Part Number: 427

Type:

Function / Version:

Size / Configuration:

Production Dates: Apr 08, 2022 - Sep 23, 2026

Number of potentially involved: 44

Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 7: Roadmaster

Model: Blackhawk All Terrain

Part Number: 422

Type:

Function / Version:

Size / Configuration:

Production Dates: Apr 08, 2022 - Sep 23, 2026

Number of potentially involved: 2,051

Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 8: Roadmaster

Model: Falcon 3HD

Part Number: 622

Part 573 Safety Recall Report 26E069

Type:

Function / Version:

Size / Configuration:

Production Dates: Jan 13, 2025 - Sep 23, 2026

Number of potentially involved: 1,915

Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 9: Roadmaster

Model: Falcon 2

Part Number: 525

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 16, 2022 - Sep 23, 2026

Number of potentially involved: 203

Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 10: Roadmaster

Model: Falcon All Terrain

Part Number: 522

Type:

Function / Version:

Size / Configuration:

Production Dates: Apr 21, 2022 - Sep 23, 2026

Number of potentially involved: 3,923

Descriptive Information:
The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Part 573 Safety Recall Report 26E069

Brand / Trade 11: Roadmaster

Model: Sterling

Part Number: 586

Type:

Function / Version:

Size / Configuration:

Production Dates: Mar 18, 2022 - Sep 23, 2026

Number of potentially involved: 110

Descriptive Information:

The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 12: Roadmaster

Model: Falcon All Terrain

Part Number: 527

Type:

Function / Version:

Size / Configuration:

Production Dates: Apr 21, 2022 - Sep 23, 2026

Number of potentially involved: 42

Descriptive Information:

The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Brand / Trade 13: Roadmaster

Model: Falcon 2

Part Number: 520

Type:

Function / Version:

Size / Configuration:

Production Dates: Feb 16, 2022 - Sep 23, 2026

Number of potentially involved: 2,677

Descriptive Information:

Part 573 Safety Recall Report 26E069

The recall is for all product manufactured with roll pins in the T-bolt. Redesigned version no longer utilizes roll pins.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The roll pin that secures the T-bolt portion of the stinger assembly may back out.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The tow bar may separate from the motorhome's hitch receiver, allowing the separation of the towed vehicle from the motorhome resulting in a potential crash.

Description of the cause:

Friction on the roll pin created by the rotational movement of the stinger T-bolt can cause the roll pin to migrate allowing the connecting parts to separate.

Identification of any warning that can occur:

Possible warnings:
The roll pin protrudes more than 1/16" from the retaining hole.
There is no roll pin in the retaining hole as it has already completely migrated out.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Roll Pin

Component Description: 1/4" X 1/2" HIGH CARBON SLOTTED SPRING PIN

Part 573 Safety Recall Report 26E069

Component Part Number: 200696-00

Component Name 2: Roll Pin
Component Description: 5/32" X 1" SLOTTED SPRING PIN - SPRING STEEL ZP
Component Part Number: 200697-00

Purchaser Information

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:
Address:
Country:

Chronology

7/13/2026 - Received customer notification of roll pin migration resulting in T-bolt separation.

8/7/2026 - Completed Analysis and began investigation of solution.

9/23/2026 - Completed development of solution.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair, Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

The vast majority of roll pins will not have migrated at all. For these customers, Roadmaster will provide a Security Band that encapsulates the roll pin in place so that it cannot migrate. For customers whose roll pin has already started to migrate, Roadmaster will provide a new T-bolt assembly with a corrected design.

How remedy component differs from recalled component:

If there has been no migration of the roll pin, then we are not replacing any components. Instead we are

Part 573 Safety Recall Report 26E069

anchoring the roll pin with the Security Band. For customers where the roll pin has migrated, we will replace the existing T-bolt assembly with a revised design that does not rely on a roll pin.

Identify how/when recall condition was corrected in production:

09/24/2026 - Revised T-bolt design no longer relies on a roll pin.

Reimbursement Plan

Description of reimbursement program:
Purpose: Reimburses owners who paid out-of-pocket to repair or replace certain recalled Roadmaster Inc. tow bars before receiving recall notification, provided the work addressed the recalled defect.

Affected tow bars: Nighthawk, Blackhawk All Terrain, Falcon 2, Falcon All Terrain, Falcon 3HD, Liberty, and Sterling models that use the recalled roll-pin T-bolt design.

Defect: Roll pin securing the T-bolt can loosen, allowing tow bar separation from the hitch receiver.

Reimbursement period: Begins October 2, 2025 and continues through the period required by federal recall regulations.

Eligibility requirements:

Remedy occurred during the reimbursement period.
Repair or replacement addressed the recalled defect or its symptoms.
Claimant provides required documentation.

Warranty limitation: No reimbursement if the repair/replacement would have been provided free under Roadmaster's Limited Lifetime Warranty, unless warranty coverage was denied or a warranty repair failed to correct the problem.

Reimbursement amount:

Replacement: Generally the owner's actual cost.
Repair: Eligible repair costs as allowed by federal regulations.

Required documentation:

Name and address.
Tow bar model and serial number.
Recall number (26E069 or 910-RPR).
Proof of repair/replacement and amount paid.
If applicable, proof of warranty denial or failed warranty repair.

Claim submission: Mail claim and supporting documents to Roadmaster Inc., Attn: Recall Reimbursement, 910-RPR, PO Box 823330, Vancouver, WA 98682.

Processing: Claims reviewed within 60 days; denials must include reasons; incomplete claims may be supplemented.

Other provisions: Payment by check or cash, no reimbursement for fraudulent claims, and no reimbursement obligation for equipment first purchased more than 10 years before recall notice.

Bottom line: Owners who paid to fix or replace an affected recall-related tow bar issue before recall notice may qualify for reimbursement if they submit documentation and the costs were not otherwise covered by warranty.

Period of reimbursement:

Part 573 Safety Recall Report 26E069

Reimbursement period: Begins October 2, 2025 and continues through the period required by federal recall regulations.

Costs to be reimbursed:
Reimbursement amount:

Replacement: Generally the owner's actual cost.
Repair: Eligible repair costs as allowed by federal regulations.

Address for reimbursement claims:
Roadmaster Inc., Recall Reimbursement
PO Box 823330
Vancouver WA, 98682

Recall Schedule

Description of recall schedule:

This will be a phased recall. Phase 1 is the notification via email to all consumers for which Roadmaster already has email contact information. Assuming we have received approval from NHTSA of this 573 report, this phase begins on 10/12 and ends on 10/30. Phase 2 is to notify these same customers via first class mail. This begins on 10/19 and ends on 11/6. Phase 3 is to notify all distributors and dealers. Phase 3 begins on on 10/19 and ends on 11/6. Phase 4 will be to first class mail and email additional dealers and consumers whose contact information is provided by distributors and dealers. This begins as soon as information is provided by distributors and continues as long as we are receiving contact information to submit the recall to the end consumer.

Planned Dealer Notification Date: Oct 19, 2026 - Nov 06, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Oct 12, 2026 - Dec 31, 2026 ☑ Phased Recall