U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26V720

Manufacturer Name: Wabash National Corporation

Submission Date: Oct 29, 2026

NHTSA Recall No.: 26V720

Manufacturer Recall No.:

Manufacturer Information

Manufacturer Name: Wabash National Corporation

Address: PO Box 6129
1000 Sagamore Parkway South
Lafayette IN, 47903-6129

Population

Total number of potentially involved: 14

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 WABASH STAKE TRUCK BODY

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Truck

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Apr 17, 2025 - Jun 12, 2026

Number of potentially involved: 14

Descriptive Information:

Model year 2026 Wabash Stake Bodies manufactured in the Cadiz, KY facility and mounted to a chassis in the Groveport, Ohio upfit facility.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Certain 2026 model year Wabash branded stake bodies are missing Identification light cluster required by FMVSS 108.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Part 573 Safety Recall Report 26V720

Vehicles missing identification lights are less visible from the rear and increase the risk of crash.

Description of the cause:

The manufacturing facility omitted ID lights with the expectation that the liftgate would have an ID light cluster, but the lights were not present on the liftgate.

Identification of any warning that can occur:

No center cluster ID lights.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1:

Component Description:

Component Part Number:

Chronology

Initial concern was reported from a customer that ID lights were missing on delivered units on 6/12/2026. Lights were immediately supplied and installed at no charge to the customer and installed on the 8 units in the order group. All 8 units were manufactured at the Cadiz, KY facility and mounted at the Groveport, OH upfit facility. Prior to 8/25 a photograph review of all similar stake bodies was conducted and found an additional 4 units that had not had ID lights installed at shipment. Lights were provided and installed at no charge for all vehicles found on this review. On 8/25 the product safety team decided to escalate to the product safety council. On 10/13 the product safety council determined that even though the vehicles were already repaired in the field, the vehicles did not meet FMVSS 108 at the time of shipment, so a recall must be filed.

Related NHTSA Recall Number:

Description of Remedy

Part 573 Safety Recall Report 26V720

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Install Identification Lights

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Planned Dealer Notification Date: ☐ No Dealers

Planned Interim Owner Notification Date: Dec 14, 2026 - Dec 14, 2026 ☐ No Owners

Planned Remedy Owner Notification Date: ☐ Phased Recall

Date when VIN will be searchable: