U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26V723

Manufacturer Name: Mac Trailer Mfg., Inc.
Submission Date: Oct 30, 2026
NHTSA Recall No.: 26V723
Manufacturer Recall No.:

Manufacturer Information

Manufacturer Name: Mac Trailer Mfg., Inc.
Address: 14599 Commerce Street
Alliance OH, 44601

Population

Total number of potentially involved: 60
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2027 MAC TRAILERS TRAILER
Product Category: Trailers
Product Type:
Fuel / Propulsion:
Production Dates: Jun 26, 2024 - Aug 04, 2026
Number of potentially involved: 60
Descriptive Information:
Model year 2025, 2026 and 2027 MAC Trailer LTT

Defect / Noncompliance Description

Description of the defect or noncompliance:

MAC Trailer LTT has identified 60 trailers with the model years 2025, 2026 and 2027. Trailers have missing rear under ride bumper.

FMVSS1: 223 - Rear impact guards

FMVSS2: 224 - Rear impact protection

Description of the safety risk, including crash, fire, death, injury:

Increased risk of a crash due to missing rear bumper.

Description of the cause:

Part 573 Safety Recall Report 26V723

Rear bumper missing.

Identification of any warning that can occur:

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: MAC Trailer Enterprises

Address: 14599 Commerce Street
Alliance OH, 44601

Country: United States

Involved Components

Component Name 1: Bumper

Component Description: Under ride bumper

Component Part Number:

Chronology

On 10/29/2026 MAC discovered that they had a trailer in facility that was missing the under ride bumper that qualified per the regulations for this (FMVSS 223 & 224). After checking the history of mfg. it was discovered that we have 60 trailer effected.

0 deaths, injuries, warranty claims and field service reports are associated with this recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Part 573 Safety Recall Report 26V723

Install rear under ride bumper.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

Engineered drawings and associated bill of materials updated for model.

Reimbursement Plan

Description of reimbursement program:
All effected trailers are under warranty.

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Expected to mail out notifications prior to 60 day notification requirement.

Planned Dealer Notification Date: ☑ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Dec 29, 2026 - Dec 29, 2026 ☐ Phased Recall

Date when VIN will be searchable: