U.S. Department of Transportation

**National Highway Traffic Safety Administration**

# Part 573 Safety Recall Report 26V739

**Manufacturer Name:** Shyft Group
**Submission Date:** Nov 09, 2026
**NHTSA Recall No.:** 26V739
**Manufacturer Recall No.:** 26-08

## Manufacturer Information

**Manufacturer Name:** Shyft Group
**Address:** 1541 Reynolds Road
Charlotte MI, 48813

## Population

**Total number of potentially involved:** 3,352
**Estimated percentage with defect:** 100%

## Vehicle Information

**Vehicle 1:** 2026-2026 Utilimaster Upfit
**Product Category:** Light Vehicles
**Product Type:** Light Truck
**Fuel / Propulsion:** Spark Ignition Fuel
**Production Dates:** Nov 25, 2025 - Sep 24, 2026
**Number of potentially involved:**
**Descriptive Information:**
This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 2:** 2021-2021 Utilimaster Upfit
**Product Category:** Light Vehicles
**Product Type:**
**Fuel / Propulsion:** Spark Ignition Fuel
**Production Dates:** Mar 23, 2023 - Dec 18, 2023
**Number of potentially involved:** 16
**Descriptive Information:**
This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 3:** 2022-2022 Utilimaster Upfit

# Part 573 Safety Recall Report 26V739

**Product Category:** Light Vehicles

**Product Type:** Light Truck

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Jan 22, 2023 - Jan 25, 2024

**Number of potentially involved:** 86

**Descriptive Information:**

This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 4:** 2024-2024 Utilimaster Upfit

**Product Category:** Light Vehicles

**Product Type:** Light Truck

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Jan 24, 2024 - Nov 25, 2025

**Number of potentially involved:**

**Descriptive Information:**

This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 5:** 2020-2020 Utilimaster Upfit

**Product Category:** Light Vehicles

**Product Type:** Light Truck

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Nov 15, 2023 - Nov 15, 2023

**Number of potentially involved:** 1

**Descriptive Information:**

This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 6:** 2017-2017 Utilimaster Upfit

**Product Category:** Light Vehicles

**Product Type:** Light Truck

**Fuel / Propulsion:** Spark Ignition Fuel

# Part 573 Safety Recall Report 26V739

**Production Dates:** Apr 17, 2026 - Apr 17, 2026

**Number of potentially involved:** 1

**Descriptive Information:**

This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 7:** 2023-2023 UTILIMASTER UPFIT

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Other

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Feb 28, 2023 - Sep 16, 2025

**Number of potentially involved:** 391

**Descriptive Information:**

This recall population is based on production records that indicate the required values may be missing on the required Tire and Loading Information Placard.

**Vehicle 8:** 2025-2025 UTILIMASTER UPFIT

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Other

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Jan 14, 2025 - Jan 14, 2026

**Number of potentially involved:** 2,857

**Descriptive Information:**

This recall population is based on production records that indicate the required values may be missing in the required Tire and Loading Information Placard.

## Defect / Noncompliance Description

**Description of the defect or noncompliance:**

The Tire and Loading Information Placard does not have the required combined weight information for the altered vehicles.

**FMVSS1:** 110 - Tire selection and rims

**FMVSS2:**

# Part 573 Safety Recall Report 26V739

**Description of the safety risk, including crash, fire, death, injury:**

Should a person follow the tire and loading information placard, he/she may unknowingly overload the tires on the vehicle. Overloaded tires may blow out increasing the risk of a crash.

**Description of the cause:**

Pending

**Identification of any warning that can occur:**

There are no warnings for missing information on a Tire and Loading Information Placard.

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:**

**Component Description:**

**Component Part Number:**

## Chronology

On 10/19/2026, a concern was raised to Product Safety and Compliance RE missing combined weight information on the required Tire and Loading information placard as required by FMVSS 110. An investigation ensued. A review of the affected population of altered vehicles was conducted and on 11/2/2026, Shyft determined a non-compliance could exist in the affected vehicles.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Mail Information/Labels

# Part 573 Safety Recall Report 26V739

**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside

**Description of remedy program:**

Shyft will supply new labels with the required information.

**How remedy component differs from recalled component:**

New labels will have the required information where others will not.

**Identify how/when recall condition was corrected in production:**

On 10/19/2026, Shyft corrected all labels.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

Shyft will mail new labels to the parties that have affected vehicles in their possession. We will instruct installers to install the required label in a manner consistent with the regulations.

**Planned Dealer Notification Date:** ☑ No Dealers

**Planned Interim Owner Notification Date:** ☐ No Owners

**Planned Remedy Owner Notification Date:** Dec 04, 2026 - Dec 04, 2026 ☐ Phased Recall

**Date when VIN will be searchable:**