U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26V761

Manufacturer Name: Rivian Automotive, LLC

Submission Date: Nov 19, 2026

NHTSA Recall No.: 26V761

Manufacturer Recall No.: FSAM-1900

Manufacturer Information

Manufacturer Name: Rivian Automotive, LLC

Address: 13250 North Haggerty Road
PLYMOUTH MI, 48170

Population

Total number of potentially involved: 1,619

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2027-2027 RIVIAN R2

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Electric Battery Power

Production Dates: Apr 24, 2026 - Aug 25, 2026

Number of potentially involved: 197

Descriptive Information:

The recall population includes certain Model Year 2022-2027 R1T, R1S, and R2 vehicles that may have received a tire placard label and/or certification label that did not contain updated information at the time of delivery. The suspect period began on October 18, 2021 and ended on August 25, 2026. That population was determined using manufacturing and service records.

Similar vehicles not included in this recall were labeled with correct information.

Vehicle 2: 2022-2027 RIVIAN R1S

Product Category: Light Vehicles

Product Type: Multipurpose Passenger Vehicle

Fuel / Propulsion: Electric Battery Power

Production Dates: Apr 25, 2022 - Jul 31, 2026

Number of potentially involved: 909

Descriptive Information:

The recall population includes certain Model Year 2022-2027 R1T, R1S, and R2 vehicles that may have received a tire placard label and/or certification label that did not contain updated information at the time of delivery. The suspect period began on October 18, 2021 and ended on August 25, 2026. That population was determined using manufacturing and service records.

Part 573 Safety Recall Report 26V761

Similar vehicles not included in this recall were labeled with correct information.

Vehicle 3: 2022-2027 RIVIAN R1T

Product Category: Light Vehicles

Product Type: Light Truck

Fuel / Propulsion: Electric Battery Power

Production Dates: Oct 18, 2021 - Jul 27, 2026

Number of potentially involved: 513

Descriptive Information:

The recall population includes certain Model Year 2022-2027 R1T, R1S, and R2 vehicles that may have received a tire placard label and/or certification label that did not contain updated information at the time of delivery. The suspect period began on October 18, 2021 and ended on August 25, 2026. That population was determined using manufacturing and service records.

Similar vehicles not included in this recall were labeled with correct information.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Subject vehicles are equipped with a tire placard label and/or certification label that may not correctly define the wheel, tire, and spare tire configuration that was on the vehicle at the time of first purchase due to modifications between build and delivery.

FMVSS1: 110 - Tire selection and rims

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A driver may not have accurate reference information for the size and recommended inflation pressures of the wheels and tires on their vehicle, possibly including the spare. Confusion regarding accurate tire information may increase the risk of a crash.

Description of the cause:

Identification of any warning that can occur:

Label information may be noticeably incorrect/missing.

Component Manufacturer

Part 573 Safety Recall Report 26V761

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Label
Component Description: US_CERTIFICATION_LABEL
Component Part Number: RL00000004-D

Component Name 2: Label
Component Description: US_TIRE_AND_LOADING_LABEL-MAKE
Component Part Number: RL00002368-A

Chronology

On November 13, 2026, Rivian determined that a potential noncompliance to FMVSS No. 110, Tire selection and rims, for certain vehicles cannot be ruled out. As of the date of this filing, Rivian is not aware of any accidents or injuries related to this issue in any market.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Rivian will replace the tire placard and/or certification labels with ones that contain correct tire information.

How remedy component differs from recalled component:

Part 573 Safety Recall Report 26V761

The remedy components are labels updated with correct information.

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

We will mail notifications on or before January 18, 2027.

Planned Dealer Notification Date: ☑ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Jan 18, 2027 - Jan 18, 2027 ☐ Phased Recall

Date when VIN will be searchable: Jan 18, 2027