Recall Campaign Bulletin

October 2026

TO: ALL MERCEDES-BENZ DEALERS

CAMPAIGN NO.	**2026080004**
CAMPAIGN DESC.	**29P7291007**
NHTSA ID	**26V481**
SUBJECT	**Corrosion on Door-Lock Microswitch (Wave 2)**
MODEL(S)	**C Class, GLA, GLB, GLC (206, 247, 254 platform)**
MODEL YEAR(S)	**2021 – 2026**
CAMPAIGN POPULATION	**771**

Campaign Technical Instructions

Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

1. Always check for other open campaigns and perform them accordingly!
2. Review the entire campaign bulletin first, and perform the procedures exactly as described.

Order No. P-RC-2026080004

Primary Parts Information:

Qty.	Part Name	Part Number
1	Drivers Door Lock for GLB/GLA	**A0997203702 **or** A0997201703
1	Drivers Door Lock for GLC/C	**A0997206002 **or** A0997202303
2	Countersunk bolt with hexalobular socket (door lock)	*
1	Pan head screw with hexalobular socket (door lock)	*

Please only order parts for vehicles that are "OPEN" otherwise orders may be cancelled

** The replacement parts should be determined in Xentry Parts Information using the vehicle identification number.*

*** Both part numbers will work for the replacement of the door lock. Order whichever one is available. It is possible that a door lock from "Kieckert" or "Magna" can be installed.*

Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list, but may be claimed as needed. The required small parts are taken into account in the budgeting.

Work Procedure:

1. Replace driver's door lock.
   For basic data of model 247, see AR72.10-P-4011MFC.





For basic data of model 206 or 254, see AR72.10-P-4011WT.

Warranty Information:

Note: *The following allowable labor operation should be used when submitting a warranty claim for this repair*:

Damage Code	Operation Number	Description	Labor Time (hrs.)
72-910-07	**11-0160**	Replace driver's door lock	1.2

Note: *Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change, and updates may not be reflected in this document.*