RECALL 26V610 / 2026-455 REMEDY INSTRUCTIONS

FOREST RIVER	Make(s): DYNAMAX Model(s): ISATA 5 Model Year(s): 2026 - 2027 Concern:The bunk mat may not be properly aligned with the opening.	Repair Code: RC-090-03-00-004867 Allotted Time:.0.30 HRS Inspection Code: RC-090-05-00-004866 Allotted Time:.0.10 HRS Photo(s) Required: IF ONLY INSPECTION Prior Authorization Required: NO Part(s) Kit Number: F100900070 Part(s) Return: NO

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

1. LOCATE THE BUNK MAT ABOVE THE CAB
2. PUSH ENTIRE BUNK MAT TO THE DRIVER SIDE WALL
3. INSTALL PROVIDED STILE (SEE FIGURE 1) INTO PASSENGER SIDE BUNK BASE (SEE FIGURE 2)
    a. FACE SCREW STILE INTO BUNK BASE
    b. THIS STILE IS STRICTLY TO PUSH THE BUNK MAT FLIP PORTION CORRECTLY INTO THE OPENING AND PROVIDES NO STRUCTURAL PURPOSE
4. ENSURE THAT BUNK MAT FLIP PORTION NOW SITS PROPERLY AROUND OPENING AND IS SUPPORTED ON BOTH SIDES OF THE FLIP PORTION
5. CLAIM REPAIR CODE



Figure 1

RECALL 26V610 / 2026-455 REMEDY INSTRUCTIONS

FOREST RIVER

Make(s): DYNAMAX
Model(s): ISATA 5
Model Year(s): 2026 - 2027

Concern:The bunk mat may not be properly aligned with the opening.

Repair Code: RC-090-03-00-004867
Allotted Time:.0.30 HRS
Inspection Code: RC-090-05-00-004866
Allotted Time:.0.10 HRS

Photo(s) Required: IF ONLY INSPECTION
Prior Authorization Required: NO
Part(s) Kit Number: F100900070
Part(s) Return: NO



Figure 2 - INSTALLED