[redacted]

September, 2026

* * * IMPORTANT SAFETY RECALL REMINDER * * *

According to our records, your 2026 Mustang has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **26S23 - Cylinder Inspection**

What is the issue? On your vehicle's engine, one or more of the clips that retain the engine's pistons to their connecting rods may be mis-installed or missing.

A mis-installed clip may result in an audible knocking noise that increases over time. Progression of this issue can lead to piston failure and engine damage, resulting in a loss of motive power and increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

[redacted]

Septiembre de, 2026

* * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * *

Según nuestros registros, no se realizaron en sur 2026 Mustang las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **26S23 - Inspección del cilindro**

¿Cuál es el problema? Uno o más de los clips que sostienen los pistones del motor de su vehículo a las bielas podrían estar mal instalados o faltantes.

Un clip mal instalado podría generar un ruido de golpeteo audible que aumenta con el tiempo. La evolución de este problema puede ocasionar una falla del pistón y dañar el motor, lo cual se traduce en una pérdida de la potencia motriz, lo que aumenta el riesgo de choque.

Si tiene preguntas o inquietudes, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es.ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.

© Copyright 2026 Ford Motor Company

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID

R K C

0104635 A / 000000000000042 / 42

[redacted]

SEE OTHER SIDE FOR OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

SEE OTHER SIDE FOR OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION