Internal notification for: G_0000154030 12292 - Emission Recall - Knock Sensor Wiring Harness Connections Reversed
gm_gmssg_q01

12/20/2012 05:40 AM

3 attachments

12292 bulletin.pdf 12292 Inventory VINs.xls GM Style Sheet.css

Your email client does not support HTML messages

Date: 12/20/2012 Ref. number: Service / Field Action / G_0000154030

Subject: 12292 - Emission Recall - Knock Sensor Wiring Harness Connections Reversed

GM CUSTOMER CARE AND AFTERSALES
DCS2867
URGENT - DISTRIBUTE IMMEDIATELY

Date:	December 20, 2012
Subject:	12292 - Emission Recall Knock Sensor Wiring Harness Connections Reversed
Models:	2013 Chevrolet Malibu Equipped with 2.5L Engine (LCV)
To:	All Chevrolet Dealers
Attention:	General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Emission Recall 12292 today. The total number of U.S. vehicles involved is approximately 57,000. Please see the attached bulletin for details.

Customer Letter Mailing
The customer letter mailing will begin January 3, 2013.

Global Connect (GWM)
The "Investigate Vehicle History" (IVH) screen will be updated December 20, 2012. A list of involved vehicles in dealer inventory is attached to this message.

Campaign Initiation Detail Report (CIDR)
The CIDR will be available December 20, 2012.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):