NISSAN NORTH AMERICA, INC.
Copyright ©

SERVICE BULLETIN

Classification:	Reference:	Date:
BT13-011	NTB13-049	May 1, 2013

2013 ALTIMA SEDAN; DOOR MIRROR CORNER FINISHER REMOVAL PROCEDURE

APPLIED VEHICLE: 2013 Altima Sedan (L33)

SERVICE INFORMATION

If the door mirror corner finisher of either front door has to be removed or replaced for any reason, make sure to remove it as noted below.

NOTE: The front door finisher must be removed prior to door mirror corner finisher removal. Refer to the **L DRIVER CONTROLS>MIR Mirrors** section of the Electronic Service Manual (ESM).



Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.