Service Information

Audi
Truth in Engineering

VAS Tester **Number: AVT-13-23**

Subject: VAS 5054A Transmitter Head – Warranty Replacement **Date: Dec. 18, 2013**

We are aware that many non-functioning VAS 5054A Transmitter Heads submitted for warranty replacement are genuine devices that exhibit physical damage, tampering, damaged OBDII /USB connections, or are non-genuine devices*.

ATTENTION!


VAS 5054A Transmitter Heads contain no user-serviceable parts!


Any non-functioning 5054A submitted for warranty replacements that are determined to have physical damage, tampering or are non-genuine devices*, are not eligible for replacement.

The cost to replace damaged or non-genuine devices submitted for warranty replacement must be assumed by the dealer.

Examples (not limited to):







* Genuine VAS 5054A Transmitter Heads are originally included with new VAS diagnostic laptop or tablet devices purchased from the **Audi Special Tools Program** administered by Snap-on – SBS, or purchased separately from SBS.

© 2013 Audi of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.