SERVICE BULLETIN

NUMBER: 08-080-13

GROUP: Electrical

DATE: October 11, 2013

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 13-077. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:
Radio Compass Function Inoperable

OVERVIEW:
This Bulletin involves replacing the Rear View Mirror.

MODELS:

2014	(WK)	Grand Cherokee (International Only)

NOTE: This bulletin applies to vehicles with Auto High Beam Headlamp Control (sales code LMS) built on or before June 03, 2013 (MDH 0603XX).

SYMPTOM/CONDITION:
If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68110891AD	Mirror, Rear View

REPAIR PROCEDURE:

1. Replace the rear view mirror by follow the detailed procedure in DealerCONNECT/TechCONNECT 23 - Body - Interior > MIRROR, Rearview > Removal/Installation.

NOTE: Perform the Smartbeam System Calibration Procedure, (Refer to 08 - Electrical/8L > Lamps and Lighting/Lamps/Lighting > Exterior/SMART BEAM > Standard Procedure) .

POLICY:
Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-12-10- 02	Mirror, Inside Rear View - Replace (1 - Semi- Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action