Special Bulletin SP14-335

Date	Expiration	Release	Page
12.2014	**12.2016**	**1**	**1(3)**

Release 1: Original release

HUBODOMETER SUPPORT ADDITION
Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, add a support on the curbside of the drive axle.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS
*Verify vehicle eligibility by checking warranty bulletin status with **SAP** or via **ONLINE WARRANTY SYSTEM** available on Service / Warranty tab of Prevost website.*

Model	VIN
X3-45 Commuter Model Year : 2014	Single vehicles 2PCG33495**E**C73**5590** 2PCG33498**E**C73**5602**

This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
651153	SUPPORT	1

Other parts that may be required if lost or damaged.

Part No.	Description	Qty
N8893293	SCREW CAP HEXS M18-1.5x50	2

NOTE
Material can be obtained through regular channels.

PROCEDURE

DANGER

Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

<QF7720961 rev3>



Figure 1

Install support on axle with removed bolts. If bolts are damaged or lost, order N8893293.

Figure 2

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately half an hour, (30min).

OTHER

VBC Bulletin	N/A
Fail Code	23.14
Defect Code	09
System Condition	B
Causal Part	651153

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.