Measure no.	Subject	
US 52892177-02	Trip distance recorder sets itself to zero	
Status date (mm/dd/yy)	**Status**	**Organization**
1/8/14	Accepted	US, MOT
Date created (mm/dd/yy)	**Created by**	**PQM Problem reference**
1/8/14	Martin Bumba	
Release date (mm/dd/yy)	**Approved by**	**Dealer release**
		Allow automatic release

Vehicles affected

E series	Engine	Body
K27/11		
Production period (from/to) (mm/dd/yy)	**Comment on production period**	**Feedback (all cases relating to measure up to) (mm/dd/yy)**
/		

Complaint

The trip distance recorder sets itself to "zero".

Cause

Software error in the instrument cluster.

Measure

Program the instrument cluster with the current ISTA/P version.

Complaint

Fault location	Fault type	Fault place
Display: Trip distance recorder	Failure	

Cause

#	Fault location	Fault type	Fault place
1	62/11 Trip distance recorder		
	Repair Task	**Special Clearance**	**Area**
		No	Electrics/Electronics

Fault code

© 2002-2014 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.