Service Bulletin

File in Section: -
Bulletin No.: PIT5321
Date: September, 2014

PRELIMINARY INFORMATION

Subject: **Normal Characteristic - Missing Underhood Trim At Front Left Fender Area**

Models: **2015 Chevrolet Colorado**
2015 GMC Canyon

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A dealer or customer may report that a trim piece is missing from the left front of the engine compartment where the fender and radiator support meet.

3979522



3979523

A dealer may call GM TAC or ParTech because they cannot find a replacement part for this item.

Recommendation/Instructions

The upper intake air baffle is present on the right side to protect the engine air filter inlet. Since no engine air inlet exists on left side, no baffle was used there.

Make no repair attempts or modifications to the vehicle, this is built to design intent.

Customer Information

Please communicate to the customer this condition is a normal build characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.