Tony Lawrence

From: Tony Lawrence
Sent: Wednesday, October 09, 2013 3:54 PM
To: All Dlrs All Rgns - PT; All Dlrs All Rgns - SR
Subject: MAZDA DEALER NOTICE - SERVICE BULLETIN RELEASE

SERVICE BULLETIN RELEASE - 10/09/2013

2013 INDEX: http://www.mstore2000.com/PDF_Files/index10-09-13.pdf

The following Service Bulletin has just been issued.

- For latest MS3 postings, click here: https://portal.mazdausa.com/m173/service/esi/MazdaServiceShop

- For printable PDF files from MStore, click on the link below each TSB title:

*** If the links do not automatically take you directly to the document, cut and paste the link into your internet browser address window and press enter.**

NEW BULLETINS

06-002/13 - 2013-2014 CX-5 - CLACKING NOISE WHEN STARTING TO MOVE VEHICLE WHILE STEERING WHEEL IS TURNED TO FULL LEFT POSITION

http://www.mstore2000.com/PDF_Files/06-002-13-2829.pdf

09-026/13 - 2013 CX-5 - NOISE COMING FROM UNDER THE DRIVER SEAT

http://www.mstore2000.com/PDF_Files/09-026-13-2833.pdf

UPDATED BULLETIN

01-005/13 – 2010-2013 MAZDA3 - ENGINE CRANKS BUT WILL NOT START IN COLD WEATHER (NO DTCs)

http://www.mstore2000.com/PDF_Files/01-005-13-2738a.pdf

- **Please distribute this information to all parts and service personnel.**
- **If you no longer wish to receive Mazda bulletins, please contact the IT Administrator at your dealership and ask them to remove your email address from under the EMDCS application.**