C117 with M270 Check Engine Light on with ME DTC P045109 "EVAP System Pressure Sensor/Switch Circuit Range/Performance Component Failures"

Topic number	LI07.70-P-059749
Version	1
Design group	07.70 Direct injection gasoline injection and ignition system
Date	09-02-2014
Validity	CLA (117)
Reason for change	
Reason for block	

Complaint:

Check Engine Light on

ME DTCs P045109 "EVAP System Pressure Sensor/Switch Circuit Range/Performance Component Failures" in the fault memory"

Cause:

This DTC is caused by an error in the ME software.

Remedy:

Perform ME control unit software update using the following XENTRY versions:

05/2014 with add-on 3755

07/2014

Symptoms
Power generation / Engine management / Engine management indicator lamp / Engine diagnosis / lit

Work units				
Op. no.	Operation text	Time	Damage code	Note
			54575 90	Software
54-0650	BATTERY CHARGER MAINTAIN VOLTAGE			
54-1011	SHORT TEST			
54-0991	SOFTWARE UPDATE			

© Copyright Daimler AG

Validity		
Vehicle	Engine	Transmission
CLA (117)	*	*

© Copyright Daimler AG