Service Bulletin

File in Section: -
Bulletin No.: PIC5934B
Date: March, 2014

PRELIMINARY INFORMATION

Subject: **Intermittently Radio Display Has Flickering or Rolling Image**

Models: **2014 Chevrolet Corvette Stingray**

This PI was superseded to update parts information. Please discard PIC5934A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

On rare occasions, a customer or dealer may comment that the radio display is blinking, flickering, rolling, or scrolling.

Typical comments are that it looks like an old TV with a rolling image and that raising or lowering the display may make the concern come and go.

Recommendation/Instructions

If this concern is encountered, replace the radio display to address this concern.

Parts Information

Part Number	Description	Qty
23476338	DISPLAY, DRVR INFO	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
3430990	Driver Information Display Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.