12/2/2015 MY14 & 15 MK

GPOP - Issue Review System

Part Number: 68232879A$

Part Description: TIPM [Totally integrated power module]

Issue Description: Before replacing a Totally Integrated Power Module (TIPM) for no start condition. Specifically when P0688 or P0685 fault code is active please call Don Shirey at cell (248) 797-2503 or Satnam Bansal at cell (248) 576-1528.
If no response within 15 minutes, proceed with repair.~

~_____~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.