Technical Bulletin

SERVICE BULLETIN

Classification:	Reference:	Date:
EL15-040a	NTB16-094a	November 3, 2016

2013-2015 PATHFINDER; DOOR MIRROR WILL NOT RETURN TO SET POSITION AFTER SHIFTING FROM REVERSE TO DRIVE

This bulletin has been amended. The Title has been modified, and references to Automatic Drive Positioner have been changed to Seat Control Unit. No other changes have been made. Please discard all previous versions.

APPLIED VEHICLES: 2013 – 2015 Pathfinder (R52) equipped with ADP
2014 Pathfinder Hybrid (R52) equipped with ADP

APPLIED VIN: 2013 – 2014 vehicles: All
2015 vehicles: Built before 5N1AR2M(**)FC 661844

APPLIED DATE: Built before April 7, 2015

IF YOU CONFIRM

The door mirror (LH and RH) automatic tilt down-up feature does not return to the original position after shifting from reverse to drive.

ACTION

Replace the Seat Control Unit.

- Use the <u>new</u> part listed in the Parts Information.

- For replacement information, refer to the appropriate Electronic Service Manual (ESM) Section J, Body Interior, ADP-Automatic Drive Positioner, DRIVER SEAT CONTROL UNIT, Removal and Installation.

Seat Control Unit

ALJIA0784ZZ

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
CONTROLLER ASSEMBLY-POWER SEAT	28565 – 3JA1A	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace Seat Control Unit	(1)	VH72AA	HD	32	(2)

(1) Refer to the electronic parts catalog (FAST) and use the Power Seat Controller (28565-*****) as the Primary Failed Part.

(2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.