Bulletin No.: PIP5538
Published date: 12/20/2017

Preliminary Information

PIP5538 Malfunction Indicator on - P0405 and/or P1426

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2018	All	All	1.5L L3A	All

Involved Region or Country	**North America**
Condition	**Malfunction Indication Lamp On - P1426 with or without P0405**
Cause	**GM is currently evaluating the concern.**

Correction:

If you encounter one of the vehicles listed above with a P1426 or P1426 and P0405 set in the ECM, follow the direction listed below.

If both P1426 and P0405 are set in the ECM, perform the SI diagnostic for the P0405 first.

Once the P0405 has been diagnosed and repaired, use GDS2 to clear the P1426.

If the P1426 resets, follow the SI diagnostic for the code.

If the P1426 does not reset, do not attempt repairs at this time.

Release the vehicle to the customer.

Please communicate to the customer that we apologize for this inconvenience and that General Motors is currently evaluating the P1426 concern.

This PI will be updated with additional details as they become available.

Version History

Version	**1**
Modified	**Created on 12/18/2017.**

© 2016 General Motors. All Rights Reserved.