Service Information

Offboard Diagnostic Information System Service (ODIS Service) **Number: VOS-17-29**

Subject: Software Version Update, Enhancements and Fixes **Date: Nov. 8, 2017**

Supersedes VOS-17-28 due to a new Diagnostic content version

The following ODIS Service software versions are available for download.

Current ODIS Service Software Versions	
Application: **V4.2.3**	Diagnostic Content: **V2.34.14**

Key Fixes/Enhancements for Diagnostic Content: 2.34.14

- General translation issues fixed.
- Test for DTC P20EE: SCR NOx Catalyst Efficiency Below Threshold Bank 1 SCR system test SYS26_7L_CATA_1_0309_11_SCR_Gesamttest_00011 completes and not in a loop – 7L Touareg 3.0L Engine CATA
- Adapt immobilizer test fails with error message: - Error ID: Infrastructure.Manufacturer.Backbone.ODS9218E – BW Tiguan
- 2018 CA Atlas Seat occupied recognition control module, no calibration, static test plan is canceled due to failed communication with the airbag control module - J234. 2018 Atlas
- 2018 BW Tiguan - ABS control module not available in Select Self-Test > Diagnosis capable systems and Guided Functions is greyed out and cannot be selected

To identify the versions currently installed on a diagnostic device, please refer to *ODIS Service – Service Information* document title: *Online Update Guide – Section 4.0*

© 2017 Volkswagen Group of America, Inc.
All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.