SSM 46388	Some 2017 MKZ and Fusion Energi vehicles may exhibit a rear brake moan noise during first application typically in the morning after the vehicle has sat overnight. Engineering is aware and is currently investigating. No repairs should be attempted at this time. Monitor OASIS for future updates.