Bulletin No.: PIT5587A
Published date: 02/12/2018

Preliminary Information

PIT5587A Terrain Diesel Driver Mode Control Knob will not Switch Drive Modes

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
GMC	Terrain	2018	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	LH7
Condition:	When attempting to change driver modes using the driver mode control knob the mode will not switch.
Cause:	Current Calibration.

Correction:

Turn the knob to the desired position and hold for 1 second and then release.

Service Procedure:

Please refer to field action recall 17337. The Engine control module reprogramming will also include a solution for the latent mode switch concern. Please refer to 17337 for labor code details.

Version History

Version	2.0

© 2016 General Motors. All Rights Reserved.