Reference	SSM72796
Models	Discovery Sport / L550
Title	L550 - Discovery Sport Tailgate Alignment Issues
Category	Body
Last modified	18-Apr-2018 00:00:00
Symptom	111000 Body Panel(s)/Unibody
Content	Issue: Retailers are reporting tailgate alignment and alignment related issues. Cause: Root cause requires further investigation. Action: Please raise an EPQR detailing where possible: • The original reason for the investigation (customer symptom). • Any functional issues affected. • Photographs of the issue(s) including the whole tailgate in the closed position. • Measurements of gap & flush data. TOPIx workshop manual WSM-19551 • 501-03: Body Closures. General Procedures. 76.28.31. • 501-26: Body Repairs. Vehicle Specific Information and Tolerance Checks. • Description and Operation. • Body and Frame. Gap and Profile Measurement. Technicians - Please rate this SSM and provide comments so that future communications can be improved. 1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern. 3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern. 5 = Excellent – All required information provided to resolve the customer concern.