BI INFORMATION BULLETIN

Modell:	Urus	Date:	14/12/2018
Group:	BI.29.18	Revision:	01
Model Year:	All	Errors front sensors driver assistance system	

ERRORS FRONT SENSOR DRIVER ASSISTANCE SYSTEM

Information to the field:

Automobili Lamborghini S.p.A. informs that some cars may present random errors on the 00A5 control unit.
Specifically, the following DTCs may occur on the control unit "00A5 - Front driver assistance systems sensors":

- *DTC 20500D, "B200FF9 Internal malfunction";*
- *DTC 205021, "B200FF9 Internal PCB Temperature Sensor not readable".*

These errors can occur in a "static" or "sporadic" manner.
Specifically, the cars on which the errors could occur are identified by the following characteristics:

ECU A5, zFAS	
SW version	0290
SW P/N	4KE 907 107. A/B/C/D
HW P/N	4N0 907 107. E/F/G/H

Field solution:

The aforementioned errors do not imply any restriction on the use of the vehicle and the functionality of the front sensors driver assistance system, the A5 control unit.
If therefore the above mentioned errors are found, it is possible to ignore them without having to perform any corrective action.

IMPORTANT:
The errors described will be correct in the next software updates that will involve the A5 control unit.

For any further information do not hesitate to contact your Area Manager or service.department@lamborghini.com.

Best regards,

Customer Service

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.