XENTRY TIPS

MBUX multimedia system: No vehicle image in menu settings

Topic number	LI82.85-P-069874
Version	1
Function group	82.85 Navigation and Communication system (CNS, ICS, COMAND, FleetBoard)
Date	05-30-2019
Validity	Model series 253 with MBUX, code 547/548/549+800
Reason for change	
Reason for block	

Complaint:

Intermittently, vehicle images may not be shown in the MBUX multimedia system (A26/17) menu settings or the energy flow display.

Cause:

Current software release (E419.6) of the MBUX multimedia system (A26/17)

Remedy:

Updated MBUX multimedia system (A26/17) software (E420.5) is currently being developed and is scheduled to be released with Regio-DVD 09/19.

Note: Please do not replace any parts.

Symptoms
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			8213F 50	