FT4640 Seats rail floor failure San Antonio Texas

Technical writer name
Devanand

Manual section **12**

First Level Parts		
Material	**Part Number**	**QTY**
-	-	-

Nb hours Level 1	20 min

MQR	7621-1275

Disposal of parts

Removed parts are:		When the retained check box is check, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed,
Discarded	Retained	
-	-	

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Config moteur	Model	NR	R1
San Antonio Texas	LA10	422	446	L82K9G9775628	L82K8G9775653	25	E	Us-Prv	US	PLB	TD	40	x	
San Antonio Texas	LA22	447	555	L82K8H9775654	L82K0H9775762	109	E	Us-Prv	US	PLB	TD	40	x	
San Antonio Texas	LA34	556	580	L82K0H9775857	L82K8H9775881	25	E	Us-Prv	US	PLB	TD	40	x	
San Antonio Texas	LA35	581	691	L82KXH9775882	L82K8H9775993	111	E	Us-Prv	US	PLB	TD	40	x	
San Antonio Texas	LB26	692	735	L82KXJ9776536	L82K6J9776579	44	E	Us-Prv	US	PLB	TD	40	x	

Daniel Theriault

Digitally signed by Daniel Theriault
DN: cn=Daniel Theriault, o=Nova Bus, ou, email=daniel.theriault@volvo.com, c=CA
Date: 2019.06.27 21:54:15 -04'00'