Latest Vehicle Concern Fixes

Outer Tail Lamp Water Ingress/ Lenses Cracking	New Range Rover Evoque 20MY
Customer Voice: • A customer may express a concern of moisture in the outer tail lamp or cracking of the outer tail lamp lenses and or a squeak type noise from the rear of the vehicle while driving. **Technical Description:** • This may be caused by an insufficient gap between the outer tail lamp and the rear quarter panel. **Status:** • TSB LTB01304NAS1 is being published to provide outer tail lamp to body clearance checks and adjustment procedures. • Should a customer express a concern, please refer to the TSB for repair guidance.	