Bulletin No.: PIP5575E
Published date: 08/20/2019

Preliminary Information

PIP5575E PQC 2019 Part Restriction T93 Transmission Control Module Has Ended

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	MQB, MQE
GMC	Sierra 1500 (New Model)	2019	All	All	All	MQB, MQE
Cadillac	CT6	2019	All	All	All	MHS, MHW

Involved Region or Country	North America
Condition	**T93 Transmission Control Module**
Cause	**Restriction**

General Motors Product Quality Center part restriction on the T93 transmission control module has ended.

We would like to thank all dealers who participated in this restriction for their cooperation.

These transmission control modules can now be ordered through the regular GM CCA parts process and utilizing repair procedures covered in Service Information.

Parts Information

Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the proper parts to repair as needed.

Version History

Version	6
Modified	08/06/2018 - Created on 03/13/2019 - Added TCM part number 24296206. 05/29/2019 - Removed TCM part number 24296206. 06/26/2019 – Updated to include Dealer Case Management process information. 08/06/2019 – Removed TCM part number 24289415 and added TCM part number 24296206. 08/20/2019 - Restriction ended.

GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.