Cummins PX9 Fuel Hose Leak – NTSTA ID: 21V601 / TC: 2021-480, Cummins Recall: C2465

Number

21PBG

Supplier

Cummins

Description

Safety Recall - Cummins PX9 Fuel Hose Leak – NTSTA ID: 21V601 / TC: 2021-480, Cummins Recall: C2465

Date

8/6/2021

What's New

Safety Recall - UPDATED - Parts and repair procedure are now available through Cummins. Model year 2021 Cummins PX9 fuel hose assemblies may leak from the hoses between the fuel pump and the remote filter head. A fuel leak in the presence of an ignition source may increase the risk of a fire. The hoses will be replaced with improved parts.

Introduction

Cummins Inc has decided that a defect which relates to motor vehicle safety exists in certain model 536, 537 and 548 vehicles.

The fuel hose assembly may leak from the hoses between the fuel pump and the remote filter head. A fuel leak in the presence of an ignition source may increase the risk of a fire.

Situation

19 chassis (17 U.S. and 2 Canada) model 536, 537 and 548 vehicles manufactured from July 15, 2020 through May 7, 2021 with Cummins PX9 Engines.

Resolution

Safety Recall

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. If you are not using Service Management to start repair orders, review SIR for "Complete" or "In Process" next to the "2465" Cummins campaign code prior to performing this repair.
3. Follow the procedures in Cummins C2465 Safety Recall to replace the two fuel hoses. Go to Cummins QuickServe and refer to the Cummins Recall – C2465.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

Go to Cummins QuickServe and refer to the Cummins Recall – C2465. File warranty claims through the Cummins warranty system.
SIR will indicate chassis involved in this recall with the designator of "2465" in the campaign field.

Links

Chassis List

Authored by: PR

Revision History

08/27/2021 - Bulletin updated. Parts and repair procedure are now available through Cummins.