US10 Emissions Engines Only-Fault Code SPN 3675 FMI 7-Engine Turbocharger Compressor Bypass Valve Position-Being Generated

Internal Content

(US10 Emission Only) - when Fault Code SPN 3675 FMI 7 Engine Turbocharger Bypass Valve Position is generated confirm that the Turbocharger Boost Pressure Sensor is not faulty by displaying a boost value (reading) while the engine is off. If so replace the Turbocharger Boost Pressure Sensor validating this resolved the issue. (The engine in this vehicle does not have a DRV Valve, please disregard diagnostic steps related to it's troubleshooting).

Tags

k08411230 spn 3675 fmi 7 mack volvo

Related links and attachments

No links or attachments available

Feedback

Give feedback

to help improve the content of this article

Live UI