Bendix AutoVue Lane Departure Warning System (LDWS) Generating Data Link Codes; J1939 Data Link Wires Switched (Will Not Record)

Internal Content

After diagnosing the Bendix AutoVue Lane Departure Warning System (LDWS) circuit the issue was found to be caused by the J1939 Data Link circuit wires being switched at the cab harness connector located near the Bendix module as shown below:





Review the applicable schematic to determine the correct pinning for the chassis, then confirm the harness connectors are pinned correctly.

Tags

k41346773 cu15 cu12 cng cu9 cng cu9 mack volvo

Live UI

Related links and attachments

No links or attachments available

Feedback

Give feedback

to help improve the content of this article

Live UI