SERVICE BULLETIN

M1545 2022-03-08

M1545 - 2022 FLHTK AND FLHTCUTG ALTERNATE AUXILIARY LAMPS

Purpose for Service Bulletin

This bulletin informs dealers that a certain number of 2022 FLHTK, FLHTK Shrine, and FLHTCUTG models built for Canada and DOM markets will be built with alternative auxiliary lamps.

Motorcycles Affected

2022 FLHTK, FLHTK Shrine and FLHTCUTG

Markets Affected

CAN and DOM.

Part Numbers

Refer to Table 1.

Table 1. Part Numbers

OE Part No.	Item Description	Temporary Replacement Part No.
68000020	AUXILIARY/FOG LAMP, LED (chrome)	68000203
68000174	AUXILIARY/FOG LAMP, LED (black)	68000239

Required Dealer Action

Table 2.

Action Required	Resolution
NO ☑ YES ☐	**Non-Actionable:** This is for informational purposes only or a technical tip.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									