# Technical Service Bulletin

| | |
|---|---|
| **Technical Service Bulletin**: TSB220021 | **Released Date**: 07-Feb-2022 |
| **Mislabeled Thermal Management System Harness** | |

# Mislabeled Thermal Management System Harness

## Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

## Contents

### Product Affected

- BES CM0904 EV104B

### Issue Summary

The existing thermal management system harness is labeled incorrectly. See Table 1 for correct labeling.

**Table 1, Correct Labeling for Thermal Management System Harness**

| | Mislabeled As | Correct Label |
|---|---|---|
| Power | x261 | x260 |
| | x263 | x262 |
| | x265 | x264 |
| Supply | x260 | x261 |
| | x262 | x263 |
| | x264 | x265 |





Figure 1, Thermal Management System Harness Schematic (Pump-side).




Figure 2, Example of Mislabeled Power Connector as x265 Which Should Be x264.

# Document History

| Date | Details |
| --- | --- |
| 2022-2-2 | Module Created |

**Last Modified: 07-Feb-2022**