VOLVO

Service and Parts Business

# Parts Bulletin

**TITLE:**

## Service Action S10148 Retaining Clip
## Model / Year: XC60 PHEV, XC90 PHEV 2022

| GROUP: | CAT/NO: | CAR MARKET: | |
|---|---|---|---|
| 26 | S10148 | United States | |
| REVISIONS: | | ISSUE DATE: 2022-02-14 | STATUS DATE: 2022-02-14 |
| | | Page 1 of 1 | |

**"Right first time in Time"**

**Reference Bulletins: QB S10148**

Volvo Car USA LLC on behalf of Volvo Car Corporation, has decided to launch Service Action S10148 on certain Model Year 2022, XC60 and XC90 PHEV vehicles.

Volvo has identified that over time, there is a risk that there will be wear on the cooling hose that potentially could lead to a refrigerant leak. In worst case scenario, this may lead to customer experiencing reduced charging efficiency and message in Driver Information Module (DIM).

The corrective action is to place a retaining clip on the cooling hose to prevent chafing.

S10148 affects 13 vehicles in the U.S.

| Part Number | Description | Qty |
|---|---|---|
| 30622624 | Retaining Clip | 1 |

Produced and printed in the USA and available as an electronic document.
© 2022 VOLVO CAR USA, LLC