2022 Ontour

CUSTOMER STATES SMELL OF PROPANE AND HISSING COMING FROM REMOTE BLEEDER VALVE-BLEEDER VALVE IS TURNED OFF//LEAK AT FITTING AT BLEEDER VALVE//HAD TO LOCATE, PULL FITTING OFF AND APPLY PIPE DOPE., THEN REATTACH. TESTED NO LEAK. 2.0

1.0 approved maximum