
# Volvo Chassis - DTC U012100 - Lost Communication With Anti-Lock Brake System (ABS) Control Module, No Additional Information

Fault Code U012100 may be caused by caused by poor ground connection.
If DTC is present do the following:

1. Disconnect the battery.
2. Remove all exterior Ground conections.
3. Thoroughly clean all surfaces.
4. Reassemble connections.
5. Apply protective coating.

The X03E ground junction is located on the left side of the dash under the cluster. See images below.

Live UI




LEFT SIDE OF DASH UNDER CLUSTER

Clear faults and verify the repair. If the fault returns continue with Guided Diagnostics.

Live UI

Tags

u012100 ground junction volvo x03e

spn639

## Related links and attachments

No links or attachments available

## Feedback

Give feedback

to help improve the content of this article

Live UI