Dealer Service Bulletin

NO.: 7SB005-23-01A
SECTION: Plumbing
DATE: September 19, 2022

MODELS AFFECTED: All Models

SUBJECT: Shower Surround Sealant

PLEASE FORWARD THIS INFORMATION TO YOUR RV SERVICE MANAGERS.

This bulletin is to advise you of a change to the shower surround sealant process. We have eliminated caulk-type sealant between the surround and the shower pan in favor of a closed-cell foam installed behind the shower surround. This will prevent moisture from getting behind the surround and eliminates the need for visible, caulk-type sealant.

Please be sure to pass this along to your staff so they are aware that the shower is not missing sealant. Reference photos below. Figures 1 and 2 indicate the new foam, Figure 3 shows the surround with no sealant.

Figure 1



Figure 2

Figure 3

If you have questions about this email, contact Winnebago Technical Assistance at 866-653-4329 or email techservice@wgo.net.

Thank you for your continued partnership!

Dean Casad
Director of Customer Support

IMPORTANT THAT ALL PARTS AND SERVICE PERSONNEL READ AND INITIAL

PARTS MANAGER	SERVICE MANAGER		SERVICE PERSONNEL					PARTS PERSONNEL				PAGE
												1 OF 1