Subject: **Engineering Information - Crankshaft Balancer Appears to be Wobbling and/or Vibrating, Mounting Bolt Does Not Appear to be Centered**

This PI has been revised to end the need for gathering information from the field. Please discard PIE0714.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2017	2022	—	—	Equipped with 3.6L Engine (RPO LGZ)	—
GMC	Canyon						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 15, 2022 Revised November 17, 2022 - Ended the need for gathering further information from the field.