2022 Tofino

Customer with a Tofino was having incorrect readings on the touch screen for fresh tank. I had him access the location and swap the leads with grey tank which was known to be showing levels. When swapped, the fresh tank showed levels and the grey tank did not. Customer will need a new fresh tank sensor for the Tofino.





