SERVICE BULLETIN

M1582 **2023-02-13**

M1582: 2023 PAN AMERICA WINDSHIELD IMPROVEMENTS

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Revision Description
2023-02-13	Initial release

Purpose for Service Bulletin

The purpose of this bulletin is to notify dealers about the revised components on the 2023 Pan Am windshield Stop Brackets. The old part number has been superseded to a new part number.

Vehicle Affected

2021-2023: Pan America (RA1250, RA1250S)

Markets Affected

All markets are affected.

Part Numbers

Refer to Table 2.

Table 2. Part Numbers

Old Part No.	Item Description	New Part No.
57300390	Stop Bracket	57300390A

Required Dealer Action

NOTE

Stop Bracket parts are not to be replaced or warrantied unless they are defective.

Table 3.

Action Required	Resolution
NO ☑ YES ☐	**Non-Actionable:** This is for informational purposes only or a technical tip.

When ordering (Part No. 573000390A) for 2021 and 2022 Pan America models, a quantity of **two** will be required to update both the left and right sides.



1. 57300390 **2. 57300390A**

Figure 1. Pan America Windshield Stop Bracket

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									